



Expertise

Protocol number: 46454398
Order No. / Reference: 26692429
Inspection date: 9 Jul 2026

Manufacturer: Mercedes-Benz

Model: Vito 119 CDI Extralang HA Aut. PRO

VIN: W1VVMCEZ5P4188481



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 119 CDI Extralang HA Aut. PRO	
Vehicle Identification number	W1VVMCEZ5P4188481
Mileage (Read)	102,426 km
First registration	12 Dec 2022
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Power / Engine displacement	140 kw / 1,950 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Selenitgrau metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	409 Tag(e)
Last service on / at	10/2025 at 83,183 km		
Key is / should be	4 / 4	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT579241
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBK 01854		
Emission standard	EURO6;WLTP;AR;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/55 R17 109T	Winter tyres on Steel	Goodyear	6mm / 6mm
2)	255/55 R17 109T	Winter tyres on Steel	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109H	Summer tyres on Light alloy	Dunlop	5mm / 5mm
2)	225/55 R17 109H	Summer tyres on Light alloy	Dunlop	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Screw-in towing eye front/rear
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- Brake lights, adaptive
- Front cupholder
- Diesel particulate filter
- Entry grab handle for the cargo area sliding door
- Electronic Stability Program (ADAPTIVE ESP) with integrated Anti-lock Braking System (ABS)
- HVO-capable vehicle
- Parking brake
- Generator management
- Transmission: 9G-TRONIC
- Seatbelt warning device for front passenger seat
- Lockable glove box
- Boot lid
- Tempmatic controlled air conditioning
- Communication module (LTE) for digital services
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Halogen fog lights
- Breakdown management
- Radio/Telematics, Audio 10
- Full wheel cover
- Tires: Tires without specified make
- Tires: Summer tires
- Headlights: halogen technology
- Key: 3-button remote control
- electromechanical power steering
- Seats: Adjustable passenger seat
- Seats: Comfort driver's seat
- 12V socket
- continuous partition wall
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Registration as a truck
- Passenger side airbag
- ATTENTION ASSIST
- Outdoor temperature display
- Battery: Backup battery for starting process
- Fixing points in the roof frame
- third brake light
- COC documents
- Comfort roof control unit
- Electronic tachometer
- Electrical components for trailer socket
- Driving light assistant
- Chassis: Standard chassis
- Electric windows, driver/passenger
- Generator 14 V / 250 A
- Speed limit 210 km/h
- Weight variant 2,800 kg
- Seatbelt warning device for driver's seat
- Main tank 57 liters
- Interior trim of cargo area, side
- Instrument cluster with pixel matrix display
- Headrests (2), front
- Headlight range control
- Multifunctional steering wheel
- Package: BlueEFFICIENCY
- Upholstery: Caluma fabric, black
- Radio: Digital Radio DAB
- Tires: 225/55R17
- Tires: Premium protection tires (3 years)
- Wheels: Steel rims 6.5 J x 17
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seat: Lumbar support driver's seat
- Seats: Driver's seat Plus with flat seat surface
- Start-stop function
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II



Extra equipment

- 2 additional keys FZ9
- Towing capacity 2500 kg
- Towbar (fixed ball head)
- Electrically folding exterior mirrors, left and right
- Intelligent tachograph
- Large fuel tank, approx. 70 liters
- LED Intelligent Light System (ILS) (incl. dynamic cornering lights, country road and motorway lights, turning lights, dynamic headlight range control, automatic high beam assist, LED taillights - incl. instrument cluster with pixel matrix display)
- Radio/Navigation: Multimedia radio and navigation system "Audio 40" (7-inch LCD touchscreen - DAB digital radio - Apple CarPlay and Android Auto - Bluetooth 3.0 - Hands-free system - Live Traffic Information - 2-way front speakers)
- Seat heating on passenger side
- Sun visor, driver/passenger side, illuminated mirror
- Distance Assist DISTRONIC active (automatic transmission) (including HOLD function)
- Upgrading/downgrading (upgrading to 3.05 t GVW)
- High Beam Assist Plus
- THERMOTRONIC automatic climate control
- Paint finish: Metallic
- leather steering wheel
- Center console with 1-DIN slot
- Package: Driver Assistance Package (Blind Spot Assist - Lane Keeping Assist - COLLISION PREVENTION ASSIST)
- Package: Parking (reversing camera - PARKTRONIC)
- Tires: M+S 225/55 R 17
- Rear door: Rear swing doors, opening to side wall
- Weld nuts side wall for extensions
- Seat: Lumbar support, passenger seat
- Seats: Comfort passenger seat
- Seat heating on driver's side
- Partition wall with 1 continuous window

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sill - right side	Sill - dent(s) - Smooth repair work
2	Door - front left side	Door - dent(s) - Smooth repair work
3	Trim / covers	Door trim - front right side - Scratch(es) - Smart repair
4	Interior	Interior - Odour - Ozone treatment
5	Body	Body - Glued / labelled - Remove
6	Sliding door, right	Door seal - Damaged - Replace
7	Seat - front	Seat cover - left side - Damaged - Replace
8	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
9	Front bumper	Front bumper (unpainted) - Scratched - Replace
10	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
11	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint



Wear and tear

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Scratch(es) - No deduction
2	Interior	Separation net - Scratch(es) - No deduction
3	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 5 Feb 2025	3.274,37 €
2	Side right, Provided by user / customer, from 7 Nov 2025	6.064,94 €

Repainting

No.	Repainting
1	Boot lid / rear door, Door - front right side

Paint coat thickness measurement

Boot lid / rear door	175 µm	Door - front right side	176 µm
----------------------	--------	-------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.





Figure 45: Misc.



Damage 1: Sill - right side: Sill - dent(s) - Smooth repair work




Damage 1: Sill - right side: Sill - dent(s) - Smooth repair work



Damage 2: Door - front left side: Door - dent(s) - Smooth repair work



Damage 2: Door - front left side: Door - dent(s) - Smooth repair work



Damage 3: Trim / covers: Door trim - front right side - Scratch(es) - Smart repair



Damage 3: Trim / covers: Door trim - front right side - Scratch(es) - Smart repair



Damage 3: Trim / covers: Door trim - front right side - Scratch(es) - Smart repair




Damage 5: Body: Body - Glued / labelled - Remove



Damage 5: Body: Body - Glued / labelled - Remove




Damage 5: Body: Body - Glued / labelled - Remove



Damage 6: Sliding door, right: Door seal - Damaged - Replace




Damage 6: Sliding door, right: Door seal - Damaged - Replace



Damage 7: Seat - front: Seat cover - left side - Damaged - Replace




Damage 7: Seat - front: Seat cover - left side - Damaged - Replace




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 8: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 9: Front bumper: Front bumper (unpainted) - Scratched - Replace




Damage 9: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 10: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Wing mirror - right side: Mirror housing - Scratch(es) - No deduction



Wear and tear 1: Wing mirror - right side: Mirror housing - Scratch(es) - No deduction



Wear and tear 2: Interior: Separation net - Scratch(es) - No deduction



Wear and tear 2: Interior: Separation net - Scratch(es) - No deduction



Wear and tear 2: Interior: Separation net - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Boot lid / rear door: 175 µm



Boot lid / rear door: 175 µm



Door - front right side: 176 µm



Door - front right side: 176 µm



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1VVMCEZ5P4188481

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 119 CDI Extralang HA
Aut. PRO

Datum	KM-Stand	Beschreibung
16.10.2025	83.183	Regelwartungsdienst
30.04.2024	34.431	Regelwartungsdienst