



IDENTIFICATION VEHICLE

Driver name:
Make: POLESTAR
Model / version: 2
Vin: LPSVSEGEKNL072913
Plate: 2BWF846
Mileage: 72820
SOH:
First registration: 15/04/2022
Color: Thunder (met)




ADDITIONAL INFORMATION







Category:
Transmission:
Interior color:
Metallic paint: ?
Type of lining:
Board computer reset: ?

DOCUMENTS

Certificate of conformity: ✓
Registration certificate: ✓
Registration certificate 2: ✓
Insurance certificate: ?
Maintenance book:
Number of keys: 1
Original key: ✓

PICTURES





VIN INFORMATION

depuis n°châssis -N-062 967
protection des piétons
ceintures de sécurité à enrouleur
siège passager réglable électrique
airbag passager désactivable
attache-remorque rabattable
PHARE LED PIXEL
support plaque immatriculation AV
hayon automatique
ASSIST PARK SEMIAUTO
plaque immat dans le pare-chocs av
système audio "High Performance"
moteur électrique av 172 kW
Pilot

Head Up Display
système d'alarme volumétrique
rallonge d'assise des sièges av
fixation siège enfant Isofix
verrouillage central
Keyless Entry
capteur de mouvement intérieur
connexion chargeur gauche
système de caméra périphérique
batterie HEV 78 kW/h
moteur électrique 170 KW
roues av motrices (traction)
airbag passager
8J X 19/9J X 19 ALU

grille de calandre active Shutter-System
Digital Key
siège avg électrique avec mémoire
avertisseur électronique
feux ar LED
phares antibrouillard
radio digitale (DAB)
sécurité enfants électrique
rétroviseur int jour/nuit automatique
Blind Spot Information System
ouverture du hayon à mains libres
1 vitesse
245/45 R 19 .. V
connexion chargeur Type 2

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	1	Fast charging cables:	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot cover	Grooved
2	Interior	Dirty
3	Contact key	Missing
5	Alloy rim FL polished	Grooved
6	Alloy rim RL polished	Grooved
7	Bumper R	Scratch(es)
8	Alloy rim RR polished	Grooved
9	Alloy rim FR polished	Grooved

Total: 8



ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Boot cover - Grooved



2 - Interior - Dirty





3 - Contact key - Missing



5 - Alloy rim FL polished - Grooved



6 - Alloy rim RL polished - Grooved



7 - Bumper R - Scratch(es)



8 - Alloy rim RR polished - Grooved



9 - Alloy rim FR polished - Grooved



4 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE