



Expertise

Protocol number: 46417624
Order No. / Reference: 26600880
Inspection date: 9 Jul 2026

Manufacturer: Kia	Model: Ceed SW 1.6 CRDi Eco-Dynamics+(48V Mild-Hyb.) DCT7 Spirit
VIN: U5YH5819GNL120798	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Kia Ceed SW 1.6 CRDi Eco-Dynamics+(48V Mild-Hyb.) DCT7 Spirit	
Vehicle Identification number	U5YH5819GNL120798
Mileage (Read)	94,011 km
First registration	3 Mar 2022
Number of holders	1
Next periodical technical inspection	02/2027
(Report not on hand)	
Power / Engine displacement	100 kw / 1,598 ccm
Fuel type / Cylinder	Hybrid Diesel / E / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Sparklingsilber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	
Last service on / at	05/2025 at 75,730 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN143784
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2234 / ABC 00004		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,960 kg	Empty weight	
Dimensions	4605 x 1800 x 1465		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91W	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/45 R17 91W	Summer tyres on Light alloy	Michelin	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 3.5-inch instrument display
- ABS (Anti-lock Braking System) with electronic brake force distribution
- Airbag: 2 curtain airbags
- Active brake light (Emergency Stop Signal, ESS)
- Alarm system
- Electrically folding exterior mirrors
- Exterior mirrors in car color
- Hill Start Assist Control (HAC)
- Brake Assist (BAS)
- Roof spoiler
- Overhead console with glasses compartment
- Roof rails
- Diesel particulate filter with SCR
- Third brake light (LED) in the rear spoiler
- twilight sensor
- Electronic Stability Control (ESC) with Traction Control System (TCS)
- High beam assist
- floor mat set
- Luggage net eyelets
- Luggage compartment lighting
- Adaptive cruise control including Stop&Go function
- Front cup holder
- rear window wiper
- ISOFIX mounts
- Headrests on all seats are height-adjustable.
- LED headlights (low and high beam) with automatic headlight range control
- LED daytime running lights at the front
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- Armrest - centre, rear
- Fatigue warning
- Electronic parking brake
- Upholstery: Cloth
- Radio: Kia radio with 8-inch touchscreen
- Radio accessory: roof antenna
- Radio accessories: 2 rear speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: USB interface
- Tire pressure monitoring system (TPMS)
- Wheels: 17-inch alloy wheels with 225/45 R17 tires
- Power steering
- Seats: Passenger seat height adjustable
- Seats: Lumbar support
- Seats: Heated front seats
- Smartphone interface Android Auto and Apple CarPlay with voice control
- 12V power outlet
- Phone: Front USB fast charging port
- static cornering light
- Airbag: 2 front airbags
- Airbag: 2 side airbags
- Active lane keeping assist with corrective steering intervention (Lane Keep Assist, LKA)
- Heated exterior mirrors
- Electrically adjustable exterior mirrors
- Exterior mirrors with integrated turn signals
- On-board computer
- Chrome trim around the side windows
- Headliner and pillar trim in grey
- Front overhead console with reading lights and central lighting
- Tachometer
- Drive Mode Select
- EcoDynamics (start-stop system ISG)
- Energy regeneration system
- Electric windows front and rear
- Front collision warning
- Compartments in the boot floor
- luggage compartment cover
- luggage compartment partition net
- Transmission: 7-speed direct-shift gearbox (DCT)
- Back window, heater
- Auto-dimming interior rearview mirror
- Automatic climate control, 2 zones, with anti-fog sensor
- Radiator grille in gloss black with chrome frame (glossy)
- LED taillights
- LED daytime running lights at the rear
- Leather gear knob
- Steering wheel: Leather steering wheel
- rear air vents
- Front center armrest, sliding
- Fog light
- Rear parking sensors (PDW-R)
- Cross-traffic alert system for detecting vehicles in the blind spot when reversing out of a parking space
- Radio accessories: 2 front speakers
- Radio accessories: 2 tweeters
- Radio accessories: DAB radio
- Rain sensor
- Tire repair kit
- Rear view camera
- Front seat belts are height-adjustable
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Pockets on the backs of the front seats
- Sun visors with illuminated makeup mirrors
- Lane change assist with blind spot warning
- Bumpers in body color
- Door handles in car color



- Interior door handle in chrome finish
- Heated windshield washer nozzles
- Central locking with remote control

- Immobiliser
- thermal insulation glazing

Extra equipment

- Paint finish: Metallic paint
- Package: P2 - Technology Package (for DCT transmission, Spirit) (4.2" Supervision instrument display - Intelligent Parking System (Parking Assist-Perpendicular Reverse, PA-PDR) with parking assistant for parallel and perpendicular parking as well as parallel exiting - Inductive charging station (for smartphones) in the center console with charging indicator - Smart Key and start button - Front parking sensors (PDW) - Tire pressure monitoring system with pressure display for each wheel in the on-board computer display - Lane Follow Assist (LFA) - Electric tailgate, sensor-controlled)
- Package: P10 - Navigation Package (Spirit, GT Line) (Kia map navigation with 26 cm (10.25 inch) screen diagonal incl. 7-year Kia navigation map update - Traffic sign recognition for speed limits (ISLW) - JBL premium sound system with subwoofer and center speaker in the dashboard - UVO Connect online services with Kia Live (real-time traffic information, weather forecast, local search, parking options) as well as the ability to access vehicle information and control vehicle functions via the UVO app)
- Separation net

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Documents	Service book (Werkstattstempel fehlt) - Incomplete - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Door - rear right side	Door - dent(s) - Smooth repair work
5	Wheel / tyres	Tyre - front right side - Porous / cracked - Replace
6	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
7	Wheel / tyres	Alloy rim - front right side - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Sill - right side	Sill - Dent / paintcoat damage - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Front bumper	Front bumper - Stone chips - No deduction
6	Interior	Interior - Soiled - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Missing parts

Description

Equipment - Tirefit complete

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der Winterradsatz ist kein Bestandteil der Ausstattungsliste.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Damage 1: Documents: Service book (Werkstattstempel fehlt) - Incomplete - No deduction




Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 4: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: U5YH5819GNL120798

Hersteller / Modell: HYUNDAI HYUNDAI Ceed SW 1.6 CRDi Eco-Dynamics+(48V
Mild-Hyb.) DCT7 Spirit

Datum	KM-Stand	Beschreibung
01.10.2025	76.491	Batterie ern
27.05.2025	75.730	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
21.02.2025	69.941	HU + AU
28.05.2024	54.518	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst
17.04.2023	28.760	Bremsflüssigkeit ern; Motoröl b. Wartung; Regelwartungsdienst