



Mercedes-Benz EQA: L434NG

| | | | |
|-------------------------|--------------------------|-------------------------|---|
| Vinnnummer: | W1N2437011J010161 | Versionname: | EQA 250 140kW / 67kWh Business Solution AMG automaat |
| First Registrationdate: | 29/06/2021 | Fiscalpower: | |
| Expertise Mileage: | 125217 | Power Kw: | 140 |
| Bodytype: | | Body colour: | Iridiumzilver metallic |
| Gearbox: | Automatic | Paint type: | Metallic |
| Transmission: | | Type of rims (mounted): | Aluminium |
| Fueltype: | Electric | Parking lot: | 489 |
| Number of seats: | 5 | | |
| Type of rims (mounted): | Aluminium | | |
| Maintenance needed: | No | | |

Options

| | | |
|-----------------------|----------|----------------------|
| Number of keys total | 2 | Lining semi-leather |
| GPS | | Lining Alcantara |
| Autom climate control | | Rear parking sensors |
| Radio multimedia | | Rear view camera |


Tyres

| Location | Position | Measures | Depth | Make | Type |
|----------|----------|-------------------------------------|--------|-------------|--------|
| Front | Left | 235 / 55 / 18 / 100 / V / Aluminium | 4,0 mm | Continental | Summer |
| | Right | 235 / 55 / 18 / 100 / V / Aluminium | 4,5 mm | Continental | Summer |
| Rear | Left | 235 / 55 / 18 / 100 / V / Aluminium | 5,0 mm | Continental | Summer |
| | Right | 235 / 55 / 18 / 100 / V / Aluminium | 5,0 mm | Continental | Summer |

Assistance equipment

| | |
|--|----------|
| Number of charging cables (rapid charge) | 1 |
|--|----------|

Door FL, Dent(s), Repair and paint (complete)



Roof pillar L, Dent(s), Repair and paint (complete)



Bumper F, Stone chip(s), Repair and paint (complete)





| | |
|-----------------------|---|
| Kenteken | L434NG |
| Merk Model | Mercedes-Benz EQA 250 140kW /67kWh Business Solution AMG automaat |
| Brandstofsoort | Elektrisch |
| Datum deel1 | 29-06-21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|-----------------|----------------|-----------------------------------|
| 20-02-26 | 116.444 | Reparatie band(en) |
| 02-02-26 | 114.827 | Onderhoudsbeurt |
| 02-02-26 | 114.827 | Ruitenwischerblad(en) voorzijde |
| 13-10-25 | 85.121 | Vervanging band |
| 12-05-25 | 94.593 | APK |
| 12-05-25 | 94.593 | Ruitenwischerblad(en) voorzijde |
| 07-03-25 | 89.861 | Onderhoudsbeurt |
| 28-03-24 | 68.247 | Onderhoudsbeurt |
| 28-03-24 | 68.247 | Remvloeistof |
| 04-05-23 | 41.572 | Onderhoudsbeurt |
| 04-05-23 | 41.572 | Ruitenwischerblad(en) achterzijde |
| 04-05-23 | 41.572 | Ruitenwischerblad(en) voorzijde |
| 09-05-22 | 22.571 | Onderhoudsbeurt |