

INSPECTION REPORT


End of contract

GENERAL INFO

File	315802
License plate	2DEH185
Vehicle identification number	ZCFC635C005505208
Dossier	2023040088
Make	Iveco Daily 40C18HA8Z H2 4100
Mileage	30543
First registration	21/02/2023
client availability date	18/06/2026
inspectionDate	01/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	Y
19	Bumper Front / Lower Cover Not Painted / Replace	Y
117	Wing Rear Left / Trim / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
214	Door Front Right // Repair & Painting	Y
237	Wing Front right / Trim / Replace	Y
329	Mud Guard Rear Left // Replace	N
562	Dashboard / Instruments Panel / Replace	N

Damage Pictures



Wing Front right / Trim / Replace-scratch




Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Door Front Right // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Mud Guard Rear Left // Replace-cracked



Dashboard / Instruments Panel / Replace-cracked