



Expertise

Protocol number: 46479783
Order No. / Reference: 26554824
Inspection date: 13 Jul 2026

Manufacturer: Opel

Model: Crossland 1.5 Diesel Elegance

VIN: W0V7H9EN9N4332637



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Crossland 1.5 Diesel Elegance	
Vehicle Identification number	W0V7H9EN9N4332637
Mileage (Read)	108,802 km
First registration	19 Sept 2022
Number of holders	1
Power / Engine displacement	81 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
readiness to drive	Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	
Last service on / at	03/2025 at 86,497 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN176413
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	With complaint
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	1844 / AMH 00117		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,835 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/65 R16 91T	Winter tyres on Steel	Pirelli	5mm / 5mm
2)	195/65 R16 91T	Winter tyres on Steel	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R17 95H	Summer tyres on Light alloy	Bridgestone	3mm / 3mm
2)	215/50 R17 95H	Summer tyres on Light alloy	Bridgestone	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS)
- Hill Start Assist
- On-board computer
- Roof design line, above, in chrome
- Diesel particulate filter (DPF) maintenance-free
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Electric front windows
- Transmission: 6-speed manual transmission
- rear window wiper
- Instrument inserts, black with chrome rings
- Automatic climate control, two zones
- Front headrests
- LED ambient lighting
- LED daytime running lights
- Headlight range adjustment, manual
- Makeup mirror
- Proactive driver assistance system
- Radio: Multimedia radio with 7" color touchscreen display, 6 speakers
- Wheels: Alloy wheels 6.5 J x 16 with tires 195/60 R16, in BiColor/Black (10 spokes)
- Visibility equipment
- Seats: Seat backrest split 60:40, foldable
- Lane Assist
- 12V power outlet in the center console, front
- Underride protection look, front and rear, in silver
- Pre-installation for child seat mounting system "ISOFIX"
- Central locking with remote control

Extra equipment

- Paint finish: Solid special color Jade White
- Steering wheel: Heated leather steering wheel and seat heating, multi-stage, driver and passenger
- Fog light
- Parkpilot ALG - Retrofit
- Quickheat rapid heating system
- Wheels: Alloy wheels 6.5 J x 17 with tires 215/50 R17, in black (5 double spokes)
- Seats: Ergonomic active seat (AGR) driver (length, height and backrest angle manually adjustable - seat tilt electrically adjustable - lumbar support electropneumatically adjustable in height and length - extendable thigh support, manually adjustable)
- Heated windscreen, ThermoTec

- Airbag for driver and passenger side
- Airbag: Side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Roof spoiler
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric rear windows
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear, including reading lights, front
- Rear headrests (3)
- Paintwork: Roof in car color
- LED headlights
- Steering wheel: Leather steering wheel with chrome elements and steering wheel remote control
- Center armrest, front
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Tire pressure warning
- Power steering
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort seats
- Solar Protect thermal insulation glazing
- Start/Stop System
- Traction control (TC Plus)
- Traffic sign assistant
- Immobiliser

- LED headlights (cornering lights - automatic headlight range control - LED taillights)
- Navigation system: 180-degree panoramic reversing camera and Multimedia Navi Pro (Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, FM/AM radio, Autostore, RDS-EON, automatic music recognition, image display via USB port, Apple CarPlay, Android Auto, text message reading and dictation, up to 10 mobile phones can be paired, navigation with integrated memory, European road map (including Russia and Turkey), 3D map display, dynamic route guidance, 2 USB ports, 3.5" color driver information display)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed, problem has been detected This is due to the following reason.: Motorkontrolle Leuchtet
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Bonnet	Bonnet - dent(s) - Smooth repair work
3	Roof	Roof rail - left side - dent(s) - Smooth repair work
4	Electrical system	Lighting system - Functional / admissibility - Perform diagnosis
5	Door - front left side	Door - dent(s) - Smooth repair work
6	2nd wheel set	1 tyre (Flanke) - Damaged - Replace
7	Engine	Engine (Kontrollleuchte an) - Functional / admissibility - Perform diagnosis

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Misc.	Inspection / maintenance (Nicht zurückgesetzt, Heft gestempelt) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Roof - Stub aerial

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

-Der montierte Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 2: Bonnet: Bonnet - dent(s) - Smooth repair work




Damage 3: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 3: Roof: Roof rail - left side - dent(s) - Smooth repair work



Damage 4: Electrical system: Lighting system - Functional / admissibility
- Perform diagnosis




Damage 5: Door - front left side: Door - dent(s) - Smooth repair work



Damage 5: Door - front left side: Door - dent(s) - Smooth repair work



Damage 5: Door - front left side: Door - dent(s) - Smooth repair work




Damage 5: Door - front left side: Door - dent(s) - Smooth repair work



Damage 6: 2nd wheel set: 1 tyre (Flanke) - Damaged - Replace




Damage 6: 2nd wheel set: 1 tyre (Flanke) - Damaged - Replace




Damage 7: Engine: Engine (Kontrollleuchte an) - Functional / admissibility - Perform diagnosis



Wear and tear 2: Misc.: Inspection / maintenance (Nicht zurückgesetzt, Heft gestempelt) - No deduction



Wear and tear 2: Misc.: Inspection / maintenance (Nicht zurückgesetzt, Heft gestempelt) - No deduction



Wear and tear 2: Misc.: Inspection / maintenance (Nicht zurückgesetzt, Heft gestempelt) - No deduction



Missing part 1: Roof: Stub aerial - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0V7H9EN9N4332637
Hersteller / Modell: OPEL OPEL Crossland 1.5 Diesel Elegance

Datum	KM-Stand	Beschreibung
17.04.2026	108.538	Kupplung ern
18.09.2025	96.553	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten
10.09.2025	95.893	AU
24.03.2025	86.497	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze vorne; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
20.06.2024	59.300	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
20.02.2023	32.791	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges