

Historial del Vehiculo -6729-MFM

MATRICULA	FECHA_COMUNICACIÓN	KM	TIPO_DANO	CONCEPTO
6729-MFM	09/04/2024	23891	ANUAL 1	Filtro aceite - Nueva
6729-MFM	09/04/2024	23891	ANUAL 1	Rellenar niveles
6729-MFM	09/04/2024	23891	ANUAL 1	Filtro actuador caudal gas
6729-MFM	09/04/2024	23891	ANUAL 1	MANO DE OBRA
6729-MFM	09/04/2024	23891	ANUAL 1	Serv inspección 30000 KM
6729-MFM	09/04/2024	23891	ANUAL 1	Aceite motor - 05W30 OEM
6729-MFM	09/04/2024	23891	ANUAL 1	Tasas reciclado residuos
6729-MFM	09/04/2024	23891	ANUAL 1	Arandela / tapón cárter - COBRE - Nueva
6729-MFM	09/04/2024	23891	ANUAL 1	Filtro antipolen - Nueva
6729-MFM	26/07/2024	31509	LUNAS	727124113R - PARABRISAS
6729-MFM	27/11/2024	44501	GARANTIA	bomba de agua en garantía de fabricante
6729-MFM	11/04/2025	45839	ANUAL 2	Pastillas delanteras
6729-MFM	11/04/2025	45839	ANUAL 2	Filtro antipolen - Bosch - Rec.Plat. AZELER - ANTIALERGICO - Nueva
6729-MFM	11/04/2025	45839	ANUAL 2	Filtro caudal gas
6729-MFM	11/04/2025	45839	ANUAL 2	MANO DE OBRA
6729-MFM	11/04/2025	45839	ANUAL 2	Arandela / tapón cárter - ACERO - Nueva
6729-MFM	11/04/2025	45839	ANUAL 2	Aceite motor - 05W30 OEM
6729-MFM	11/04/2025	45839	ANUAL 2	Tasas reciclado residuos
6729-MFM	11/04/2025	45839	ANUAL 2	Serv inspección 2º año
6729-MFM	11/04/2025	45839	ANUAL 2	Filtro aceite - Nueva
6729-MFM	11/04/2025	45839	ANUAL 2	Filtro de glp
6729-MFM	11/04/2025	45839	ANUAL 2	Líquido lavaparabrisas
6729-MFM	09/04/2025	48526	COLISIÓN SIN CONTRARIO	
6729-MFM	09/04/2025	48526	COLISIÓN SIN CONTRARIO	Mano de Obra Chapa: MANO OBRA CARROCERO
6729-MFM	09/04/2025	48526	COLISIÓN SIN CONTRARIO	rh - *MOLDURA PASE ALETA D.I.
6729-MFM	01/12/2025	70256	REV 090.000	Filtro antipolen - Bosch - Rec.Plat. AZELER - ANTIALERGICO - Nueva
6729-MFM	01/12/2025	70256	REV 090.000	Tasas reciclado residuos
6729-MFM	01/12/2025	70256	REV 090.000	Batería - Nueva
6729-MFM	01/12/2025	70256	REV 090.000	Filtro aceite - Nueva
6729-MFM	01/12/2025	70256	REV 090.000	Serv inspección 90000 KM

6729-MFM	01/12/2025	70256 REV 090.000	Aceite motor - 05W30 OEM
6729-MFM	01/12/2025	70256 REV 090.000	Arandela / tapón cárter - ACERO - Nueva
6729-MFM	01/12/2025	70256 REV 090.000	Líquido lavaparabrisas
6729-MFM	01/12/2025	70256 REV 090.000	MANO DE OBRA
6729-MFM	20/01/2026	75757 SISTEMA DE FRENADO	Jgo discos freno dl
6729-MFM	20/01/2026	75757 SISTEMA DE FRENADO	MANO DE OBRA
6729-MFM	20/01/2026	75757 SISTEMA DE FRENADO	Pastillas freno dl - Hella - Rec.Plat. AZELER
6729-MFM	28/01/2026	76451 SERV. NEUMATICOS	DD / PIRELLI / 215 60 HR17 96 H / Turismo INVIERNO
6729-MFM	28/01/2026	76451 SERV. NEUMATICOS	ALINEACION VEHICULOS
6729-MFM	28/01/2026	76451 SERV. NEUMATICOS	DI / PIRELLI / 215 60 HR17 96 H / Turismo INVIERNO
6729-MFM	12/05/2026	87608 SUPL. NEUMATICOS	Pinchazo+equilibrado



RENAULT CAPTUR

INTENS TCE 74KW (100CV) GLP

VIN	VF1RJB00770446445
Primera matriculación	16/3/2023
Kilometraje del vehículo	90.151 km

DETALLES DE LA INSPECCIÓN

Fecha de la inspección	6/8/2026 9:41:51	Descripción de la dirección de inspección	Hartmann MADRID-2
------------------------	------------------	---	-------------------

INFORMACIÓN DEL VEHÍCULO

Marca	RENAULT	Primera matriculación	16/3/2023
Modelo	CAPTUR	Tipo de carrocería	Berlina
VIN	VF1RJB00770446445	Tipo de combustible	Híbrido

DOCUMENTOS Y MANTENIMIENTO

Núm llaves	1	Documento de matriculación	No
Ficha Técnica	No	Tipo de libro de mantenimiento	Libro de mantenimiento presente
Manual de instrucciones	Sí		

NEUMÁTICOS

Neumáticos montados

Ubicación	Posición	Banda de rodadura	Fabricante	Dimensiones	Temporada de neumáticos	Tipo de llantas	Neumáticos Runflat
Delantera	Izquierda	4,0 mm	Pirelli	215/60 R 17 100 V	Verano	Acero	No aplica
Delantera	Derecha	4,0 mm	Pirelli	215/60 R 17 100 V	Verano	Acero	No aplica
Trasera	Izquierda	3,0 mm	Pirelli	215/60 R 17 100 V	Verano	Acero	No aplica
Trasera	Derecha	3,0 mm	Pirelli	215/60 R 17 100 V	Verano	Acero	No aplica

DAMAGES

Interior



1 Ignition key	
Damage type	Missing
Repair mode	Replace



2 Roof liner	
Damage type	Burned
Repair mode	Smart repair



12 Tyre repair kit	
Damage type	Missing
Repair mode	Replace




15 Boot lid covering R	
Damage type	Scratch(es)
Repair mode	Repair/replace (lump sum)

Exterior




3 Bumper F	
Damage type	Scratch(es)
Repair mode	Repair and paint (complete)




4 | Headlight L

Damage type	Broken
Repair mode	Replace



5 | Wing trim FL

Damage type	Missing
Repair mode	Replace



6 | Outside rear-view mirror housing L

Damage type	Scratch(es)
Repair mode	Paint




7 | Wing FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



8 | Door FL

Damage type	Dent(s)
Repair mode	Repair and paint (complete)





9 | Door RL

Damage type	Scratch(es)
Repair mode	Paint




10 | Wing RL

Damage type	Scratch(es)
Repair mode	Paint



11 | Wing trim RL

Damage type	Scratch(es)
Repair mode	Paint



13 | Bumper corner RL

Damage type	Scratch(es)
Repair mode	Polish



14 | Bumper corner RR

Damage type	Scratch(es)
Repair mode	Paint



16 | Bumper R

Damage type	Scratch(es)
Repair mode	Paint



17 | Bumper moulding R

Damage type	Scratch(es)
Repair mode	Paint



18 | Wing RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



19 | Door RR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



20 | Door FR

Damage type	Dent(s)
Repair mode	Repair and paint (complete)



21 | Outside rear-view mirror housing R

Damage type	Scratch(es)
Repair mode	Paint



22 | Wing trim FR

Damage type	Scratch(es)
Repair mode	Paint



23 | Wing trim RR

Damage type	Scratch(es)
Repair mode	Paint



24 | Wheel cover FR

Damage type	Scratch(es)
Repair mode	Replace



25 | Wheel cover RR

Damage type	Residue
Repair mode	Replace



26 | Wheel cover RL

Damage type	Scratch(es)
Repair mode	Replace



27 | Wheel cover FL

Damage type	Scratch(es)
Repair mode	Replace

Commercial photos

