



Expertise

Protocol number: 46381418
Order No. / Reference: 26544027
Inspection date: 7 Jul 2026

Manufacturer: Porsche
VIN: WP1ZZZ95ZMLB03006

Model: Macan PDK



Vehicle details	
Manufacturer / Type / Model / Equipment	
Porsche Macan PDK	
Vehicle Identification number	WP1ZZZ95ZMLB03006
Mileage (Read)	86,618 km
First registration	10 Nov 2020
Number of holders	1
Next periodical technical inspection	11/2026
(Report on hand)	
Power / Engine displacement	180 kw / 1,984 ccm
Fuel type / Cylinder	Petrol / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Vulkangrau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	14,900 km
Last service on / at	03/2025 at 77,162 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FW626434
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0583 / AKW 00019		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,510 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	265/45 R20 104Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	295/40 R20 106Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	265/45 R20 104V	Winter tyres (Without wheel rim)	Pirelli	6mm / 6mm
2)	295/40 R20 106V	Winter tyres (Without wheel rim)	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Facelift, Interior package: black, Sound package Plus, Non-smoking package, Loading sill protection (aluminum), Trailer stabilization program, Electrically folding exterior mirrors, Electrically adjustable exterior mirrors Adjustable and heated exterior mirrors, aspherical left-hand side mirror, automatic headlight activation, LED taillights, third brake light, LED daytime running lights, LED turn signals, windshield wipers with rain sensor, black window trim, black sideblade air deflectors, painted rear diffuser, high-gloss black roof spoiler, windshield with top tint, heated rear window, digital radio reception (DAB+), Porsche CDR Plus audio system with touchscreen color display (radio/CD player), mobile phone/cell phone preparation with Bluetooth interface, AUX-IN and USB multimedia sockets, Porsche Communication Management (PCM) including online navigation module, universal audio interface, multimedia smartphone applications (online services/apps), Connect Plus (Bluetooth, Apple CarPlay, WLAN, vehicle tracking system), rear USB ports (charging function only), on-board computer, tire pressure monitoring system, driver/passenger airbags, head airbag system (curtain airbags), side airbags Front airbag, passenger side deactivatable, 3-zone automatic climate control, cabin air filter: activated carbon filter (odor filter), seat upholstery: Alcantara/synthetic leather, interior: standard equipment synthetic leather/Alcantara, comfort seats in front, split-folding rear seat backrest, comfort headrests, electric windows, electric windows front and rear, central locking with remote control, tailgate with automatic opening and closing system, black seat belts, anti-theft alarm system with interior monitoring, immobilizer, cup holders, Isofix child seat anchors in the rear, anti-lock braking system (ABS), electric parking brake, driver assistance system: multi-collision brake, tire repair kit, steering wheel (sport/leather, 3-spoke) with multifunction and shift paddles, automatic brake differential (ABD), Porsche Traction Management (PTM), traction control (ASR), Porsche Stability Management (PSM) Low emissions according to Euro 6d-TEMP emissions standard, start/stop system, gasoline particulate filter (GPF), engine drag torque control (MSR), body: 4-door, drive type: all-wheel drive, wheelbase 2807 mm, transmission 7-speed dual-clutch transmission (PDK), engine 2.0 Ltr. - 180 kW 16V TFSI KAT



Extra equipment

- Roof rails with roof moldings, Lane Change Assist, Heated leather steering wheel with multifunction controls, Light Comfort Package, Driver Memory Package, Power Steering Plus (speed-sensitive), Comfort Access (keyless door unlocking), Auto-dimming exterior/interior mirrors, Darkened rear windows (privacy glass), Heated front seats, Two-piece electric panoramic sunroof, Alloy wheels front/rear: 9x20 / 10x20 (Turbo wheel, Platinum, satin finish), Cruise control with distance control, Fuel tank: 75 liters, LED headlights including Porsche Dynamic Light System Plus (PDLS+), Smartphone storage compartment, Speed Limit Display, Floor mats, Metallic paint, Electrically folding trailer hitch, Parking Assist with reversing camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Digitaler Nachweis, nur 1. Inspektion nachgewiesen) - No evidence - No deduction
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Front bumper	Front bumper - Scratch(es) - Paint
4	Roof	Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit complete



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterreifensatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres




Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 3: Front bumper: Front bumper - Scratch(es) - Paint



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work




Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work




Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work




Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work



Damage 4: Roof: Roof (inkl. Holm links & rechts) - dent(s) - Smooth repair work




Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WP1ZZZ95ZMLB03006

Hersteller / Modell: PORSCHE PORSCHE Macan PDK

Datum	KM-Stand	Beschreibung
02.11.2022	29.981	Bremsflüssigkeit ern; Regelwartungsdienst