



Expertise

Protocol number: 46413293  
Order No. / Reference: 26609179  
Inspection date: 9 Jul 2026

Manufacturer: Ford

Model: Focus Turnier 1.5 EcoBlue Start-Stopp-System  
COOL&CONNECT

VIN: WF0PXXGCHPMM32883



| Vehicle details                                                   |                   |
|-------------------------------------------------------------------|-------------------|
| <b>Manufacturer / Type / Model / Equipment</b>                    |                   |
| Ford Focus Turnier 1.5 EcoBlue Start-Stopp-System<br>COOL&CONNECT |                   |
| <b>Vehicle Identification number</b>                              | WF0PXXGCHPMM32883 |
| <b>Mileage (Read)</b>                                             | 115,180 km        |
| <b>First registration</b>                                         | 15 Apr 2021       |
| <b>Number of holders</b>                                          | 1                 |
| <b>Next periodical technical inspection</b><br>(Report on hand)   | 01/2028           |
| <b>Power / Engine displacement</b>                                | 88 kw / 1,499 ccm |
| <b>Fuel type / Cylinder</b>                                       | Diesel / 4        |
| <b>Gearbox / Number of gears</b>                                  | Manual / 6        |
| <b>Type of drive</b>                                              | Front drive       |
| <b>Type of vehicle</b>                                            | Station wagon     |
| <b>Colour / colour code</b>                                       | Frost-Weiß        |
| <b>Doors / Seats</b>                                              | 5 / 5             |
| <b>Upholstery type</b>                                            | Cloth             |
| <b>Colour of upholstery</b>                                       | Anthracite-Black  |



## Vehicle details

|                                                  |                              |                                |                                                            |
|--------------------------------------------------|------------------------------|--------------------------------|------------------------------------------------------------|
| <b>Maintenance booklet / proof</b>               | Available / complete         | <b>Next maintenance in</b>     | 54 %                                                       |
| <b>Last service on / at</b>                      | 02/2026 at 110,385 km        |                                |                                                            |
| <b>Key is / should be</b>                        | 2 / 2                        | <b>FZG documents</b>           | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
|                                                  |                              | <b>Letter No.</b>              | FZ482561                                                   |
| <b>Previous damage / Accident</b>                | Detectable                   | <b>Repainting</b>              | Detectable                                                 |
| <b>Inspection conditions</b>                     | sufficient                   | <b>Lifting equipment / pit</b> | yes                                                        |
| <b>Test drive</b>                                | Not performed                | <b>Engine function test</b>    | Performed                                                  |
| <b>Manufacturer key number/ type code number</b> | 8566 / BPV 00453             |                                |                                                            |
| <b>Emission standard</b>                         | EURO6;WLTP;AP;PI/CI; M, N1 I | <b>fine dust sticker</b>       |                                                            |
| <b>Permitted total weight</b>                    | 1,955 kg                     | <b>Empty weight</b>            |                                                            |

## Tyres

### Mounted tyres

| #  | Tyre size      | Type of tyre                | Manufacturer | Tread depth |
|----|----------------|-----------------------------|--------------|-------------|
| 1) | 205/60 R16 92V | Summer tyres on Light alloy | Goodyear     | 3mm / 3mm   |
| 2) | 205/60 R16 92V | Summer tyres on Light alloy | Goodyear     | 3mm / 3mm   |

### Replacement

| Typ | Tyre size      | Type of tyre          | Manufacturer | Tread depth |
|-----|----------------|-----------------------|--------------|-------------|
| N   | 125/70 R16 96M | Summer tyres on Steel | Hankook      | 2 mm        |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Airbag: Passenger airbag deactivation
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R 16 tires
- Fabric headliner
- Roof spoiler painted in car color
- Tachometer
- Driver information system
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto-hold function
- Ford ECO-Coach
- Luggage compartment lighting
- Luggage compartment floor, adjustable in two ways
- Cruise control
- Illuminated glove compartment
- rear window wiper
- Instrument lighting, adjustable
- Isofix bracket
- LED daytime running lights
- Steering wheel: 3-spoke design
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light
- Pollen filter and dust filter
- Post-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 2-way adjustable
- Seats: Map grid on the driver's and front passenger's seat backrests
- Start-stop system
- Carpet floor mats in the front
- Black trim around the side windows
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Central/Double Locking
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Mounting points behind the second row of seats
- Chrome decor
- Roof rails, aluminum
- Diesel particulate filter (DPF)
- Electronic Safety and Stability Program (ESP)
- Driving mode switch, selective
- Electric windows front and rear
- Ford Easy Fuel
- FordPass Connect including eCall, live traffic information (only with navigation) and Wi-Fi hotspot
- Speed limiter
- Transmission: 6-speed manual transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Headrests: 2 front and 3 rear, height adjustable
- Leather gear knob
- Adjustable steering column
- Center console "Premium" front
- Navigation: Ford Navigation, Ford SYNC 3 with AppLink, 8" touchscreen (20.3 cm) with DAB/DAB+
- Front and rear parking pilot system
- Upholstery: Cloth
- Pre-Collision Assist
- Rear view camera
- Electromechanical power steering
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest
- Seats: Front sports seats with enhanced lateral support
- 12-volt power outlet in the luggage compartment
- Child safety lock on the rear doors, manual
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Heat-insulating glazing, tinted
- Additional heating



## Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Package: Comfort (2-zone automatic climate control for driver and front passenger side, separately adjustable - Ford Key Free system (keyless locking/unlocking) including Ford Power Start function (keyless starting) - Windscreen wipers with rain sensor, variable sensitivity adjustment - Interior mirror, automatically dimming - Headlights with delayed shut-off)
- Cigarette lighter and ashtray in the center console
- Paint finish: Frost White
- Spare wheel: Emergency wheel (when in use, a maximum speed of 80 km/h is permitted.)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Safety partition net for luggage compartment
- Seats: Ford ergonomic seat (front seats adjustable in 18 ways: - length, height and tilt of the seat; extendable thigh support; adjustable backrest; lumbar support electrically adjustable in 4 ways; headrest adjustable in 4 ways)

## Brief expert findings

|                      |                                                                                                                                                                              |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Documents submitted  | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison       | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.    |
| Inspection           | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle.                     |
| Test drive           | No test drive/shunting maneuver was carried out during the inspection of the vehicle.                                                                                        |
| Engine function test | An engine test run was performed.                                                                                                                                            |

## Value reducing factors

| No. | Component group | Description                              |
|-----|-----------------|------------------------------------------|
| 1   | Rear bumper     | Rear bumper - Scratch(es) - Smart repair |
| 2   | Engine          | Engine - Leaking - Perform diagnosis     |

## Wear and tear

| No. | Component group | Description                               |
|-----|-----------------|-------------------------------------------|
| 1   | Vehicle glazing | Windscreen - Stone chips - No deduction   |
| 2   | Front bumper    | Front bumper - Stone chips - No deduction |
| 3   | Bonnet          | Bonnet - Stone chips - No deduction       |
| 4   | Interior        | Interior - Scratch(es) - No deduction     |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Missing parts

### Description

Interior - Separation net

## Previous damages

| No. | Previous damage                                                          | Extent of damage (Net) |
|-----|--------------------------------------------------------------------------|------------------------|
| 1   | Front, Side - left, Provided by user / customer, from 29 Jul 2025        | 3.908,31 €             |
| 2   | Side right, Professionally repaired, Invoice of repair done Non-existent |                        |



## Repainting

### No. Repainting

1 Mudguard - left side, Side panel - rear right side, Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

Professionally repaired previous damages were found at the vehicle.



**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)



**Figure 3:** Diagonal rear (left)



**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.




**Damage 1:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 1:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 2:** Engine: Engine - Leaking - Perform diagnosis



**Damage 2:** Engine: Engine - Leaking - Perform diagnosis



**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side



**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side




**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side



**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side



**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side



**Repainting 1:** Mudguard - left side, Side panel - rear right side, Door - rear right side