



Expertise

Protocol number: 46661667
Order No. / Reference: 26644465
Inspection date: 22 Jul 2026

Manufacturer: Skoda
VIN: TMBJH9NP2M7075108

Model: Superb Combi 2.0 TDI Ambition



Vehicle details	
Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 2.0 TDI Ambition	
Vehicle Identification number	TMBJH9NP2M7075108
Mileage (Read)	108,830 km
First registration	14 Jun 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Black-Magic Perleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	1,100 km
Last service on / at	07/2025 at 89,698 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD050971
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8004 / APL 01101		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,213 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99V	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/60 R16 99V	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/60 R16 99H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Closed storage compartments behind the wheel arches in the trunk, including cargo elements
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Traction control (ASR)
- Exterior mirrors and door handles in body color
- Illuminated glove compartment
- Hydraulic brake assist (HBA)
- Roof rails, black
- Diesel particulate filter and SCR catalyst
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- ISOFIX preparation on the outer rear seats, including top tether
- LED low beam
- Steering wheel: height and reach adjustable
- Rear center armrest with cup holders and pass-through option
- Multifunction display in the instrument cluster
- LED fog lights with integrated cornering lights
- Radio: Bolero infotainment system
- Radio accessories: Digital radio reception DAB+
- Radio accessories: SmartLink+
- Tire pressure monitoring
- Wheels: 16" Orion alloy wheels
- Electromechanical power steering
- Seats: Adjustable lumbar support in the front seats
- Seats: Rear seat backrest split 60:40, foldable
- Sun visor on driver and passenger side with illuminated make-up mirror
- 12V socket in the center console, front and rear
- Chrome-plated elements
- Lashing eyes in the trunk
- Central locking with remote control
- Storage compartments
- Airbag, driver and switchable passenger airbag
- Airbag, head airbags
- Anti-lock braking system (ABS)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Grey headliner
- Decorative inlay silver brushed
- Tachometer
- Easy Start (start-stop button instead of ignition lock)
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor
- Front radar assistant including city emergency braking function
- Transmission: 6-speed manual transmission
- Tinted windows
- Rear window wiper including windshield washer system
- Boot cover, roll-up and removable, semi-automatic
- Front and rear headrests are height-adjustable.
- LED taillights
- Reading lights at the front and rear of the headliner
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- Upholstery: Cloth
- Radio accessories: 2 USB-A ports in the center console
- Radio accessories: In-car communication
- Radio accessories: Wireless SmartLink for Apple CarPlay
- Tire mobility kit
- Heated windshield washer nozzles
- Superb seat belts
- Seats: Height-adjustable front seats
- SKODA Care Connect
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- Telephone: Convenient Bluetooth hands-free phone system
- Immobiliser



Extra equipment

- Adaptive Cruise Control (ACC) (control range up to 210 km/h) (replaces cruise control)
- Swiveling trailer hitch including trailer stabilization
- Heated windshield
- Electric tailgate opening (including boot cover and multifunction storage compartment)
- Paint finish: Pearl effect
- Steering wheel: Heated steering wheel (2 spokes)
- Matrix LED headlights (AFS - dynamic high beam assist - automatic headlight range control - headlight cleaning system - LED taillights in crystal glass look - incl. dynamic turn signals)
- Front and rear parking sensors
- Seats: Heated front seats
- Sunshade roller blind for the rear side windows
- Lane Assist, Blind Spot Detection and Parking Assist (Lane Assist with adaptive lane guidance)
- Variable loading floor in the trunk including organizer and aluminum crossbars
- Airbag, proactive occupant protection including rear side airbags
- Ashtray and lighter at the front
- Digital instrument cluster (Virtual Cockpit) 10.2"
- ISOFIX preparation on the front passenger seat
- Climatronic air conditioning (3-zone) (fully automatic, separately adjustable for driver, front passenger and rear seats)
- Package: Business Amundsen (Combi) (Amundsen dynamic radio navigation system - 8" capacitive touchscreen in glass design - color Maxi-Dot display - Wi-Fi hotspot (uses the data connection of the paired mobile phone) - voice control - phone box with inductive charging function (connection via external antenna) - driver fatigue detection - 230 V socket and USB ports, tablet holder in the rear - Sunset (dark tinted rear window and rear side windows) - Infotainment Online subscription (3 years) - luggage net partition)
- Traffic sign recognition for navigation systems

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front left side	Door edge - Scratched - Smart repair
3	Boot lid / rear door	Rear spoiler - dent(s) - Smooth repair work
4	Sill - right side	Sill - Scratched - Smart repair
5	Roof	Roof rail - left side - Dent / paintcoat damage - Smart repair
6	Roof	Roof - dent(s) - Smooth repair work
7	Side panel - rear right side	Side panel - Scratched - Paint
8	Rear bumper	Rear bumper - Scratched - Paint
9	Door - rear left side	Door - Scratched - Paint
10	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
11	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
12	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
13	Vehicle glazing	Windscreen - Broken / torn - Replace



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front left side: Door edge - Scratched - Smart repair



Damage 2: Door - front left side: Door edge - Scratched - Smart repair



Damage 3: Boot lid / rear door: Rear spoiler - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Rear spoiler - dent(s) - Smooth repair work



Damage 4: Sill - right side: Sill - Scratched - Smart repair




Damage 4: Sill - right side: Sill - Scratched - Smart repair



Damage 4: Sill - right side: Sill - Scratched - Smart repair



Damage 4: Sill - right side: Sill - Scratched - Smart repair



Damage 5: Roof: Roof rail - left side - Dent / paintcoat damage - Smart repair



Damage 5: Roof: Roof rail - left side - Dent / paintcoat damage - Smart repair



Damage 5: Roof: Roof rail - left side - Dent / paintcoat damage - Smart repair




Damage 5: Roof: Roof rail - left side - Dent / paintcoat damage - Smart repair




Damage 5: Roof: Roof rail - left side - Dent / paintcoat damage - Smart repair




Damage 6: Roof: Roof - dent(s) - Smooth repair work




Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 6: Roof: Roof - dent(s) - Smooth repair work




Damage 6: Roof: Roof - dent(s) - Smooth repair work




Damage 6: Roof: Roof - dent(s) - Smooth repair work



Damage 7: Side panel - rear right side: Side panel - Scratched - Paint




Damage 7: Side panel - rear right side: Side panel - Scratched - Paint



Damage 7: Side panel - rear right side: Side panel - Scratched - Paint



Damage 7: Side panel - rear right side: Side panel - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint




Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 8: Rear bumper: Rear bumper - Scratched - Paint



Damage 9: Door - rear left side: Door - Scratched - Paint



Damage 9: Door - rear left side: Door - Scratched - Paint



Damage 9: Door - rear left side: Door - Scratched - Paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 13: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 13: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 13: Vehicle glazing: Windscreen - Broken / torn - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: TMBJH9NP2M7075108
Hersteller / Modell: SKODA SKODA Superb Combi 2.0 TDI Ambition

Datum	KM-Stand	Beschreibung
28.10.2025	95.316	Batterie ern; Systemtest/Eigendiagnose
23.07.2025	89.698	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben + Klötze h; Bremsscheiben + Klötze v; Bremsscheiben hinten; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
02.12.2024	74.758	Systemtest/Eigendiagnose
13.11.2024	73.674	AU
05.01.2024	54.057	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Reparatur Sonstiges; Wartung Sonstiges
29.12.2022	30.318	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges