

DEKRA Automotive Solutions

Vehicle details

VIN	TMBEG6NW0 L3108008	Registration date	01/01/1900	Exterior Color	Unknown
Brand	SKODA	Licence Plate	2CVZ813	Odometer	132 762 km
Model	SCALA				

Inspection Details

Arrival Date	26/06/2026	Inspection ID	7041890	Inspection date	06/07/2026
Assign Date	26/06/2026	Fleet owner	LIZY Belgique	Inspection loc.	Parc Lizy



Generic equipment


Removable element

Emergency compressor kit	✓
Refill emergency kit	✓
Rear parcel shelf	✓

Technical Document

Service manual holder	✓
User manual	✓
Adapter USB	✓
Spare key	✓
Certificate of conformity	✓
Title / License document	✓

Tyres



Damages

1		Part	Engine soundproofing	Repair Time	0.20	Part Cost	21.10€
		Position	-	Repair Cost	15.00€	Gross Cost	36.10€
		Damages	Perforated	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	Replace	Flat Rate	-	Net Cost	36.10€
2		Part	Bonnet	Repair Time	-	Part Cost	-
		Position	-	Repair Cost	-	Gross Cost	-
		Damages	Dented	Paint Time	-	Depreciation %	-
		Severity	-	Paint cost	-	Depreciation	-
		Repair mode	For info	Flat Rate	-	Net Cost	-

DEKRA Automotive Solutions

3



Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	153.00€
Damages	Improper repair	Paint Time	1.80	Depreciation %	-
Severity	-	Paint cost	153.00€	Depreciation	-
Repair mode	Repair	Flat Rate	-	Net Cost	153.00€
vernis qui se decolle					

4



Part	Turning signal side	Repair Time	0.40	Part Cost	24.33€
Position	Front left	Repair Cost	30.00€	Gross Cost	54.33€
Damages	Broken	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	Net Cost	54.33€

5



Part	Spoiler	Repair Time	0.80	Part Cost	208.89€
Position	Back	Repair Cost	60.00€	Gross Cost	268.89€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	Net Cost	268.89€

6



Part	Bumper	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	144.50€
Damages	Scratched	Paint Time	1.70	Depreciation %	-
Severity	-	Paint cost	144.50€	Depreciation	-
Repair mode	Repair	Flat Rate	-	Net Cost	144.50€

7



Part	Wing	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	-
Damages	Dented	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	Net Cost	-

Summary Inspection

Gross Price	656.82€	Depreciation	-	Net Price	656.82€
-------------	---------	--------------	---	-----------	---------

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	75.00€	1.40	105.00€	-	-	105.00€
Paintwork	85.00€	3.50	297.50€	-	-	297.50€
Paint preparation	85.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	254.32€	-	-	254.32€
Flat Rate	0.00€	-	-	0.00€

Signatures		
Signature Receiver	Signature Expert	Signature Customer / Driver
		Verraeve Stephanie  06-07-26 10:54