



Expertise

Protocol number: 46401776
Order No. / Reference: 26698861
Inspection date: 8 Jul 2026

Manufacturer: Opel	Model: Astra Sports Tourer 1.5 D Automatik Business Elegance
VIN: VXKFCYHZTP1100806	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra Sports Tourer 1.5 D Automatik Business Elegance	
Vehicle Identification number	VXKFCYHZTP1100806
Mileage (Read)	113,191 km
First registration	26 Mar 2024
Number of holders	1
Next periodical technical inspection	03/2027
(Report not on hand)	
Power / Engine displacement	96 kw / 1,499 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	TYPE HABILLAGE EXTERIEUR PLATE STANDARD
Doors / Seats	5 / 5
Upholstery type	Part leather
Colour of upholstery	Anthracite-Light grey



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	9 Monat(e)
Last service on / at	03/2026 at 103,348 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB418967
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AEY 00107		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	1,980 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	5mm / 2mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Fulda	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Steel rim with wheel cover	Fulda	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Storage compartments • Airbag: Front airbags, driver and front passenger • Airbag: Front and rear outer head airbags • Automatic activation of the hazard warning lights • Exterior mirror housings in black • On-board computer • Roof rails • Tachometer • Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus) • Transmission: 8-speed automatic transmission • rear window wiper • Cable set for trailer hitch • Dual-zone automatic climate control • Paintwork: Roof in car color • LED interior lighting • Steering wheel: Leather steering wheel, flat-bottomed, perforated, with steering wheel remote control and paddle shifters • Navigation system • Electric parking brake • Tire pressure monitoring system • 180-degree reversing camera • Keyless locking and starting system Keyless Open & Start • safety net • Heated seats, driver and passenger • Solar Protect thermal insulation glazing • 12V power outlet in the center console • Electronic immobilizer • Central locking with remote control | <ul style="list-style-type: none"> • Airbag: Chest-pelvis-side airbags, driver and front passenger • Anti-lock braking system (ABS) • Exterior mirrors, electrically adjustable, heated and folding • Hill Start Assist • third brake light • Diesel particulate filter (DPF) maintenance-free • Electronic brake force distribution (EBD) • Electric windows front and rear • Front collision warning system • Back window, heater • Interior rearview mirror, automatically dimming • Air conditioning: Intelli-Air air quality system "Clean Cabin" • Front headrests and 3 rear headrests, height adjustable • LED ambient lighting • LED headlights • Steering wheel heating • Illuminated makeup mirrors in both sun visors • Center armrest, front and rear • Fog light • Tire repair kit • Wheels: Alloy wheels 7.5 J x 17 (5 spokes) in silver/black • Rear seat backrest folds forward in a 40:20:40 split • Seat belts: Three-point seat belts in all seats • Seats: Ergonomic active driver's seat, fabric/premium leatherette Isabella • Start/Stop System • Pre-wiring for ISOFIX child seat mounting system • Wireless Charging |
|---|---|

Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Paint finish: Solid | |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	2nd wheel set	1 wheel cover - Scratched - Replace
2	Braking system	Brake discs - rear (Freibremsen-Mehrkosten möglich) - Corrosion - Perform
3	Wheel / tyres	Tyre - rear right side (Einfahrschaden, nicht fahrbereit) - Leaking - Replace
4	Seat - front	Seat cover - right side (Sitze) - Soiled - Clean
5	Sill - left side	Sill - front - Scratched - Smart repair
6	Front bumper	Front bumper - Scratch(es) - Smart repair
7	Engine	Engine cover - Broken / torn - Replace
8	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
9	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side - left, Provided by user / customer, from 22 May 2025	6.957,90 €

Repainting

No.	Repainting
1	Mudguard - left side, Professionally carried out

Paint coat thickness measurement

Mudguard - left side	216 µm
----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Documents




Figure 20: Documents




Figure 21: Documents




Figure 22: Documents



Figure 23: Documents



Figure 24: Documents



Figure 25: Documents



Figure 26: Additional tyres



Figure 27: Navigation



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.



Damage 1: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 1: 2nd wheel set: 1 wheel cover - Scratched - Replace



Damage 2: Braking system: Brake discs - rear (Freibremsen-Mehrkosten möglich) - Corrosion - Perform



Damage 2: Braking system: Brake discs - rear (Freibremsen-Mehrkosten möglich) - Corrosion - Perform



Damage 2: Braking system: Brake discs - rear (Freibremesen-Mehrkosten möglich) - Corrosion - Perform



Damage 2: Braking system: Brake discs - rear (Freibremesen-Mehrkosten möglich) - Corrosion - Perform



Damage 2: Braking system: Brake discs - rear (Freibremesen-Mehrkosten möglich) - Corrosion - Perform



Damage 2: Braking system: Brake discs - rear (Freibremesen-Mehrkosten möglich) - Corrosion - Perform



Damage 3: Wheel / tyres: Tyre - rear right side (Einfahrschaden, nicht fahrbereit) - Leaking - Replace



Damage 3: Wheel / tyres: Tyre - rear right side (Einfahrschaden, nicht fahrbereit) - Leaking - Replace



Damage 3: Wheel / tyres: Tyre - rear right side (Einfahr Schaden, nicht fahrbereit) - Leaking - Replace



Damage 3: Wheel / tyres: Tyre - rear right side (Einfahr Schaden, nicht fahrbereit) - Leaking - Replace



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 4: Seat - front: Seat cover - right side (Sitze) - Soiled - Clean



Damage 5: Sill - left side: Sill - front - Scratched - Smart repair



Damage 5: Sill - left side: Sill - front - Scratched - Smart repair



Damage 5: Sill - left side: Sill - front - Scratched - Smart repair




Damage 5: Sill - left side: Sill - front - Scratched - Smart repair




Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 6: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 7: Engine: Engine cover - Broken / torn - Replace



Damage 7: Engine: Engine cover - Broken / torn - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value




Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction




Wear and tear 1: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Mudguard - left side: 216 µm