

Expertise

Protocol number: 46202180
Order No. / Reference: 26544865
Inspection date: 26 Jun 2026

Manufacturer: Ford

Model: Transit Connect 250 L2 Trend

VIN: WF0SXXWPGSNJ57321



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit Connect 250 L2 Trend

Vehicle Identification number WF0SXXWPGSNJ57321

Mileage (Read) 46,865 km

First registration 9 Nov 2022

Number of holders 1

Power / Engine displacement 88 kw / 1,499 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle Van

Colour / colour code Frost Weiß

Doors / Seats 4 / 3

Upholstery type Cloth

Colour of upholstery Black-Anthracite



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	28 %
Last service on / at	01/2025 at 30,076 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK842028
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BMN 02528		
Emission standard	EURO6;WLTP;AQ;PI/CI; N1 II	fine dust sticker	
Permitted total weight	2,370 kg	Empty weight	

Tyres

Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Dunlop	4mm / 4mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Dunlop	6mm / 6mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	205/60 R16 96H	Summer tyres on Light alloy	Continental	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 96H	Summer tyres on Steel	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment with 12-volt connection
- Driver's side airbag
- Exterior mirrors, narrow mirror format
- Battery, reinforced
- Rubberized flooring, front
- Diesel particulate filter (DPF)
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Ford Easy Fuel
- Heated windshield
- Transmission: 6-speed transmission
- Glove compartment with lid
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Alternator/Generator
- Fog light
- Wheels: Alloy wheels 6.5 J x 16 with 205/60 R16 tires
- Side protection strips, plastic
- Safety brake assist
- Automatic door locking mechanism (45 sec.)
- Start-stop system
- Power outlet: 12-volt connection on the front center console
- Daytime running light
- Child safety lock on sliding doors
- Lashing eyes
- Electronic immobilizer (EPATS)
- Central locking with remote control

Extra equipment

- Airbag: Front airbag for passenger (front airbag for passenger including deactivation function and glove compartment with lid)
- Floor covering: Front floor mats, all-weather floor mats (2-piece set)
- Remote control: 2nd remote control key for central locking (instead of conventional key)
- Spare wheel: Steel wheel
- Seats: Seat package 30 (fabric "Capitol/City" in Ebony (black) - double passenger seat, variably foldable and collapsible (with storage compartment under smaller seat section) - driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - headrests, height-adjustable - seat heating for driver's seat - lumbar support, manual (driver's seat))
- Partition wall to the cargo area with pass-through opening, no window

- ABS with EBD
- Exterior mirrors, electrically adjustable and heated
- Exterior mirror housing black
- Hill start assist
- On-board computer including outside temperature display
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows
- FordPass Connect
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Front interior lighting with delay function
- Paint finish: Solid
- Cargo area floor protection plastic, molded
- Steering column, adjustable in height and reach
- Center console, front
- Emergency brake light
- Sliding door at rear, right
- Electro-mechanical power steering
- Front seat belts are height-adjustable
- Front spoiler lip
- Dust and pollen filter
- Front bumper and rear bumper end caps painted in body color
- Door handles, black
- Warning system for unfastened seat belts
- Heat-insulating glazing, lightly tinted
- Auxiliary electric heater (PTC), front

- Fixed towbar (incl. ESP trailer stabilization and continuous power supply)
- Electrically folding exterior mirrors (including electric front windows with quick-up/down function - mirrors fold in automatically when the vehicle is locked)
- Cargo area lighting, LED
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, TMCpro live traffic, detailed 3D visualization, Michelin travel guide for Europe)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Instrument panel	Centre console - front - Glued / labelled - De-glue / neutralise
2	Sliding door, right	Door seal (Unten) - Broken / torn - Replace
3	Roof	Roof - dent(s) - Smooth repair work
4	Boot lid / rear door	Rear door - right side - Paint defect - Smart repair
5	Seat - front	Seat cover - left side - Burn hole (cigarettes) - Smart repair
6	Roof	Roof rail - right side - Dent / paintcoat damage - Smart repair
7	Sill - right side	Trim (Materialabtrag) - Scratched - Replace
8	Rear bumper	Rear bumper (unpainted) - Broken / torn - Replace
9	Sill - right side	Sill - Deformed - Repair and paint
10	Side panel - rear right side	Side panel - Deformed - Repair and paint
11	Sliding door, right	Sliding door - Deformed - Repair and paint
12	Side panel - rear left side	Side panel - Deformed - Repair and paint
13	Front bumper	Front bumper (Kratzer) - Stone chips - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Interior	Cargo area floor (Laderaum) - Scratch(es) - No deduction
3	Door - front left side	Door - dent(s) - No deduction
4	Misc.	Misc. (Regale) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 18 Jun 2024	1.754,84 €



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.



Damage 1: Instrument panel: Centre console - front - Glued / labelled - De-glue / neutralise



Damage 1: Instrument panel: Centre console - front - Glued / labelled - De-glue / neutralise




Damage 2: Sliding door, right: Door seal (Unten) - Broken / torn - Replace



Damage 2: Sliding door, right: Door seal (Unten) - Broken / torn - Replace



Damage 3: Roof: Roof - dent(s) - Smooth repair work




Damage 3: Roof: Roof - dent(s) - Smooth repair work



Damage 4: Boot lid / rear door: Rear door - right side - Paint defect - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Paint defect - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Paint defect - Smart repair



Damage 4: Boot lid / rear door: Rear door - right side - Paint defect - Smart repair



Damage 5: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



Damage 5: Seat - front: Seat cover - left side - Burn hole (cigarettes) - Smart repair



Damage 6: Roof: Roof rail - right side - Dent / paintcoat damage - Smart repair



Damage 6: Roof: Roof rail - right side - Dent / paintcoat damage - Smart repair



Damage 6: Roof: Roof rail - right side - Dent / paintcoat damage - Smart repair



Damage 7: Sill - right side: Trim (Materialabtrag) - Scratched - Replace




Damage 7: Sill - right side: Trim (Materialabtrag) - Scratched - Replace



Damage 7: Sill - right side: Trim (Materialabtrag) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (unpainted) - Broken / torn - Replace




Damage 8: Rear bumper: Rear bumper (unpainted) - Broken / torn - Replace




Damage 8: Rear bumper: Rear bumper (unpainted) - Broken / torn - Replace



Damage 8: Rear bumper: Rear bumper (unpainted) - Broken / torn - Replace



Damage 8: Rear bumper: Rear bumper (unpainted) - Broken / torn - Replace



Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint




Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 9: Sill - right side: Sill - Deformed - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 10: Side panel - rear right side: Side panel - Deformed - Repair and paint




Damage 10: Side panel - rear right side: Side panel - Deformed - Repair and paint



Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint



Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint



Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint



Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint



Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint




Damage 11: Sliding door, right: Sliding door - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Deformed - Repair and paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint




Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Damage 13: Front bumper: Front bumper (Kratzer) - Stone chips - Paint



Wear and tear 3: Door - front left side: Door - dent(s) - No deduction




Wear and tear 3: Door - front left side: Door - dent(s) - No deduction




Wear and tear 4: Misc.: Misc. (Regale) - No deduction



Wear and tear 4: Misc.: Misc. (Regale) - No deduction



Wear and tear 4: Misc.: Misc. (Regale) - No deduction



Wear and tear 4: Misc.: Misc. (Regale) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0SXXWPGSNJ57321
Hersteller / Modell: FORD FORD Transit Connect 250 L2 Trend

Datum	KM-Stand	Beschreibung
15.01.2025	30.076	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.11.2024	0	HU + AU