



Expertise

Protocol number: 46538321
Order No. / Reference: 26652354
Inspection date: 15 Jul 2026

Manufacturer: Renault

Model: Master dCi 135 L3H3 VA Basis

VIN: VF1MA000666414533



Vehicle details

Manufacturer / Type / Model / Equipment

Renault Master dCi 135 L3H3 VA Basis

Vehicle Identification number VF1MA000666414533
Mileage (Read) 30,172 km
First registration 10 Feb 2021
Number of holders 1
Next periodical technical inspection 01/2027
(Report on hand)

Power / Engine displacement 100 kw / 2,299 ccm
Fuel type / Cylinder Diesel / 4
Gearbox / Number of gears Manual / 6
Type of drive Front drive
Type of vehicle Van

Colour / colour code Mineral-Weiß
Doors / Seats 4 / 3
Upholstery type Leather
Colour of upholstery Black

Re-import no
readiness to drive Not roadworthy / moveable



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	0 km
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX151152
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	3333 / BCZ 01242		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112T	All-season tyres on Steel	Continental	6mm / 6mm
2)	225/65 R16 112T	All-season tyres on Steel	Continental	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • ABS with EBV and brake assist • Automatic door locking after starting to drive • On-board computer • Tachometer • ESP with load detection • Chrome-plated front grille surround • Glove compartment, closed • Fuel tank 105 liters • LED daytime running lights • Light and rain sensor • Pollen filter • Wheel cover • Tire repair kit • Wheels: Steel rim 16" • Key: 3-button key with radio remote control • Power steering • Seats: Driver's seat height adjustable • 12V power outlet on the dashboard • Electronic immobilizer | <ul style="list-style-type: none"> • Airbag: Driver's side • Exterior mirrors, electrically adjustable and heated • third brake light • Easy-Life work surface - elimination • electric front windows • Transmission: 6-speed manual transmission • Headrests (3) • Paint finish: Solid • Height-adjustable steering wheel • Alternator 230 A • Upholstery: Fabric "Kaleido" • Tires 225/65 R16 • Self-cleaning diesel particulate filter • Sliding door on the right, closed • Crosswind assist • Seats: Double passenger seat (multifunctional) • Seats: Driver's seat, height adjustable • Lashing eyes in the cargo area floor • Central locking |
|--|---|

Extra equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Airbag: Passenger airbag • Ventilation, right side panel perforated sheet metal • Rear doors, opening angle 180°, with window • LED lighting in the cargo area • Upholstery: artificial leather • Tires: All-season tires • Partition wall with window, barred | <ul style="list-style-type: none"> • Airbag: Side airbag for driver and front passenger • Rear parking sensors • Wooden floor in the cargo area • Package: Sound & Climate DAB+ (Air conditioning with pollen filter - Radio MP3 DAB+ with integrated Bluetooth hands-free system) |
|--|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.



Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Historie) - No evidence - No deduction
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Mudguard - left side	Mudguard - left side - Scratched - Smart repair
4	Sill - left side	Sill - Scratched - Smart repair
5	Wheel / tyres	Tyre - front right side (225,65,16,g) - Broken / torn - Replace
6	Wheel / tyres	Tyre - rear right side (225,65,16g) - Broken / torn - Replace
7	Tail light	Tail lamp - right side - Scratched - Replace
8	Body	Body (Ausbleichungen) - Glued / labelled - Conditioning
9	Misc.	Inspection / maintenance - Due - Perform
10	Boot lid / rear door	Rear door - left side - Scratch(es) - Paint
11	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
12	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Partition wall - Dent / paintcoat damage - No deduction
2	Boot lid / rear door	Rear door - right side (Innen) - Scratched - No deduction
3	Boot lid / rear door	Rear door - left side - Dent / paintcoat damage - No deduction
4	Fuel system	Tank flap - Soiled - No deduction
5	Sill - right side	Sill - Scratched - No deduction
6	Rear bumper	Rear bumper (unpainted) - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit filler

Repainting

No. Repainting

- 1 Side panel - rear right side

Paint coat thickness measurement

Side panel - rear right side

217 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Comments

- Restlaufzeit bis zum nächsten Service wird nicht angezeigt.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 3: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage 3: Mudguard - left side: Mudguard - left side - Scratched - Smart repair



Damage 4: Sill - left side: Sill - Scratched - Smart repair



Damage 4: Sill - left side: Sill - Scratched - Smart repair



Damage 4: Sill - left side: Sill - Scratched - Smart repair



Damage 5: Wheel / tyres: Tyre - front right side (225,65,16,g) - Broken / torn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (225,65,16,g) - Broken / torn - Replace



Damage 5: Wheel / tyres: Tyre - front right side (225,65,16,g) - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - rear right side (225,65,16g) - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - rear right side (225,65,16g) - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - rear right side (225,65,16g) - Broken / torn - Replace




Damage 7: Tail light: Tail lamp - right side - Scratched - Replace



Damage 7: Tail light: Tail lamp - right side - Scratched - Replace




Damage 7: Tail light: Tail lamp - right side - Scratched - Replace



Damage 7: Tail light: Tail lamp - right side - Scratched - Replace



Damage 8: Body: Body (Ausbleichungen) - Glued / labelled - Conditioning



Damage 8: Body: Body (Ausbleichungen) - Glued / labelled - Conditioning




Damage 8: Body: Body (Ausbleichungen) - Glued / labelled - Conditioning




Damage 8: Body: Body (Ausbleichungen) - Glued / labelled - Conditioning



Damage 10: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 10: Boot lid / rear door: Rear door - left side - Scratch(es) - Paint



Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 12: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Body: Partition wall - Dent / paintcoat damage - No deduction



Wear and tear 2: Boot lid / rear door: Rear door - right side (Innen) - Scratched - No deduction



Wear and tear 3: Boot lid / rear door: Rear door - left side - Dent / paintcoat damage - No deduction



Wear and tear 4: Fuel system: Tank flap - Soiled - No deduction



Wear and tear 5: Sill - right side: Sill - Scratched - No deduction



Wear and tear 6: Rear bumper: Rear bumper (unpainted) - dent(s) - No deduction



Missing part 1: Equipment: Tirefit filler - Missing - Replace



Repainting 1: Side panel - rear right side