






Vehicle information



Make:	smart	License:	
Gearbox:	Automatic	Body color:	
Model:	#5	VIN:	HESYA5C40SG203904
Fuel type:	Electric	Power:	
Version:	Pulse	First registration	06/02/2026
Mileage:	6468 km	N° of doors:	5

Damage summary

Front	①
Left	①
Right	③

Commercial pictures





Options according to the inspector

Floor mats	OK	Panoramic roof	Yes	Type of GPS	GPS big screen color
Type of Tow bar	Tow bar removable				

Damages

Alloy rim FR polished
Scratch(es)
Repair and paint (complete)
Right



Alloy rim RL polished

Scratch(es)

Repair and paint (complete)

Left




Alloy rim RR polished

Scratch(es)

Repair and paint (complete)

Right



Bumper F

Scratch(es)

Spot repair

Front



Door RR
Scratch(es)
Spot repair
Right



Tyres

Front Left
Summer
255/45/20/105/V
Continental
6.0 mm

Front Right
Summer
255/45/20/105/V
Continental
4.7 mm

Rear Left
Summer
255/45/20/105/V
Continental
4.4 mm

Rear Right
Summer
255/45/20/105/V
Continental
3.5 mm

Checks

Car checked on car lift?	No	Certificate of Conformity	Yes
Cover trailer hitch	Yes	Fuel Level	25
Maintenance needed	No	Multi-media screen functioning?	Yes
Number head rests	5	Number of charging cables (rapid charge)	1
Number of doors	5	Number of keys total	1
Registration certificate original	Yes	Type of Emergency Tool	Repair kit present
Type of Instructionbook	Digital Instructionbook	Type of Luggage cover	Boot cover present
Type of Maintenance book	Digital maintenance	Vehicle accident?	No

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.