



Expertise

Protocol number: 46791414
Order No. / Reference: 26777074
Inspection date: 27 Jul 2026

Manufacturer: Kia

Model: Ceed SW 1.6 CRDi (48V Mild-Hybrid) Vision

VIN: U5YH5819APL146921



Vehicle details

Manufacturer / Type / Model / Equipment

Kia Ceed SW 1.6 CRDi (48V Mild-Hybrid) Vision

Vehicle Identification number U5YH5819APL146921
Mileage (Read) 135,978 km
First registration 14 Jul 2023
Number of holders 1

Fuel type Hybrid Diesel / E
Engine displacement / Cylinder 1,598 ccm / 4
Power 100 kW
Gearbox / Number of gears Manual / 6
Type of drive Front drive
Type of vehicle Station wagon

Colour / colour code Black Metallic
Doors / Seats 5 / 5
Upholstery type Cloth
Colour of upholstery Black-Grey

readiness to drive Not roadworthy / not moveable



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	12,510 km
Last service on / at	05/2026 at 128,488 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV849520
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Not roadworthy / not moveable		
Manufacturer key number/ type code number	2234 / ABC 00026		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,930 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	unterschiedliche Hersteller	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Summer tyres on Light alloy	Hankook	6mm / 6mm
2)	205/55 R16 91H	Summer tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
Tirefit		Expiration date 04/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment



Standard equipment

- ABS (Anti-lock Braking System) with electronic brake force distribution
- Airbag: 2 side airbags
- Active lane keeping assist with corrective steering intervention (Lane Keep Assist, LKA)
- Electrically adjustable exterior mirrors
- Hill Start Assist Control (HAC)
- Brake Assist (BAS)
- Overhead console with glasses compartment
- Roof rails
- Anti-theft alarm system
- Tachometer
- Drive Mode Select
- EcoDynamics (start-stop system ISG)
- Electronic Stability Control (ESC) with Traction Control System (TCS)
- Electric windows front and rear (with auto-up/down function and anti-pinch protection at the front)
- Front Collision Avoidance Assist (FCA) with braking intervention and pedestrian/bicycle detection as well as warning via steering wheel vibration
- Luggage net eyelets
- Luggage compartment lighting
- Transmission: 6-speed manual transmission
- Back window, heater
- Rear Seat Alert (RSA)
- air conditioning, manual
- Faux leather gear knob
- LED taillights
- LED daytime running lights at the front
- Steering wheel: Leather steering wheel
- Rear center armrest (with integrated cup holder)
- Driver Attention Warning (DAW)
- Fog light
- Kia Connect online services with Kia Live (real-time traffic information, weather forecast, local search, parking options, and the ability to access vehicle information and control vehicle functions via the Kia Connect app)
- Radio accessories: 2 front speakers
- Radio accessories: 2 tweeters
- Radio accessories: DAB radio
- Tire pressure monitoring system (TPMS)
- Wheels: 16-inch alloy wheels with 205/55 R16 91H tires
- Power steering (electronically assisted)
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Heated front seats
- Sun visors with illuminated makeup mirrors
- Lane Follow Assist (LFA)
- Supervision instrument display with a 10.7 cm (4.2 inch) screen diagonal
- Airbag: 2 front airbags (passenger airbag can be deactivated)
- Airbag: 2 curtain airbags
- Active brake light (Emergency Stop Signal, ESS)
- Heated exterior mirrors
- Exterior mirrors in car color
- On-board computer
- Headliner and pillar trim in grey
- Front overhead console with reading lights and central lighting
- Diesel particulate filter with SCR
- Third brake light (LED) in the rear spoiler
- twilight sensor
- Gloss black inserts (instrument panel, door trim and gearshift surround)
- Energy Regeneration System (Alternator Management System, AMS)
- High Beam Assist (HBA)
- Headlights (Halogen)
- floor mat set
- Compartments in the boot floor
- luggage compartment cover
- Cruise control and speed limiter
- Front cup holder
- rear window wiper
- ISOFIX anchor points (on both outer rear seats)
- Headrests on all seats are height-adjustable.
- Radiator grille in gloss black with chrome frame (glossy)
- LED daytime running lights at the rear
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- Front center armrest (with storage compartment)
- Navigation: Kia map navigation with 26 cm (10.25 inch) screen diagonal (incl. 2 over-the-air updates and 7-year Kia navigation map update)
- Rear parking sensors (PDW-R)
- Upholstery: Cloth
- Radio accessory: Roof antenna (in shark fin design)
- Radio accessories: 2 rear speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: USB interface
- Tire repair kit
- Reversing camera (transmission to multimedia screen)
- Front seat belts are height-adjustable (three-point seat belts at all seating positions - seat belt warning system front and rear)
- Smartphone interface Android Auto and Apple CarPlay with voice control
- 12V power outlet (in the center console)
- Interior door handle in chrome finish
- Traffic sign recognition for speed limits (Intelligent Speed Limit Warning, ISLW)
- Central locking with remote control



- Immobiliser
- thermal insulation glazing

Extra equipment

- P8 - Comfort Package (Vision)
- P9 - Navigation Package (Vision)
- Paint finish: Metallic paint
- Preparation for detachable towbar ((wiring kit and bodywork modifications carried out, towbar included), additional costs for installation of the towbar carrier will apply)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not roadworthy at the time of inspection, but only capable of being towed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door handle - outside - Scratch(es) - Smart repair
2	Door - front left side	Door - Stone chips - Smart repair
3	Electrical system	Battery - Differs from the original configuration - Perform diagnosis
4	Sill - right side	Sill - Scratch(es) - Smart repair
5	Roof	Roof rail - left side - Scratch(es) - Smart repair
6	Body	A-pillar - left side - Scratch(es) - Smart repair
7	Door - rear right side	Door - Scratch(es) - Smart repair
8	Trim / covers	Door trim - rear right side - Scratch(es) - Loss in value
9	Rear bumper	Spoiler - Scratch(es) - Replace
10	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
11	Rear bumper	Rear bumper - Scratch(es) - Paint
12	Side panel - rear left side	Side panel - Scratch(es) - Paint
13	Front bumper	Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint
14	Door - front right side	Door (Lackstift) - Paint defect - Paint
15	Roof	Roof - Scratch(es) - Paint
16	Bonnet	Bonnet (Anätzung) - Paint defect - Paint
17	Boot lid / rear door	Boot lid - Scratch(es) - Paint
18	Side panel - rear right side	Side panel (Einschlüsse) - Paint defect - Repair and paint
19	Vehicle glazing	Windscreen - Broken / torn - Replace
20	Door - rear left side	Door (Spachtel eingefallen) - Unprofessionally repaired - Repair and paint



Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Sill - Scratch(es) - No deduction
2	Wheel / tyres	Tyre - front left side - Broken / torn - No deduction
3	Trim / covers	Floor mats - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Rear of vehicle - Key trailer hitch (2x)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 30 May 2025	818,26 €
2	Side - left, not professionally repaired, Invoice of repair done Non-existent, from 12 Feb 2025	829,58 €
3	Side right, Provided by user / customer, from 12 Nov 2024	1.410,79 €

Repainting

No. Repainting

1 Door - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear left side 242 µm |

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.

Comments

Der montierte Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Damage 1: Door - front left side: Door handle - outside - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Stone chips - Smart repair



Damage 2: Door - front left side: Door - Stone chips - Smart repair



Damage 3: Electrical system: Battery - Differs from the original configuration - Perform diagnosis



Damage 4: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 4: Sill - right side: Sill - Scratch(es) - Smart repair



Damage 5: Roof: Roof rail - left side - Scratch(es) - Smart repair



Damage 5: Roof: Roof rail - left side - Scratch(es) - Smart repair



Damage 5: Roof: Roof rail - left side - Scratch(es) - Smart repair



Damage 6: Body: A-pillar - left side - Scratch(es) - Smart repair




Damage 6: Body: A-pillar - left side - Scratch(es) - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 8: Trim / covers: Door trim - rear right side - Scratch(es) - Loss in value



Damage 8: Trim / covers: Door trim - rear right side - Scratch(es) - Loss in value



Damage 9: Rear bumper: Spoiler - Scratch(es) - Replace




Damage 9: Rear bumper: Spoiler - Scratch(es) - Replace



Damage 10: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 10: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 11: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 11: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 12: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 12: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 12: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint




Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint



Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint



Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint



Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint



Damage 13: Front bumper: Front bumper (+ Spoiler erneuern) - Dent / paintcoat damage - Paint



Damage 14: Door - front right side: Door (Lackstift) - Paint defect - Paint



Damage 14: Door - front right side: Door (Lackstift) - Paint defect - Paint




Damage 14: Door - front right side: Door (Lackstift) - Paint defect - Paint




Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint




Damage 16: Bonnet: Bonnet (Anätzung) - Paint defect - Paint



Damage 16: Bonnet: Bonnet (Anätzung) - Paint defect - Paint



Damage 16: Bonnet: Bonnet (Anätzung) - Paint defect - Paint



Damage 16: Bonnet: Bonnet (Anätzung) - Paint defect - Paint




Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 17: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 18: Side panel - rear right side: Side panel (Einschlüsse) - Paint defect - Repair and paint



Damage 18: Side panel - rear right side: Side panel (Einschlüsse) - Paint defect - Repair and paint



Damage 18: Side panel - rear right side: Side panel (Einschlüsse) - Paint defect - Repair and paint



Damage 19: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 19: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 20: Door - rear left side: Door (Spachtel eingefallen) - Unprofessionally repaired - Repair and paint



Damage 20: Door - rear left side: Door (Spachtel eingefallen) - Unprofessionally repaired - Repair and paint



Damage 20: Door - rear left side: Door (Spachtel eingefallen) - Unprofessionally repaired - Repair and paint



Wear and tear 2: Wheel / tyres: Tyre - front left side - Broken / torn - No deduction



Wear and tear 2: Wheel / tyres: Tyre - front left side - Broken / torn - No deduction



Wear and tear 3: Trim / covers: Floor mats - Broken / torn - No deduction



Repainting 1: Door - rear left side



Repainting 1: Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: U5YH5819APL146921

Hersteller / Modell: HYUNDAI HYUNDAI Ceed SW 1.6 CRDi (48V Mild-Hybrid) Vision

Datum	KM-Stand	Beschreibung
08.06.2026	130.734	Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Wartung Sonstiges
20.05.2026	128.488	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.08.2025	105.891	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
24.02.2025	83.959	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
11.12.2024	61.023	Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
30.07.2024	42.036	Bremsflüssigkeit; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
10.01.2024	19.058	Bremsflüssigkeit; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges