



Expertise

Protocol number: 46794157
Order No. / Reference: 26685288
Inspection date: 29 Jul 2026

Manufacturer: Volvo

Model: V90 T6 Recharge AWD Plus Dark

VIN: YV1PWH1VXP1191947



Vehicle details

Manufacturer / Type / Model / Equipment

Volvo V90 T6 Recharge AWD Plus Dark

Vehicle Identification number	YV1PWH1VXP1191947
Mileage (Read)	65,408 km
First registration	28 Nov 2022
Number of holders	1
Next periodical technical inspection	12/2027
(Report on hand)	

Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,969 ccm / 4
Power	186 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Station wagon

Colour / colour code	Onyx Schwarz-Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Beige



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	191 Tag(e)
Last service on / at	02/2026 at 60,124 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ204563
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	9101 / BSB 00015		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,590 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R20 99W	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	245/40 R20 99W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/40 R19 100V	Winter tyres on Light alloy	Michelin	6mm / 6mm
2)	255/40 R19 100V	Winter tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS - Anti-lock Braking System
- Driver and passenger side airbags with two-stage deployment system
- Aluminum loading sill protector in the luggage compartment
- High-gloss black applications on the rear of the vehicle
- Dashboard and door trim in leather look with contrasting stitching
- Sport exterior mirrors in high-gloss black
- Outdoor temperature display
- Hill Start Assist (HSA)
- fog sensor
- On-board computer with vehicle control functions
- third brake light
- Roof edge spoiler
- Digital services including Google Maps navigation system
- Driver Alert - Attention Warning
- Driver Awareness
- Rear parking assist with automatic braking intervention (rear)
- Electronic Stability Control (ESC)
- Advanced air purification system with fine dust filtration according to air quality standard PM2.5
- Automatic emergency braking
- Sport front grille
- Luggage compartment lid release via remote control or from the driver's seat
- Front seat belt height adjustment
- rear window wiper
- Interior lighting
- Intelligent driver information system
- High-gloss black louvers in the center console
- Keyless Start
- Automatic air conditioning
- Rear headrests foldable, electrically
- Charging cable Schuko/Type 2 (Mode 2), 7 m length, single-phase, 10 A
- Steering wheel adjustable for height and reach
- Illuminated makeup mirror for driver and front passenger
- One Pedal Drive
- Package: Seating comfort
- Electric parking brake
- Pollen filter
- Radio: High Performance Sound Pro audio system by Harman/Kardon
- Radio accessories: Two USB-C ports on the back of the center console
- Wheels: Tire pressure monitoring system (passive)
- Safety Assistance
- Safety braking system with disc brakes all around (internally ventilated)
- Sun blinds for the rear side windows (integrated)
- Start/Stop technology
- Acoustic Vehicle Alerting System (AVAS)
- Airbag, passenger airbag can be deactivated
- Active safety belts with belt tensioners
- Ambient lighting
- Android infotainment system
- Applications in the front bumper in high-gloss black
- Electrically folding exterior mirrors
- Electrically adjustable exterior mirrors
- Heated exterior mirrors and rear window (automatic)
- Attachment system for carrier bags in the luggage compartment
- LED turn signals integrated into the exterior mirrors
- Brake energy recuperation
- CleanZone air quality system
- Roof rails in high-gloss black (integrated)
- Digital Instrumentation 2nd Gen.
- Driver Assistance
- Inlays: Checkered aluminum inlay
- Aluminum door sill plates with Recharge lettering at the front and rear
- Electronic differential lock
- Electric windows front and rear
- Window surround in high-gloss black
- Sport front and rear apron
- Luggage compartment partition net
- Adaptive Cruise Control
- Transmission: 8-speed Geartronic
- Automatic tailgate (electric)
- Interior and exterior mirrors with automatic dimming function
- ISOFIX anchors for the outer rear seats
- Keyless Drive (electronic access system)
- Child safety lock for the rear doors, electric
- Headrests (5)
- Charging box under the cargo floor
- Cargo area roller blind (electric)
- LED headlights "Thor's Hammer"
- Steering wheel: Multifunction buttons on the steering wheel
- Emergency brake lights
- Package: Parking Assistance
- Package: Winter Package
- Parking ticket holder
- Upholstery: Leather/leatherette comfort seats
- Radio accessory: Roof antenna (fin)
- Radio accessories: Subwoofer
- Rain sensor including automatic light function
- Run-off Road Protection
- Wheel accessories: Tire sealant
- Speed-sensitive power steering
- Safety steering column (adaptive)
- Seats: Rear seat backrests can be folded down in a 40/60 split or completely.



- Fuel filler neck with misfuelling protection
- Premium textile floor mats, front and rear
- First aid kit and warning triangle
- Glazing: Acoustic glazing for the side windows
- Warning tone/indicator when seat belts are not fastened (for all seats)
- Central locking system with two remote controls and integrated emergency keys

- Power outlet: 12-volt connection in the luggage compartment
- Trailer Stability Assist (TSA) - Preparation for trailer stability control
- Lashing eyes in the luggage compartment (foldable)
- Immobiliser
- WHIPS whiplash protection system

Extra equipment

- Chassis: Adaptive air suspension on the rear axle with Four C technology (Continuously Controlled Chassis Concept) with adjustable modes Comfort, Eco, Dynamic, including automatic leveling system)
- Package: Light Package (Headlight cleaning system - Full LED headlights "Thor's Hammer" Active High Beam with extended high beam, dynamic cornering lights, intelligent high beam assistant with adaptive headlight range control and integrated LED daytime running lights)
- Side and rear windows tinted (from the B-pillar back)
- Child seats (2-stage) integrated into the outer rear seats
- Paint finish: Metallic paint
- Charging cable with Schuko plug (Mode 2), 7m length max. 1
- Panoramic glass sliding roof with lifting function (with integrated, continuously adjustable sunshade (electric))
- Wheels: 20" alloy wheels, 5-twin-spoke sport design, diamond cut/ high-gloss black (8.5 J x 20 with 245/40 R20 tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratched - Smart repair
2	Indicator - front	Mirror - left side - Scratched - Replace
3	Door - rear right side	Door - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper - Scratched - Paint
5	Boot lid / rear door	Boot lid - Scratch(es) - Paint
6	Side panel - rear right side	Side panel - Scratch(es) - Paint
7	Door - front left side	Door - Scratch(es) - Paint
8	Door - front right side	Door - Scratch(es) - Paint
9	Front bumper	Front bumper - Scratched - Paint
10	Vehicle glazing	Rear window - Broken / torn - Replace



Wear and tear

No.	Component group	Description
1	2nd wheel set	2 alloy rims (Nicht Bestandteil der Ausstattung) - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Tail light	Tail lamp - left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich.
- Mehrkosten möglich .

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Documents



Figure 21: Additional tyres




Figure 22: Navigation



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.






Figure 43: Misc.




Damage 1: Wing mirror - left side: Cap - Scratched - Smart repair




Damage 1: Wing mirror - left side: Cap - Scratched - Smart repair



Damage 2: Indicator - front: Mirror - left side - Scratched - Replace




Damage 2: Indicator - front: Mirror - left side - Scratched - Replace



Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 4: Rear bumper: Rear bumper - Scratched - Paint




Damage 4: Rear bumper: Rear bumper - Scratched - Paint




Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 4: Rear bumper: Rear bumper - Scratched - Paint




Damage 4: Rear bumper: Rear bumper - Scratched - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 5: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Paint



Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 6: Side panel - rear right side: Side panel - Scratch(es) - Paint




Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 7: Door - front left side: Door - Scratch(es) - Paint




Damage 7: Door - front left side: Door - Scratch(es) - Paint




Damage 7: Door - front left side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 8: Door - front right side: Door - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratched - Paint



Damage 9: Front bumper: Front bumper - Scratched - Paint




Damage 9: Front bumper: Front bumper - Scratched - Paint




Damage 9: Front bumper: Front bumper - Scratched - Paint



Damage 9: Front bumper: Front bumper - Scratched - Paint



Damage 10: Vehicle glazing: Rear window - Broken / torn - Replace




Damage 10: Vehicle glazing: Rear window - Broken / torn - Replace




Damage 10: Vehicle glazing: Rear window - Broken / torn - Replace




Damage 10: Vehicle glazing: Rear window - Broken / torn - Replace



Damage 10: Vehicle glazing: Rear window - Broken / torn - Replace



Wear and tear 1: 2nd wheel set: 2 alloy rims (Nicht Bestandteil der Ausstattung) - Scratch(es) - No deduction



Wear and tear 1: 2nd wheel set: 2 alloy rims (Nicht Bestandteil der Ausstattung) - Scratch(es) - No deduction



Wear and tear 1: 2nd wheel set: 2 alloy rims (Nicht Bestandteil der Ausstattung) - Scratch(es) - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 3: Vehicle glazing: Windscreen - Stone chips - No deduction



Wear and tear 5: Tail light: Tail lamp - left side - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: YV1PWH1VXP1191947

Hersteller / Modell: VOLVO VOLVO V90 T6 Recharge AWD Plus Dark

Datum	KM-Stand	Beschreibung
09.02.2026	60.124	Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
13.02.2025	35.365	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
17.01.2024	17.455	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges