



Expertise

Protocol number: 46593804
Order No. / Reference: 26726466
Inspection date: 17 Jul 2026

Manufacturer: Mercedes-Benz

Model: 317 CDI Sprinter Standard HA 9G-TRONIC

VIN: W1V3KBFZ9RP701917



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz 317 CDI Sprinter Standard HA 9G-TRONIC	
Vehicle Identification number	W1V3KBFZ9RP701917
Mileage (Read)	260,993 km
First registration	17 Apr 2024
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	125 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Obsidian black metallic
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	53,600 km
Last service on / at	03/2026 at 193,150 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB951756
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BOW 13352		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Light alloy	Continental	8mm / 8mm
2)	235/65 R16 115R	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Semperit	8mm / 8mm
2)	235/65 R16 115R	Winter tyres on Steel	Semperit	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R C	Summer tyres on Light alloy	Continental	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- Storage compartment above windshield
- Rear towing eye
- ADAPTIVE ESP (latest generation) with load- and speed-dependent driving dynamics control
- Outdoor temperature display
- Battery: fleece battery 12 V / 92 Ah
- third brake light
- Diesel particulate filter and SCR
- Entry handle on rear right corner pillar
- Electric window regulator for driver and passenger door
- Noise measures
- Seatbelt warning device for driver's seat
- Main tank 71 liters
- HOLD function
- KEYLESS start
- Child safety locks on doors in the passenger compartment
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system
- Breakdown management
- Radio: Radio preparation
- Radio accessories: Communication module (LTE) for digital services
- Tires: Summer tires
- Sliding door on the right, cargo/passenger compartment
- Seats: Passenger seat armrest
- Seats: Adjustable passenger seat
- Start-stop function
- continuous partition wall
- Lashing eyes
- Warning triangle
- Heat-insulating glass
- Approval N1
- Storage compartment under cockpit
- Axle ratio $i = 3.923$
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Hill start assist
- Brake lights, adaptive
- Tachometer
- Driving light assistant
- Generator 14 V / 200 A
- Transmission: 9G-TRONIC
- Grab handle for entry to the cargo area sliding door on the partition wall
- Instrument panel and combination instrument with various storage options
- Headrests (2), front
- Headlight range control
- Without weight increase/decrease: 3,500 kg
- Upholstery: Cloth
- Radio: Pre-installation for digital radio DAB
- Tires: Tires without specified make
- Tires: Premium protection tires (3 years)
- Wheels: Steel rims 6.5 J x 16
- Power steering
- Seats: Driver's seat armrest
- Seats: Driver's seat
- Speedometer km/h
- First aid kit
- Pre-installation for Remote Services Plus
- Immobiliser
- Central locking with radio remote control

Extra equipment

- Storage for smartphones including wireless charging
- Distance Assist DISTRONIC active
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Plastic flooring
- Front cupholder
- Anti-theft alarm system and burglar alarm system
- Digital operating instructions
- Chassis stabilization level II
- Fire extinguisher
- Main tank 93 liters
- Hinged lids for storage compartments on the left and right
- Tempmatic controlled air conditioning
- Comfort roof control unit
- Fuel filter with water separator
- LED High Performance Headlights
- leather steering wheel
- Cable duct on side wall
- Marker lights, side
- Navigation accessories: Live Traffic Information
- Navigation: 3 years of free map data updates
- Fog lights with cornering function
- Package: Acoustics in conjunction with MBUX
- Package: Instrument panel charging package in conjunction with MBUX (The charging package expands the charging options in the cockpit with two 5V USB-C ports and one 12V socket. One USB port and the 12V socket are installed in the center storage compartment of the instrument panel, and another USB port is located in the lower part of the center console. This allows for the charging of electronic devices such as mobile phones within easy reach of the driver and front passenger.)
- Tires: Continental brand
- Spare wheel carrier with jack (under frame end)
- Double-leaf rear door, opening to side wall
- Seats: Passenger seat, two-seater
- Seats: Lumbar support for driver's seat
- Seat heating on driver's side
- 230V socket
- Blind Spot Assist
- Partition wall with 1 continuous window
- Cargo area lining up to the beltline
- Front axle with increased load capacity in conjunction with Stage II stabilization
- Elimination of vehicle lowering
- WET WIPER SYSTEM
- Thermal insulation driver's compartment
- Additional rear door locking mechanism at 90 degrees
- Storage above roof lining
- Active Lane Keeping Assist
- Entrance rear door
- Electrically folding exterior mirrors
- Battery: Auxiliary battery for retrofitted devices, interior
- Reference mass of at least 2611 kg is necessary.
- Brake assist, active
- Ceiling light in the cargo/passenger compartment (with door contact)
- Entry handle on rear left corner pillar
- High Beam Assist
- Seatbelt warning device for front passenger seat
- Hinged lid for storage compartment
- Clothes hooks in the driver's cab
- Instrument cluster with color display in conjunction with Active Lane Keeping Assist or Cruise Control
- Paint finish: Metallic
- LED light strip in the cargo area
- Cable duct at rear portal
- Steering wheel: Multifunction steering wheel
- MBUX multimedia system with 10.25-inch touchscreen (High-resolution 10.25-inch touchscreen, hard drive navigation including 3 years of free map data updates, Mercedes PRO features, LINGUATRONIC voice control, WLAN hotspot, multimedia connection unit for connecting portable devices via two USB-C interfaces, multimedia unit in piano black, outer ring of the air vents in matte silver, center fill speaker for improved sound and voice output, improved hands-free function, live traffic capability, digital operation)
- Package: Parking package with reversing camera
- Package: SMOKER
- Radio: Digital Radio DAB
- Rain sensor
- Spare wheel
- Wheels: Alloy wheels 6.5 J x 16
- Seats: Armrest, driver and passenger door
- Seats: Driver's seat box, low
- Seats: Suspension seat comfort version, driver's seat
- 12V socket in the trunk/cargo area
- Power outlet in passenger compartment
- Battery isolator relay additionally
- Traffic Sign Assistant
- Rear panel
- Warm air auxiliary heater with timer
- Hot water auxiliary heater (5 kW)
- Long-throw nozzles in I-panel
- Heat-insulating glass with band filter on the windshield
- Thermal insulation of the cargo/passenger compartment



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sill - left side	Sill - Scratch(es) - Smart repair
2	Vehicle glazing	Windscreen - Stone chips - Smart repair
3	Door - front right side	Door - Scratch(es) - Smart repair
4	Side panel - rear left side	Interior trim - Broken / torn - Replace
5	Body	Body - Glued / labelled - De-glue / neutralise
6	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Boot lid / rear door	Rear door - left side - Scratch(es) - No deduction
2	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No. Accident

- Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Interior - rear



Figure 9: Instrument cluster




Figure 10: Instrument cluster



Figure 11: Instrument panel



Figure 12: Instrument panel




Figure 13: Interior 360° view



Figure 14: Cargo area



Figure 15: Cargo area



Figure 16: VIN



Figure 17: Mounted tyres



Figure 18: Mounted tyres




Figure 19: Documents




Figure 20: Documents



Figure 21: Documents



Figure 22: Additional tyres



Figure 23: Navigation



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.




Figure 36: Misc.



Damage 1: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 1: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 2: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 2: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Side panel - rear left side: Interior trim - Broken / torn - Replace



Damage 4: Side panel - rear left side: Interior trim - Broken / torn - Replace



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise




Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Wear and tear 1: Boot lid / rear door: Rear door - left side - Scratch(es) - No deduction



Wear and tear 1: Boot lid / rear door: Rear door - left side - Scratch(es) -
No deduction




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V3KBFZ9RP701917

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ 317 CDI Sprinter Standard
HA 9G-Tronic

Datum	KM-Stand	Beschreibung
02.03.2026	193.150	Bremse Sonstiges; Bremsklötze hinten; Bremsscheiben hinten; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose; Wartung Sonstiges
31.10.2025	129.598	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
31.01.2025	62.295	Getriebeöl ern/prüfen; Motoröl b. Wartung; Regelwartungsdienst