



Expertise

Protocol number: 46516841
Order No. / Reference: 26417256
Inspection date: 8 Jul 2026

Manufacturer: Volkswagen

Model: Tiguan 1.4 eHybrid OPF DSG R-Line

VIN: WVGZZZ5N3PW407612



Vehicle details

Manufacturer / Type / Model / Equipment

Volkswagen Tiguan 1.4 eHybrid OPF DSG R-Line

Vehicle Identification number WVGZZZ5N3PW407612
Mileage (Read) 65,044 km
First registration 23 Nov 2022
Number of holders 1
Next periodical technical inspection 02/2028
(Report on hand)

Power / Engine displacement 110 kw / 1,395 ccm
Fuel type / Cylinder Hybr.B/E ext.aufl / 4
Gearbox / Number of gears Automatic / 6
Type of drive Front drive
Type of vehicle SUV

Colour / colour code Delfingrau Metallic
Doors / Seats 5 / 5
Upholstery type Cloth
Colour of upholstery Grey-Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	11,500 km
Last service on / at	04/2026 at 61,520 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP846628
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CNC 00310		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,350 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/40 R20 101V	Summer tires (with run-flat tires) on Light alloy	Continental	5mm / 5mm
2)	255/40 R20 101V	Summer tires (with run-flat tires) on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm
2)	215/65 R17 99H	Winter tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger including knee airbag on the driver's side
- 30-color ambient lighting
- Adaptive Cruise Control (ACC) (DSG)
- Electrically adjustable and heated exterior mirrors
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles
- Display: Digital Cockpit Pro, multicolor, various selectable info profiles
- Parking assistance
- Electronic stability program and electromechanical brake booster
- Automatic headlight control, with LED daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Rear window heated
- Rear spoiler in R-style
- ISOFIX mounting points, also for i-Size child car seats
- Air conditioning system "Air Care Climatronic"
- Rear headrests (3)
- Front headrests
- Charging cable: Mains charging cable for household socket
- Steering wheel: Multifunction sports steering wheel in leather, heated, with touch controls and paddle shifters
- Fatigue detection
- Non-smoking version
- Otto particulate filter
- Upholstery: Cloth
- Radio accessories: 8 speakers
- Tire pressure monitoring system
- Gearshift knob in leather
- electromechanical power steering
- Seats: Front passenger seat backrest folds down completely
- Seats: Rear bench seat asymmetrically split
- Seats: Front seats with height adjustment
- 12-volt socket
- Bumpers in body color, in "R-Line" styling
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Navigation function "Discover Media" incl. "Streaming & Internet"
- Central locking without safe locking, with remote control and 2 remote keys
- Airbag: Head airbag system for front and rear passengers including front side airbags
- App-Connect including App-Connect Wireless for Apple CarPlay and Android Auto
- third brake light
- black roof rails
- Decorative inlays "Carbon Grey"
- Tachometer
- e-Sound
- Electronic parking brake including auto-hold function
- Driving assistant "Travel Assist" and lane keeping assistant "Lane Assist"
- Electric windows front and rear
- High beam control Light Assist
- Pedestrian detection
- Transmission: 6-speed DSG
- rear window wiper
- Interior mirror automatically dimming
- LED license plate lighting
- Combination instrument cluster with electronic speedometer
- Mode 3 Type 2 charging cable, 16 A
- LED reading lights, 2 in the front and 2 in the rear
- LED headlights with LED daytime running lights
- Light in the front footwell
- Front center armrest adjustable in height and length, with storage box and rear air vents
- Emergency call service
- Pedals and footrest in brushed stainless steel
- Radio
- Rain sensor
- Wheels: Tire Mobility Set omitted
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Lumbar support in the front
- Seats: Top comfort seats in the front
- Start-stop system with brake energy recuperation
- Power outlet: 2 USB-C ports on the front
- Textile floor mats front and rear with decorative stitching in grey
- Electronic immobilizer
- Green thermal insulation glazing, sides and rear



Extra equipment

- Trailer maneuvering assistant "Trailer Assist" including parking assist "Park Assist" and parking aid
- Anti-theft alarm system with safe locking (anti-theft alarm system with interior monitoring, backup horn and tow-away protection, central locking with safe locking, remote control and 2 remote folding keys)
- Paint finish: Metallic
- Navigation system "Discover Pro" incl. "Streaming & Internet" (App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Digital radio reception DAB+ - 23.4 cm TFT touchscreen with gesture control - FM radio and diversity antenna - RDS - MP3 playback - 2 USB-C ports - 4 x 20 watts of power - Map with 2D display - "Comfort" phone interface connectable via Bluetooth - Wireless charging - Traffic sign recognition - Voice control - Points of interest - We Connect Plus incl. We Connect free for 3 years)
- Package: Exterior Design Package "Black Style" (4 "Valencia" 8.5 J x 19 alloy wheels in black, Airstop tires 255/45 R 19, optimized for rolling resistance - black exterior mirror housings - tinted rear side windows and rear window, approximately 90% light-absorbing - bumpers in body color, in "R-Line" styling, with design elements in black - black trim strips)
- Panoramic tilt/slide sunroof with panoramic roof at the rear
- Progressive steering
- Rear View reversing camera
- Foldable towbar (electric release)
- Electrically adjustable, folding, and heated exterior mirrors, ambient lighting, passenger-side mirror lowering function
- Display: Head-up display
- Chassis: Adaptive chassis control DCC (including driving profile selection)
- LED matrix headlights - IQ.LIGHT (Dynamic Light Assist high beam control for LED matrix headlights - LED headlights with LED daytime running lights and cornering lights - LED taillights, dark red)
- Mesh partition
- Package: "Easy Open & Close" with safe locking mechanism ("Easy Open & Close" - tailgate with sensor-controlled opening and closing, with remote unlocking - keyless locking and starting system "Keyless Access" with safe locking mechanism)
- Package: Business Premium (DSG) (App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Leather multifunction steering wheel, heated, with shift paddles - Automatically heated front windscreen washer nozzles - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Package: Winter, additionally with heated outer rear seats (windscreen washer nozzles automatically heated - front seats and outer rear seats heated)
- Wheels: Alloy (4) "Suzuka" 8.5 J x 20, Volkswagen R (in black - AirStop tires 255/40 R 20 - wheel locks with enhanced theft protection)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Sill (Seitenwand Kniestück) - Dent / paintcoat damage - Smart repair
2	Wing mirror - right side	Cap - Scratched - Replace
3	Rear bumper	Rear bumper - Scratch(es) - Paint
4	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
5	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
6	Boot lid / rear door	Boot lid (& Lackschaden) - Dent / paintcoat damage - Repair and paint
7	Wheel / tyres	Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Wear and tear

No.	Component group	Description
1	Door - rear left side	Door edge - Scratch(es) - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction
3	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction
4	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction
5	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction
6	2nd wheel set	1 tyre (Nicht Bestandteil der Ausstattung) - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - charging cable (Schuko Stecker / Haushaltssteckdose)

Accident damages

No. Accident

1 Front

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.




Figure 38: Misc.



Damage 1: Side panel - rear left side: Sill (Seitenwand Kniestück) - Dent / paintcoat damage - Smart repair



Damage 1: Side panel - rear left side: Sill (Seitenwand Kniestück) - Dent / paintcoat damage - Smart repair



Damage 1: Side panel - rear left side: Sill (Seitenwand Kniestück) - Dent / paintcoat damage - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratched - Replace



Damage 2: Wing mirror - right side: Cap - Scratched - Replace



Damage 2: Wing mirror - right side: Cap - Scratched - Replace




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 3: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 4: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 5: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Boot lid (& Lackschaden) - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Boot lid (& Lackschaden) - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Boot lid (& Lackschaden) - Dent / paintcoat damage - Repair and paint



Damage 6: Boot lid / rear door: Boot lid (& Lackschaden) - Dent / paintcoat damage - Repair and paint



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace




Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side (+ beide Felgen an der Hinterachse) - Scratch(es) - Replace



Wear and tear 1: Door - rear left side: Door edge - Scratch(es) - No deduction




Wear and tear 1: Door - rear left side: Door edge - Scratch(es) - No deduction



Wear and tear 1: Door - rear left side: Door edge - Scratch(es) - No deduction




Wear and tear 2: Door - front left side: Door edge - Scratch(es) - No deduction



Wear and tear 2: Door - front left side: Door edge - Scratch(es) - No deduction



Wear and tear 2: Door - front left side: Door edge - Scratch(es) - No deduction




Missing part 1: Equipment: charging cable (Schuko Stecker / Haushaltssteckdose) - Missing - Replace



Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVGZZZ5N3PW407612

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Tiguan 1.4 eHybrid OPF DSG R-Line

Datum	KM-Stand	Beschreibung
14.04.2026	61.520	Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
10.07.2025	46.498	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
14.08.2024	29.753	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
29.09.2023	14.639	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges