



Expertise

Protocol number: 47165802
Order No. / Reference: 26803673
Inspection date: 19 Aug 2026

Manufacturer: Nissan

Model: Leaf 40 kWh N-Connecta

VIN: SJNFAAZE1U0134167



Vehicle details	
Manufacturer / Type / Model / Equipment	
Nissan Leaf 40 kWh N-Connecta	
Vehicle Identification number	SJNFAAZE1U0134167
Mileage (Read)	23,622 km
First registration	12 Aug 2021
Number of holders	1
Fuel type	Electric
Power	90 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	White University
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details

Maintenance booklet / proof	Non-existent	Next maintenance in	
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FX889144
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2228 / AAJ 00001		
Emission standard	2017/1151	fine dust sticker	
Permitted total weight	1,995 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R17 95W	All-season tyres on Light alloy	Kleber	4mm / 4mm
2)	215/50 R17 95W	All-season tyres on Light alloy	Kleber	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver and passenger side
- Airbag: Front side airbags
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD) and NISSAN brake assist
- Exterior mirrors with automatic folding function
- Hill Start Assist
- Electronic Stability Program (ESP)
- High Beam Assist
- Transmission: Automatic, continuously variable
- shark antenna
- Interior mirror, automatically dimming
- Intelligent AROUND VIEW MONITOR (for 360° all-round view with front and rear parking sensors - 4 cameras (front, rear and exterior mirrors) create a 360° bird's-eye view which is displayed on the screen in the cockpit, thus enabling safe and precise parking - incl. intelligent motion and fatigue detection)
- Headrests (5) front and rear (height adjustable in all seats)
- Front charging port Type 2, AC (up to 6.6 kW)
- Charging cable: EVSE cable (Mode 2 safety system) with household plug (up to 2.3 kW)
- Leather steering wheel
- Steering wheel: Remote control on the steering wheel (for: - Audio system - On-board computer - Speed limiter and speed control system)
- NISSAN Connect EV navigation system (multimedia system with - 8" color touchscreen display - navigation voice control including RDS-TMC messages - DAB digital radio with MP3 playback - Bluetooth audio streaming - hands-free system - voice control - iPod gateway - 1 front USB port, 2 rear USB ports, AUX interface - 6 speakers - EV telematics system - route planning, range display, eco-ranking, energy information, driver analysis - NissanConnect EV app for controlling, among other things, the air conditioning and charging process)
- Wheels: Light alloy (4) 6.5J x 17" (with tires 215/50 R 17")
- LED taillights
- Windows tinted from the B-pillar back
- electric power steering
- Seats: Driver and passenger seats manually adjustable
- Seats: Driver's seat height adjustable
- 12-volt socket, front
- Blind spot assist, active
- Glazing: Laminated glass windshield
- Traffic sign recognition
- Central locking including remote control (intelligent key with start/stop button and charging port lock)
- Airbag: Front and rear head airbags
- Acoustic Vehicle Alerting System (AVAS)
- Electrically adjustable exterior mirrors in car color (with integrated turn signal)
- Outdoor temperature display
- third brake light
- Electric windows front and rear
- Cruise control system and speed limiter
- Cup holders (front, rear and center console)
- Heated rear window
- Intelligent Adaptive Speed and Distance Assist
- Intelligent Autonomous Emergency Braking Assistant (with pedestrian detection)
- Intelligent lane keeping assist active (with corrective braking intervention)
- Automatic climate control (with pollen filter)
- Removable boot cover (with lighting)
- Paint finish: Solid
- Charging port: Fast charging port at the front (CHAdeMO), direct current up to 50 kW (Vehicle2Grid Ready)
- Charging cable: Mode 3 charging cable Type 2/Type 2 (up to 7.4kW)
- Steering column adjustable in height and depth
- Headlight range control
- Light and rain sensor
- Fog light
- Electric parking brake
- Upholstery: Cloth
- ProPILOT (with intelligent autonomous: - Traffic jam assist with stop & go function - Steering assist for independent lane keeping - Speed and distance assist)
- Cross-traffic alert
- Radio accessories: Apple CarPlay and Android Auto
- Radio accessories: Roof antenna
- Tire pressure monitoring system (TPMS)
- Color reversing camera
- Rear seat backrest foldable asymmetrically (60:40)
- Windscreen wipers with intermittent function front and rear
- Seat belts: Three-point seat belts (belt tensioners and belt force limiters for front seat belts)
- Seats: ISOFIX child seat attachment (on the outer rear seats)
- Chrome-look door handles
- Glazing: UV-absorbing windshield
- Electronic immobilizer

Extra equipment

- All-season tyres



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Misc.	Main inspection - No evidence - No deduction
3	Equipment	Tirefit filler - Expired - Replace
4	Roof	Roof - dent(s) - Smart repair
5	Trim / covers	Door trim - front left side - Scratch(es) - Loss in value
6	Sill - left side	Sill - Scratch(es) - Smart repair
7	Side panel - rear right side	Side panel - dent(s) - Smart repair
8	Rear bumper	Rear bumper - Scratch(es) - Smart repair
9	Front bumper	Front bumper - Scratch(es) - Smart repair
10	Door - rear right side	Door - Scratch(es) - Smart repair
11	Roof	Roof rail - right side - Scratch(es) - Smart repair
12	Wheel / tyres	Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace
13	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Loss in value
14	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
15	Rear axle	Rear axle (wegen der beschädigten Felge) - Specify findings - Measure
16	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Tyre - front (Über 4mm) - No deduction
2	Fog lamp	Fog lamp - front left side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Fahrzeug ist lt. Rechnung ein: CONNECTA

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Damage 3: Equipment: Tirefit filler - Expired - Replace



Damage 4: Roof: Roof - dent(s) - Smart repair



Damage 4: Roof: Roof - dent(s) - Smart repair



Damage 5: Trim / covers: Door trim - front left side - Scratch(es) - Loss in value



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 6: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 7: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 9: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 9: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 10: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 10: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 11: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 11: Roof: Roof rail - right side - Scratch(es) - Smart repair



Damage 12: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace



Damage 12: Wheel / tyres: Tyre - rear right side (nicht fahrbereit) - Broken / torn - Replace




Damage 13: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 13: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Loss in value



Damage 14: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 14: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 16: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Damage 16: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Replace



Wear and tear 2: Fog lamp: Fog lamp - front left side - Scratch(es) - No deduction



Wear and tear 2: Fog lamp: Fog lamp - front left side - Scratch(es) - No deduction