

INSPECTION REPORT





End of contract

GENERAL INFO

File	315735
License plate	2DSE985
Vehicle identification number	WF0FXXWPMHPD81627
Dossier	2022 217 068
Make	Ford Kuga 2.5i EB 165kW ST-Lin
Mileage	40458
First registration	09/06/2023
client availability date	18/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	



DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
38	Front Bonnet / Insulation / Replace	N
63	Wing Front Left // Painting	N
84	Door Front Left // Repair & Painting	N
103	Door Rear Left // Painting	N
124	Light / Rear left / Replace	N
135	Bumper Rear // Replace & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	N
216	Door Front Right // Polish	Y
217	Door Front Right / Trim / Replace	Y
222	Side View Mirror Right // Painting	Y
230	Wing Front right // Smart Repair Small	N
244	Light / Front Right / Replace	N
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N

Damage Pictures



Light / Rear left / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Wing Front Left // Painting-scratch



Light / Front Right / Replace-scratch





Bumper Front // Painting-scratch




Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Polish-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Painting-scratch



Door Rear Left // Painting-scratch



Wing Front right // Smart Repair Small-dent




Door Front Left // Repair & Painting-scratch + dent



Front Bonnet / Insulation / Replace-cracked



Bumper Rear // Replace & Painting-cracked



Interior // Repair 1-Incinerated