



Expertise

Protocol number: 46202509
Order No. / Reference: 26539874
Inspection date: 19 Jun 2026

Manufacturer: CUPRA

Model: Born 150kW/58kWh

VIN: VSSZZK19RP018443



Vehicle details	
Manufacturer / Type / Model / Equipment	
CUPRA Born 150kW/58kWh	
Vehicle Identification number	VSSZZK19RP018443
Mileage (Read)	22,402 km
First registration	21 May 2024
Number of holders	1
Next periodical technical inspection	05/2027
(Report not on hand)	
Power / Engine displacement	70 kw / 0 ccm
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Vapor Grey
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	658 Tag(e)
Last service on / at	04/2026 at 21,773		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY930857
Previous damage / Accident	None detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	7593 / ASO 00024		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,280 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/55 R18 95T	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • Airbag: Airbag for driver and front passenger • Airbag: Head airbag system, front and rear • Exterior mirrors: aspherical on driver's side, convex on passenger's side • third brake light • CCS charging socket • CUPRA e-Sound • CUPRA side skirts in Liquid Grey • decorative elements • Electronic Stability Control (ESC) • Luggage compartment lighting • Speed limiter • rear window wiper • Rear bumper and diffuser in body color • High-voltage battery warranty 8 years or maximum 160,000 km, with 70% Abattery power • Keyless Go (engine start/stop button) • Air conditioning: Climatronic with electronic temperature control • Paint finish: Solid • Steering wheel: CUPRA Supersport multifunction steering wheel in leather • Center console with integrated storage compartment and cup holders • Progressive steering • Rain sensor • Wheels: CYCLONE 7.5J x 18" alloy wheels • Seat belts - front and rear • Seats: CUPRA sports bucket seats in the front • Seats: Driver's seat with height adjustment • Sport pedals in aluminum look • 12V socket in the luggage compartment • Ultrasonic parking aid front and rear • Electronic immobilizer • thermal insulation glazing | <ul style="list-style-type: none"> • Airbag: Passenger airbag deactivation • Ambient lighting in the front door panel • Electrically adjustable, folding and heated exterior mirrors • Exterior mirror housing in Liquid Grey • C-pillar with CUPRA design element • CUPRA Drive Profile • CUPRA lettering on tailgate • Black headliner • Electronic parking brake including auto-hold function • Electric windows front and rear, with anti-pinch protection and one-touch function • Transmission: 1-speed automatic • Rear spoiler in car color • Manufacturer's warranty: 5 years or up to 150,000 km • Interior mirror automatically dimming • ISOFIX child seat restraint system, in the 2nd row of seats left and right as well as on the front passenger seat • Headrests, 2 front • Headrests, 3 rear • Mode 3 Type 2 charging cable, 16 A • Lights: Full headlights • front center armrest • Fatigue detection • Emergency call service • Radio: Radio and multimedia systems • Tire pressure monitoring system • Windscreen wiper interval control • Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable • Sun visors with illuminated makeup mirror • Lane departure warning system • Front bumper in body color • Front Assist area monitoring system with City Emergency Braking function |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyre - front left side - Porous / cracked - Replace
2	Wheel / tyres	Tyre - front right side - Porous / cracked - Replace
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Door - rear right side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Roof	Roof rail - left side - Scratch(es) - No deduction
2	Roof	Roof rail - right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No. Repainting

1	Mudguard - left side, Door - rear left side, Door - front left side, Professionally carried out, Invoice of repair done Non-existent
---	--

Paint coat thickness measurement

Mudguard - left side	175 µm	Door - rear left side	201 µm
Door - front left side	162 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Damage 1: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace



Damage 1: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace



Damage 1: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace



Damage 2: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 2: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 2: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 4: Door - rear right side: Door - Scratch(es) - Paint



Damage 4: Door - rear right side: Door - Scratch(es) - Paint



Wear and tear 2: Roof: Roof rail - right side - Scratch(es) - No deduction




Wear and tear 2: Roof: Roof rail - right side - Scratch(es) - No deduction



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZK19RP018443
Hersteller / Modell: SEAT SEAT Born 150kW/58kWh

Datum	KM-Stand	Beschreibung
09.04.2026	21.773	Bremsflüssigkeit; Bremsflüssigkeit ern; Regelwartungsdienst