



Expertise

Protocol number: 46605981
Order No. / Reference: 26701943
Inspection date: 20 Jul 2026

Manufacturer: Volkswagen
VIN: WVGZZCD1PW513507

Model: Golf Variant 2.0 TDI SCR DSG Style



Vehicle details	
Manufacturer / Type / Model / Equipment	
Volkswagen Golf Variant 2.0 TDI SCR DSG Style	
Vehicle Identification number	WVGZZCD1PW513507
Mileage (Read)	135,471 km
First registration	19 Oct 2022
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Deep Black Perleffekt
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Black-Dark grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	14,800 km
Last service on / at	11/2025 at 125,285 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM785263
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0603 / CNN 01419		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,060 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91W	Summer tyres on Light alloy	Continental	7mm / 7mm
2)	225/45 R17 91W	Summer tyres on Light alloy	Nexen	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Dunlop	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger
- 30-color ambient lighting
- App-Connect
- Electrically adjustable and heated exterior mirrors with memory function and passenger-side mirror lowering function.
- Chrome strip at the bottom of the side windows
- Decorative inlays "New Brushed Dark Metal"
- Digital Cockpit Pro, multicolor
- Electronic differential lock XDS
- Electronic stability program and electromechanical brake booster
- Automatic headlight control, with LED daytime running lights
- Pedestrian protection measures expanded
- luggage compartment cover
- Rear window heated
- Rear spoiler in car color
- Air conditioning system "Air Care Climatronic"
- Front headrests
- LED Plus headlights
- Illuminated strip between headlights and door handle recesses
- Front center armrest adjustable in height and length
- Non-smoking version
- Emergency call service
- Radio "Composition"
- Wheels: Alloy wheels (4) "Nottingham" 7.5 J x 17
- Rear bench seat undivided, backrest asymmetrically split and foldable with center armrest
- Seat belts: Three-point automatic seat belt for the middle rear seat
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Start-stop system
- Bumpers in body color
- Textile floor mats front and rear
- Electronic immobilizer
- 2 USB charging ports on the rear of the center console
- Airbags: Front and rear head airbags, front side airbags, center airbag
- Adaptive Cruise Control (ACC) "stop & go"
- Exterior mirror housings and door handles in body color
- third brake light
- Car2X
- black roof rails
- Diesel particulate filter and SCR catalyst
- Parking assistance
- Electronic parking brake including auto-hold function
- Driving assistant "Travel Assist" and lane keeping assistant "Lane Assist"
- Electric windows, front and rear
- Windscreen made of laminated safety glass, heat and sound insulating
- Transmission: 7-speed DSG
- Rear window wiper with intermittent function
- ISOFIX mounting points
- Rear headrests (3)
- LED reading lights at the front (2) and 2 at the rear
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Fatigue detection
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set
- Keyless start system without safe locking
- electromechanical power steering
- Seat belts: Three-point automatic seat belts for the outer rear seats
- Seats: ergoActive seat with 14-way adjustment and memory function on the driver's side
- 12-volt power outlet in the luggage compartment
- Telephone interface with inductive charging function
- Ambient lighting with logo projection
- Central locking without safe locking, with remote control and 2 remote folding keys



Extra equipment

- Package: Business Premium incl. navigation system (DSG) (6+1 speakers, App-Connect incl. App-Connect Wireless for Apple CarPlay, Android Auto, automatic distance control, adaptive cruise control (ACC) stop/go, speed limiter, emergency brake, pedestrian detection, travel assist, lane assist, emergency assist, leather multifunction steering wheel, heated, with shift paddles, multifunction camera, Discover Media navigation incl. streaming & internet (MP3, touchscreen, USB), cargo net partition, radio, heated windshield washer system, voice control, telephone interface, Comfort with inductive charging, textile floor mats, traffic sign recognition, heated front seats)
- Paint finish: Pearl effect
- Rear side windows and rear window tinted
- Rear View reversing camera
- Towbar, foldable with electric release

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door handle - outside - Scratch(es) - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
4	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
5	Door - rear left side	Door - Scratched - Smart repair
6	Door - rear right side	Door - Scratched - Smart repair
7	Sill - left side	Sill - Scratch(es) - Smart repair
8	Side panel - rear left side	Sill - Scratch(es) - Smart repair
9	Roof	Roof rail - right side - Stone chips - Smart repair
10	Side panel - rear right side	Sill - Scratch(es) - Smart repair
11	Side panel - rear left side	Side panel - Scratch(es) - Smart repair
12	Wheel / tyres	Tyre - rear right side - Porous / cracked - Replace
13	Boot lid / rear door	Boot lid - Scratch(es) - Paint
14	Boot lid / rear door	Boot lid - Scratch(es) - Paint
15	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Replace
16	Door - front left side	Door - Scratch(es) - Paint
17	Rear bumper	Rear bumper - Scratch(es) - Paint
18	Roof	Roof rail - left side - Scratch(es) - Paint
19	Bonnet	Bonnet - Scratch(es) - Paint
20	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Paint
21	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
22	Roof	Roof - Scratch(es) - Paint



Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lining - Scratched - No deduction
2	Engine	Engine cowling lower front - Scratched - No deduction
3	Engine	Engine cowling - lower - Scratched - No deduction
4	Door - front right side	Brightware - upper - Scratch(es) - No deduction
5	Trim / covers	Boot lid - interior trim - Scratched - No deduction
6	Body	Wheel well - front left side (Radhausschale unterhalb) - Scratched - No deduction
7	Body	Wheel well - front right side (Radhausschale unterhalb) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Die Beiliegenden Räder sind kein Teil der Ausstattung.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.





Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Door - rear right side: Door handle - outside - Scratch(es) - Smart repair



Damage 1: Door - rear right side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 4: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise




Damage 4: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 5: Door - rear left side: Door - Scratched - Smart repair




Damage 5: Door - rear left side: Door - Scratched - Smart repair




Damage 5: Door - rear left side: Door - Scratched - Smart repair



Damage 5: Door - rear left side: Door - Scratched - Smart repair



Damage 6: Door - rear right side: Door - Scratched - Smart repair




Damage 6: Door - rear right side: Door - Scratched - Smart repair




Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 7: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 8: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 8: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 9: Roof: Roof rail - right side - Stone chips - Smart repair




Damage 9: Roof: Roof rail - right side - Stone chips - Smart repair



Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 10: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 11: Side panel - rear left side: Side panel - Scratch(es) - Smart repair



Damage 11: Side panel - rear left side: Side panel - Scratch(es) - Smart repair




Damage 12: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 12: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 12: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 12: Wheel / tyres: Tyre - rear right side - Porous / cracked - Replace



Damage 13: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 13: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 14: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 14: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 14: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace




Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 15: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 16: Door - front left side: Door - Scratch(es) - Paint



Damage 16: Door - front left side: Door - Scratch(es) - Paint



Damage 16: Door - front left side: Door - Scratch(es) - Paint



Damage 16: Door - front left side: Door - Scratch(es) - Paint




Damage 16: Door - front left side: Door - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 17: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 18: Roof: Roof rail - left side - Scratch(es) - Paint




Damage 18: Roof: Roof rail - left side - Scratch(es) - Paint




Damage 18: Roof: Roof rail - left side - Scratch(es) - Paint




Damage 18: Roof: Roof rail - left side - Scratch(es) - Paint



Damage 19: Bonnet: Bonnet - Scratch(es) - Paint



Damage 19: Bonnet: Bonnet - Scratch(es) - Paint



Damage 19: Bonnet: Bonnet - Scratch(es) - Paint




Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 20: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 21: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 21: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 21: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 21: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 22: Roof: Roof - Scratch(es) - Paint



Damage 22: Roof: Roof - Scratch(es) - Paint



Wear and tear 4: Door - front right side: Brightware - upper - Scratch(es)
- No deduction



Wear and tear 4: Door - front right side: Brightware - upper - Scratch(es)
- No deduction



Wear and tear 5: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 5: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 5: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 6: Body: Wheel well - front left side (Radhausschale unterhalb) - Scratched - No deduction



Wear and tear 6: Body: Wheel well - front left side (Radhausschale unterhalb) - Scratched - No deduction



Wear and tear 6: Body: Wheel well - front left side (Radhausschale unterhalb) - Scratched - No deduction



Wear and tear 7: Body: Wheel well - front right side (Radhausschale unterhalb) - Scratched - No deduction



Wear and tear 7: Body: Wheel well - front right side (Radhausschale unterhalb) - Scratched - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WVVZZZCD1PW513507

Hersteller / Modell: VOLKSWAGEN VOLKSWAGEN Golf Variant 2.0 TDI SCR DSG
Style

Datum	KM-Stand	Beschreibung
28.11.2025	125.285	AU; Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben hinten; Bremsscheiben vorne; Getriebeöl ern/prüfen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
10.12.2024	97.241	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
25.04.2024	63.066	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.07.2023	29.442	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges