



Expertise

Protocol number: 46547785
Order No. / Reference: 26681461
Inspection date: 16 Jul 2026

Manufacturer: Ford

Model: Explorer EcoBoost Plug-in Hybrid PLATINUM

VIN: WF02K8HY3MNA15256



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Explorer EcoBoost Plug-in Hybrid PLATINUM	
Vehicle Identification number	WF02K8HY3MNA15256
Mileage (Read)	87,360 km
First registration	23 Sept 2021
Number of holders	1
Power / Engine displacement	267 kw / 2,956 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 6
Gearbox / Number of gears	Automatic / 10
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Carbonized-Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Brown



Vehicle details			
Maintenance booklet / proof	Non-existent	Next maintenance in	6 %
Last service on / at	07/2024 at 66,548 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GD579198
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BTR 00008		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	3,160 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/55 R20 110Y	All-season tyres on Light alloy	Hankook	5mm / 5mm
2)	255/55 R20 110Y	All-season tyres on Light alloy	Hankook	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	165/70 R18 116M	Summer tyres on Steel	Sonstige	2 mm
Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.				



Equipment



Standard equipment

- 360-degree camera with "Split View" technology
- All-wheel drive
- Towbar preparation kit
- Dashboard with design elements in carbon look
- Exhaust system with four tailpipes made of polished stainless steel
- Exterior mirrors, electrically adjustable, heated, folding
- Tires: Spare wheel
- Hill start assist
- Overhead console with glasses storage compartment
- Theft alarm system
- Front door sill trim
- EV mode (EV Auto, EV Later, EV Now, EV Charge)
- Lane keeping assist including lane keeping assist and driver fatigue warning
- Electric parking brake with auto hold function
- Ford Intelligent Drive Assist, semi-automated driving assistance
- Heated windshield
- Transmission: 10-speed automatic
- Tailgate with satin chrome trim
- Heated rear window
- Rear spoiler painted in car color
- Interior mirror, automatically dimming
- Intelligent Protection System (IPS)
- Map reading light at the front and reading lights in the 2nd and 3rd rows of seats
- Front headrests (2)
- Charging cables: 2 charging cables for charging the high-voltage battery
- LED headlights with high beam assist and LED daytime running lights
- Steering column, electrically adjustable in height and reach
- Front center console with padded armrest, storage compartment and 2 cup holders
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Parking Assist (Active Park Assist)
- Post-Collision Assist
- Radio accessories: B&O Sound System
- Windscreen wipers with rain sensor and defrost function
- Lettering
- Side skirts in black with contrasting inserts in satin chrome
- Power steering
- Seats: 3rd row of seats electrically extendable and retractable
- Sunshades for the 2nd row of seats
- Power outlet: 12-volt connection in the first row of seats and in the luggage compartment
- Leather-covered door inserts
- Door handles in body color with satin chrome accents
- Lashing eyes in the luggage compartment
- Central locking with remote control
- Active noise cancellation
- Ambient lighting
- Anti-lock braking system (ABS)
- Leather-covered dashboard
- Evasive Steering Assist (ESA)
- Exterior mirrors in contrasting glossy black
- Tires: 8 J x 20 alloy wheels (4) in 10-spoke design, glossy
- Hill descent control
- third brake light
- Roof rails
- 12.3-inch digital instrument panel
- Electronic Stability Program (ESP)
- Driving mode switch selective
- Chassis: Sport-tuned chassis
- Electric windows front and rear
- Ford Easy Fuel
- Ford KeyFree system
- FordPass Connect
- Luggage compartment cover
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- rear window wiper
- Inductive charging station for mobile devices
- Intelligent speed limiter with speed limit display
- ISOFIX anchor points on the outer seats of the 2nd and 3rd rows of seats
- Air conditioning with automatic temperature control
- Radiator grille
- LED taillights
- LED fog lights
- Steering wheel: Multifunction leather steering wheel, heated
- Make-up mirrors in driver and passenger sun visors
- MyKey key system
- Navigation system: Ford navigation system including Ford SYNC 3
- Panoramic sunroof, electric
- Upholstery: Leather
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: 2nd row - outer seats sliding "Easy Entry"
- Seats: Heated rear seats in the 2nd row
- Seats: Sports seats, climate-controlled and heated
- Start-stop system
- Power outlet: 230-volt connection
- Carpet floor mats front and rear with Brunello decorative stitching
- Variable radiator air intake
- Immobiliser



Extra equipment

- All-weather floor mats front and rear, tub shape
- Explorer luggage compartment retaining net Part no.: 2405904
- Paint finish: Concrete Grey Metallic
- Trailer hitch - removable
- All-season tires instead of standard summer tires
- Luggage compartment tray for the rear area
- Charging cable open. Charging station

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Spoiler - Scratch(es) - Smart repair
2	Front bumper	Spoiler - Scratched - Smart repair
3	Door - front left side	Door - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - front right side (Oxidiert) - Worn - Loss in value
5	Wheel / tyres	Alloy rim - rear right side (Oxidiert) - Worn - Loss in value
6	Wheel / tyres	Alloy rim - rear left side (Oxidiert) - Worn - Loss in value
7	Wheel / tyres	Alloy rim - front left side (Oxidiert) - Worn - Loss in value

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side right, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	232 µm	Side panel - rear right side	230 µm
Door - rear right side	257 µm	Door - front right side	173 µm



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Rear bumper: Spoiler - Scratch(es) - Smart repair



Damage 1: Rear bumper: Spoiler - Scratch(es) - Smart repair




Damage 2: Front bumper: Spoiler - Scratched - Smart repair



Damage 2: Front bumper: Spoiler - Scratched - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side (Oxidiert) - Worn - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side (Oxidiert) - Worn - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side (Oxidiert) - Worn - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear right side (Oxidiert) - Worn - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear left side (Oxidiert) - Worn - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear left side (Oxidiert) - Worn - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front left side (Oxidiert) - Worn - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front left side (Oxidiert) - Worn - Loss in value



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side




Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF02K8HY3MNA15256

Hersteller / Modell: FORD FORD Explorer EcoBoost Plug-in Hybrid PLATINUM

Datum	KM-Stand	Beschreibung
29.07.2024	66.548	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.09.2023	42.973	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
29.08.2022	21.000	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges