

Volkswagen e-Golf BEV 136pk E-dition Winter Multimedia, Jul-20, 73,294 km



Memo



VIN	WVWZZZAUZL8913543
Initial registration	23-07-2020
Initial Dutch Registration	23-07-2020
European Type Approval	e1*2007/46*0623*44
Mileage reading / hour counter reading	73,294 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	1515 kg
Doors	5
Power capacity	100 kW
Emission code / Energy label	Z
Wheelbase	263
Loading space	
Load capacity	
RDW details	
Battery capacity	35.8 kWh
Range	230 km
Battery health	
Charging cables type	2
AC/DC	AC
Battery purchase/rent	Unknown
Taxation	VAT (Yellow number plate)
Colour	Black
Country of registration	The Netherlands

Accessories fitted to vehicles

	Rear view camera		Central locking remote control		Metallic paint
	Adaptive cruise control		Cruise control		Navigation
	Adaptive power steering		Electronic Stability Program		Parking sensors rear
	ABS		Electric windows front		Parking sensors front + rear
	Automatic air conditioning ECC		Electric windows front + rear		Start immobiliser
	Automatic interior mirror dimmer		LED lighting		Heated front seats
	Bluetooth telephone connection		Alloy rims		

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|---|---|--|
| <ul style="list-style-type: none"> • Achteropk verkeer waarsch • AEB • Armsteun achter • Armsteun voor • Band.sp.contr.syst. • Bestuurdersairbag • Boordcomputer • Bots herkenning+activatie • Buitensp. elektr. + verw. • Comfortstoel(en) • Dakspoiler • Dimlichten aut. • EBD | <ul style="list-style-type: none"> • ESP • Forward Collision Warning • Hill hold functie • Hoofd airbag(s) a. • Hoofd airbag(s) v. • Hoofdsteunen actief • In delen neerkl. achterb. • Knie airbag(s) • LED dagrijverlichting • LED koplampen • Lederen stuurwiel • Lendesteunen (verstelb.) • Lichtmetalen velgen 16" | <ul style="list-style-type: none"> • Multifunctioneel stuur • Multimedia-voorbereiding • Oplaadmogelijkheid • Parkeersensor voor • Passagiersairbag • Sperdifferentieel • Stoel best. hoogte verst. • Stoel pass. hoogte verst. • Vermoeidheids herkenning • Verstelbaar stuur • Vervolgbotsing preventie • Zij airbag(s) v. |
|---|---|--|



Vehicle state

MOT due date	23-07-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	16"		
Wheel	Brand	Type	Tread depth
Front wheel left	Goodyear	Summer tyre	2 mm
Front wheel right	Goodyear	Summer tyre	2 mm
Rear wheel left	Goodyear	Summer tyre	5 mm
Rear wheel right	Goodyear	Summer tyre	5 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident	Component	Observations
Unacceptable damage		
1 	Rear door left	dent(s)
2 	Deurgreep buit v l	scratch(es)
3 	Front door left	scratch(es)
4 	Dorpel l	scratch(es)
5 	Engine bonnet	stone impact
6 	Front bumper	various damage (see photo)
7 	Rear wing right	scratch(es)
8 	Rear door right	scratch(es)
9 	C/d-stijl r bekleding binnen	scratch(es)
10 	Kofferklep bekleding	scratch(es)

11



Rear bumper

scratch(es)

12



Kofferklep

scratch(es)

13



Roof

Hail damage, circa 20