



Expertise

Protocol number: 46625516
Order No. / Reference: 26674320
Inspection date: 21 Jul 2026

Manufacturer: Ford

Model: Transit 350 L3H2 Lkw VA MH Trail

VIN: WF0FXXTTRFLT44519



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit 350 L3H2 Lkw VA MH Trail

Vehicle Identification number WF0FXXTTRFLT44519

Mileage (Read) 54,897 km

First registration 24 Jun 2021

Number of holders 1

Fuel type Hybrid Diesel / E

Engine displacement / Cylinder 1,995 ccm / 4

Power 96 kW

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle Van

Colour / colour code Polar Silber-Metallic

Doors / Seats 4 / 6

Upholstery type Artificial leather

Colour of upholstery Black

Vehicle with smoke odor Yes (not ozone-treated)



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	324 Tag(e)
Last service on / at	07/2025 at 45,529 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FZ451495
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BSU 00357		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	Winter tyres on Steel	Falken	5mm / 5mm
2)	235/65 R16 121R	Winter tyres on Steel	Falken	8mm / 8mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/65 R16 115R	Summer tyres on Light alloy	Continental	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Driver's side airbag
- Battery: Battery life, programming of battery life to 10 minutes
- roof, middle
- Tachometer
- Third brake light
- Windows: Sliding windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel
- Transmission: 6-speed transmission
- Interior lighting with delay function at the front
- Cargo area lighting
- Steering column, adjustable in height and reach
- Package: Rear seat package 2 (2nd row, 3-seater bench - removable - incl. height-adjustable headrests and 2 ISOFIX brackets)
- Wheels: Tire repair kit
- Headlights with delayed shut-off
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Mechanical limited-slip differential
- Start-stop system
- Rear bumper with integrated step
- Daytime running light
- Plastic partition wall with window (including protective grille)
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Second key with remote control
- Axle load increase
- Anti-lock braking system with electronic brake force distribution (EBD)
- On-board computer
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Front electric windows
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area floor: rubberized
- MyKey key system
- Particulate filter: diesel particulate filter
- Wheels: 6.5 J x 16 alloy wheels in a 10-spoke design (6.5 J x 16 with 235/65 R16 tires)
- Headlights with static cornering lights
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Seat package 18A (driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - double passenger seat with storage compartment under individually foldable seat cushions - height-adjustable headrests - integrated (fold-out) tray in the double passenger seat - interior armrest for driver - manual lumbar support (driver's seat) - seat cover: leather)
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment

Extra equipment

- Airbag (passenger side)
- Paint finish: Metallic
- Package: Visibility Package III (electrically adjustable, heated and folding exterior mirrors - Lane Keeping Assist with Driver Alert and High Beam Assist - Heated windscreen - High-mounted LED downlights - Adjustable instrument lighting - Fog lights - Front and rear parking sensors - Rearview camera with image transmission of the reversing path on the display - Windscreen wipers with rain sensor - Headlight assist with day/night sensor - Windscreen washer fluid level sensor)
- Power outlet: 12-volt connection in the cargo area (D-pillar)
- Blind Spot Assist including Cross Traffic Alert (electrically adjustable and heated exterior mirrors, also electrically foldable)
- All-weather floor mats in a custom fit
- Cargo area lighting, LED
- Radio: Audio System 21: Ford audio system with 8" multifunction display (Connected Radio (AM/FM) - Digital radio reception DAB/ DAB+ (Digital Audio Broadcasting) - FordPass Connect Wi-Fi hotspot (up to 4G/LTE, for up to 10 mobile devices) - 8" TFT multifunction display (20.32 cm screen diagonal) - Four speakers, antenna - Integrated control panel and audio remote control on the steering wheel - Bluetooth interface - USB port - Hands-free system - Android Auto and Apple CarPlay support - Emergency Call Assistant)
- Winter complete wheels, steel rims



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front right side	Door - dent(s) - Smart repair
3	Side panel - rear right side	Side panel - dent(s) - Smart repair
4	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
5	Sliding door, right	Sliding door with glass panel - dent(s) - Smart repair
6	Sliding door, right	Protection strip - Deformed - Replace
7	Interior	Interior - Odour - Ozone treatment
8	Boot lid / rear door	Hinge (rechts unten) - Malposition - Set / adjust
9	Vehicle glazing	Side window - rear left side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair
10	Vehicle glazing	Side window - rear right side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair
11	2nd wheel set	1 tyre - Broken / torn - Replace
12	Seat - front	Seat cover -2 seater - right side - Burn hole (cigarettes) - Smart repair
13	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
14	Rear bumper	Bumper - rear right side - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Protection strip - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Tirefit compressor

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Door - front right side: Door - dent(s) - Smart repair




Damage 2: Door - front right side: Door - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 3: Side panel - rear right side: Side panel - dent(s) - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 4: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 5: Sliding door, right: Sliding door with glass panel - dent(s) - Smart repair



Damage 5: Sliding door, right: Sliding door with glass panel - dent(s) - Smart repair



Damage 6: Sliding door, right: Protection strip - Deformed - Replace



Damage 6: Sliding door, right: Protection strip - Deformed - Replace



Damage 8: Boot lid / rear door: Hinge (rechts unten) - Malposition - Set / adjust



Damage 8: Boot lid / rear door: Hinge (rechts unten) - Malposition - Set / adjust



Damage 8: Boot lid / rear door: Hinge (rechts unten) - Malposition - Set / adjust




Damage 8: Boot lid / rear door: Hinge (rechts unten) - Malposition - Set / adjust



Damage 8: Boot lid / rear door: Hinge (rechts unten) - Malposition - Set / adjust



Damage 9: Vehicle glazing: Side window - rear left side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair



Damage 9: Vehicle glazing: Side window - rear left side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair




Damage 9: Vehicle glazing: Side window - rear left side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair




Damage 9: Vehicle glazing: Side window - rear left side (Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair



Damage 10: Vehicle glazing: Side window - rear right side
(Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair



Damage 10: Vehicle glazing: Side window - rear right side
(Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair



Damage 10: Vehicle glazing: Side window - rear right side
(Schiebefenster, Zusatzkosten können entstehen) - Loose - Repair



Damage 11: 2nd wheel set: 1 tyre - Broken / torn - Replace



Damage 11: 2nd wheel set: 1 tyre - Broken / torn - Replace




Damage 12: Seat - front: Seat cover -2 seater - right side - Burn hole
(cigarettes) - Smart repair



Damage 12: Seat - front: Seat cover -2 seater - right side - Burn hole (cigarettes) - Smart repair



Damage 12: Seat - front: Seat cover -2 seater - right side - Burn hole (cigarettes) - Smart repair




Damage 13: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 13: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 13: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 13: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 13: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 14: Rear bumper: Bumper - rear right side - Broken / torn - Replace



Damage 14: Rear bumper: Bumper - rear right side - Broken / torn - Replace



Missing part 1: Equipment: Tirefit compressor - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXTTTRFLT44519
Hersteller / Modell: FORD FORD Transit 350 L3 VA MH Trail

Datum	KM-Stand	Beschreibung
09.07.2025	45.529	Bremsflüssigkeit; Bremsflüssigkeit ern; HU + AU; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
18.06.2024	39.530	Batterie ern; Systemtest/Eigendiagnose
16.05.2024	38.156	Regelwartungsdienst
07.06.2023	29.378	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
01.08.2022	21.212	Ölwechsel