



Expertise

Protocol number: 46673298
Order No. / Reference: 26606617-1
Inspection date: 20 Jul 2026

Manufacturer: Opel

Model: Zafira Life 2.0 D L Aut. Tourer

VIN: VXEEVHZ7NZ069811



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Zafira Life 2.0 D L Aut. Tourer

Vehicle Identification number VXEEVHZ7NZ069811

Mileage (Read) 101,581 km

First registration 2 Jan 2023

Number of holders 1

Next periodical technical inspection 01/2028
(Report on hand)

Fuel type Diesel

Engine displacement / Cylinder 1,997 ccm / 4

Power 130 kW

Gearbox / Number of gears Automatic / 8

Type of drive Front drive

Type of vehicle Van

Colour / colour code Mondstein Grau Metallic

Doors / Seats 5 / 7

Upholstery type Leather

Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	Available / complete	Next maintenance in	23 Monat(e)
Last service on / at	06/2026 at 100,660 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ347581
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	3003 / BBA 00338		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,100 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	225/55 R17 101Y	Summer tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Goodyear	5mm / 4mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Continental	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Equipment

- Klimaanlage



Standard equipment

- Low beam automatically
- Airbag for driver and front passenger side - front passenger airbag can be deactivated
- Airbag: Head airbags, driver and front passenger
- Airbag: Curtain airbags, in the 2nd and 3rd rows of seats
- Anti-lock braking system (ABS) with cornering brake control (CBC) and brake assist
- Automatic activation of the hazard warning lights and unlocking of the doors after deployment of the airbag or seatbelt tensioner.
- On-board computer
- Headliner with 3 reading lights and ambient lighting including 6 air vents in the rear
- Electronic Stability Program (ESP Plus)
- Electric front windows with one-touch function
- Floor mats in all rows of seats
- Electric handbrake
- Glazed tailgate, with rear window wiper and heater
- Interior lighting - 1st row of seats: 3 LED lights - 2nd and 3rd row of seats: 2 LED lights - Seat belt fastening indicator
- Interior mirror, automatically dimming
- Air conditioning: Auxiliary air conditioning, rear
- Steering wheel: Multifunction leather steering wheel, flattened at the bottom
- Headlight range adjustment, manual
- Navigation system: Multimedia Navi Pro with 7" color touchscreen, voice control for audio, telephone, and navigation. Automatic music recognition for audio devices with USB connection. Bluetooth audio streaming. Hands-free calling via Bluetooth interface. Display of phonebook and call lists. Display of images via USB interface. Navigation system with integrated memory. European road map. 3D map display. Dynamic route guidance. TMC traffic information. Smartphone integration via Apple CarPlay and Android Auto. 1 USB interface. 8 speakers. Head-up display.
- Panoramic reversing camera 180° display of the area behind the vehicle up to 180 degrees, including steering guidelines, when reverse gear is engaged, on the color display of the infotainment system.
- Radio: Digital radio reception DAB+ Digital Audio Broadcasting
- Rain sensor
- Tire repair kit including tire sealant and 12-volt compressor (without jack)
- Sliding door trim with cover, in vehicle color
- Keyless locking and starting system Keyless Open & Start
- Side protection strips in vehicle color
- Seat belts: Three-point seat belts in all seats - Belt force limiter, front - Double belt tensioners, front - Warning tone and light for unfastened seat belts, front
- Heated seats for driver and front passenger
- Solar Protect heat-insulating glazing in the rear, extra dark tinted
- Sun visors for driver and passenger side including make-up mirrors
- Storage compartments - Storage compartment in the center console, front - Storage shelf above the windshield, closed - Storage compartment in the front doors, suitable for 1.5-liter beverage bottles - Closed, cooled and illuminated glove compartment - Closed glove compartment, bottom - Closed storage compartment on the dashboard, passenger side
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Diesel particulate filter
- Tachometer
- Window: Window, driver's side in the 2nd row of seats, fixed
- Transmission: 8-speed automatic transmission
- Head-Up Display projects, on request, speed, settings of the intelligent cruise control and limiter, traffic signs with speed limits and their cancellation, front collision warnings and navigation information into the driver's direct field of vision.
- Child safety lock, electric
- Automatic climate control: Dual-zone automatic climate control in the front, with particle and odor filter - Manual recirculation mode - Automatic air distribution - Sun sensor - Activated carbon filter
- Fog light
- Rear fog lights with reversing lights
- Package: Driver Assistance Package 1 - High Beam Assist - Driver Alert System - Solar Reflect Windscreen - Lane Keeping Assist - Traffic Sign Recognition with Intelligent Speed Control
- Package: Driver Assistance Package 2 - Semi-adaptive cruise control and speed limiter - Forward collision warning - Instrument cluster, 3.5" color driver information display - Emergency brake assist - Solar reflective windshield
- Park pilot, front and rear, with acoustic warning signal when parking forwards and backwards - blind spot warning
- Quickheat rapid heating system
- Radio accessories: Sound system for better audio quality: - 10 speakers - Amplifier and subwoofer under the driver's seat
- Tire pressure warning
- Wheels: Alloy wheels in bicolor, 7J x 17, tires 225/55 R17 101
- Side impact protection
- Power steering
- Safety steering column, height and length adjustable
- Seats: 6 leather seats, Claudia Schwarz - Comfort driver's seat: 6-way electrically adjustable, with lumbar support, armrest, massage function and seat heating - Comfort passenger seat: 4-way electrically adjustable, with lumbar support, armrest, massage function and seat heating - Two individual seats on rails in the 2nd row with armrests, swivel, foldable and removable and ISOFIX - Two individual seats on rails in the 3rd row with armrests, foldable and removable and ISOFIX - Height-adjustable headrests



- Sunshades in the 2nd row of seats
- 12-volt power outlet in the second row of seats
- 12V socket
- Traction Control (TC) Plus - Traction control with engine and brake intervention
- Exterior door handles, in chrome
- Illuminated door sill trim
- Xenon headlights with LED daytime running lights
- Ignition keys (2), both foldable - 3-button remote ignition key

- Power outlet: 220/230V, in the second row of seats under the passenger seat
- Door: Electric sliding door, driver and passenger side - with opening sensor, with sensor control
- Immobiliser
- Central locking with remote control

Extra equipment

- Luggage compartment cover
- Folding table on a rail system, movable between the 2nd and 3rd row of seats, removable
- Luggage compartment partition net vertically behind the last row of seats
- Paint finish: Metallic

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratched - Smart repair
2	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
3	Rear bumper	Rear bumper - Scratched - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - Scratched - No deduction
2	2nd wheel set	1 alloy rim - Scratched - No deduction
3	2nd wheel set	1 alloy rim - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Professionally repaired, Invoice of repair done	Non-existent

Repainting

No.	Repainting
1	Mudguard - right side, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done



Paint coat thickness measurement

Roof rail - left side	87 µm	Roof rail - right side	92 µm
Boot lid / rear door	99 µm	Mudguard - left side	94 µm
Mudguard - right side	169 µm	Bonnet	95 µm
Side panel - rear left side	90 µm	Side panel - rear right side	95 µm
Door - rear left side	93 µm	Door - rear right side	184 µm
Door - front left side	103 µm	Door - front right side	156 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Additional tyres




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Damage 1: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratched - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair




Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Wear and tear 1: Door - rear left side: Door - Scratched - No deduction



Wear and tear 1: Door - rear left side: Door - Scratched - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 2: 2nd wheel set: 1 alloy rim - Scratched - No deduction




Wear and tear 3: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 3: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Wear and tear 3: 2nd wheel set: 1 alloy rim - Scratched - No deduction



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Door - rear right side, Door - front right side



Mudguard - right side: 169 µm



Door - rear right side: 184 µm



Door - front right side: 156 µm