



Expertise

Protocol number: 46547477
Order No. / Reference: 26555063
Inspection date: 14 Jul 2026

Manufacturer: Opel

Model: Astra 1.2 Turbo Business Elegance

VIN: VXKFPHNSLP1016785



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Astra 1.2 Turbo Business Elegance

Vehicle Identification number VXKFPHNSLP1016785

Mileage (Read) 106,968 km

First registration 27 Mar 2023

Number of holders 1

Power / Engine displacement 96 kw / 1,199 ccm

Fuel type / Cylinder Petrol / 3

Gearbox / Number of gears Manual / 6

Type of drive Front drive

Type of vehicle Saloon car

Colour / colour code Arktisweiß

Doors / Seats 5 / 5

Upholstery type Cloth / leather combination

Colour of upholstery Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	19,200 km
Last service on / at	06/2026 at 106,251 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ382128
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / AET 00085		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,840 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94H	Winter tyres on Steel	Continental	4mm / 4mm
2)	205/55 R16 94H	Winter tyres on Steel	Uniroyal	8mm / 8mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94H	All-season tyres on Light alloy	Continental	4mm / 4mm
2)	205/55 R16 94H	All-season tyres on Light alloy	Continental	5mm / 5mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • Storage compartments • Airbag: Front airbags, driver and front passenger • Airbag: Front and rear outer head airbags • Automatic activation of the hazard warning lights • Exterior mirror housings in black • On-board computer • Tachometer • Electronic brake force distribution (EBD) • Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus) • Transmission: 6-speed manual transmission • rear window wiper • Cable set for trailer hitch • Dual-zone automatic climate control • Paintwork: Roof in car color • LED interior lighting • Steering wheel: Leather steering wheel, flat-bottomed, with steering wheel remote control • Center armrest, front and rear • Fog light • Electric parking brake • Tire pressure monitoring system • Rear seat backrest folds forward in a 60:40 split • Seat belts: Three-point seat belts in all seats • Heated seats, driver and passenger • Solar Protect thermal insulation glazing • 12V power outlet in the center console • Electronic immobilizer • Central locking with remote control | <ul style="list-style-type: none"> • Airbag: Chest-pelvis-side airbags, driver and front passenger • Anti-lock braking system (ABS) • Exterior mirrors, electrically adjustable, heated and folding • Hill Start Assist • third brake light • Eco Coaching: Upshift recommendation via display in the driver information display • Electric windows front and rear • Front collision warning system • Back window, heater • Interior rearview mirror, automatically dimming • Air conditioning: Intelli-Air air quality system "Clean Cabin" • Front headrests and 3 rear headrests, height adjustable • LED ambient lighting • LED headlights • Steering wheel heating • Illuminated makeup mirrors in both sun visors • Navigation system • Otto particulate filter • Tire repair kit • 180-degree reversing camera • Keyless locking and starting system Keyless Open & Start • Seats: Ergonomic active driver's seat, fabric/premium leatherette Isabella • Start/Stop System • Pre-wiring for ISOFIX child seat mounting system • Wireless Charging |
|--|---|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Paint finish: Solid | <ul style="list-style-type: none"> • Wheels: Alloy wheels 7 J x 16 (5 double spokes) in silver with all-weather tires (with all-weather tires 205/55 R 16) |
|---|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Vehicle glazing	Rear window - Glued / labelled - De-glue / neutralise
3	Rear bumper	Rear bumper - Scratched - Smart repair
4	Door - rear right side	Door (Mehrkosten möglich) - Scratched - Conditioning
5	Interior	Interior - Soiled - Clean
6	Trim / covers	Sill - front right side - Damaged - Replace
7	Bonnet	Insulation lining - Damage caused by marten / rodent - Replace
8	Body	Underbody panelling - Damaged - Replace
9	Braking system	Brake discs and brake pads - front (Tragbild mangelhaft,Rost) - Worn - Replace
10	Braking system	Brake discs and pads - rear (Tragbild mangelhaft,Rost) - Worn - Replace
11	Vehicle glazing	Windscreen - Broken / torn - Replace
12	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
13	Side panel - rear right side	Side panel (Rost) - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Brightware / decorative strip (Heckklappe) - Scratched - No deduction
2	Seat - front	Backrest cover - left side - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, not professionally repaired, Invoice of repair done Non-existent	

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 2: Vehicle glazing: Rear window - Glued / labelled - De-glue / neutralise



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratched - Smart repair



Damage 4: Door - rear right side: Door (Mehrkosten möglich) - Scratched - Conditioning



Damage 4: Door - rear right side: Door (Mehrkosten möglich) - Scratched - Conditioning



Damage 5: Interior: Interior - Soiled - Clean



Damage 5: Interior: Interior - Soiled - Clean



Damage 6: Trim / covers: Sill - front right side - Damaged - Replace




Damage 6: Trim / covers: Sill - front right side - Damaged - Replace



Damage 7: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace




Damage 7: Bonnet: Insulation lining - Damage caused by marten / rodent - Replace



Damage 8: Body: Underbody panelling - Damaged - Replace



Damage 8: Body: Underbody panelling - Damaged - Replace




Damage 9: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Worn - Replace



Damage 9: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Worn - Replace



Damage 10: Braking system: Brake discs and pads - rear (Tragbild mangelhaft, Rost) - Worn - Replace



Damage 10: Braking system: Brake discs and pads - rear (Tragbild mangelhaft, Rost) - Worn - Replace



Damage 11: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 11: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel (Rost) - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel (Rost) - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear right side: Side panel (Rost) - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel (Rost) - Dent / paintcoat damage - Repair and paint




Damage 13: Side panel - rear right side: Side panel (Rost) - Dent / paintcoat damage - Repair and paint



Missing part 1: Equipment: Vehicle key - Missing - Replace



Previous damage 1: Front



Previous damage 1: Front



Previous damage 1: Front



Previous damage 1: Front



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VVKFPHNSLP1016785

Hersteller / Modell: OPEL OPEL Astra 1.2 Turbo Business Elegance

Datum	KM-Stand	Beschreibung
05.06.2026	106.251	Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
24.09.2025	82.570	Bremsklötze hinten; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
11.03.2025	66.419	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
21.08.2024	45.786	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
29.11.2023	20.228	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges