



Expertise

Protocol number: 46508190
Order No. / Reference: 26727330
Inspection date: 13 Jul 2026

Manufacturer: Seat

Model: Ibiza 1.0 MPI S&S Reference

VIN: VSSZZKJZNR047587



Vehicle details	
Manufacturer / Type / Model / Equipment	
Seat Ibiza 1.0 MPI S&S Reference	
Vehicle Identification number	VSSZZKJZNR047587
Mileage (Read)	113,075 km
First registration	18 Jan 2022
Number of holders	1
Power / Engine displacement	59 kw / 999 ccm
Fuel type / Cylinder	Petrol / 3
Gearbox / Number of gears	Manual / 5
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Nevada Weiß Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	8,500 km
Last service on / at	09/2025 at 91,538 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG171063
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	7593 / ANY 00345		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,630 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	185/65 R15 88T	Summer tyres on Light alloy	7mm / 7mm
2)	185/65 R15 88T	Summer tyres on Light alloy	7mm / 7mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 08/2025	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the front doors
- Airbag: Driver and passenger side
- Airbag: Side airbag for driver and front passenger
- Exterior mirror housings in body color
- Hill Start Assist (HHC)
- On-board computer
- Tachometer
- Electric front windows (with anti-pinch protection and one-touch function)
- luggage compartment cover
- Transmission: 5-speed manual
- Heated rear window (with timer function)
- Heating and fresh air system with 4-stage fan and recirculation mode
- Galvanized body
- Child safety locks on the rear doors
- Headrests (5) front and rear height adjustable
- Steering wheel: Multifunction steering wheel
- Front reading light
- Multi-collision brake (automatic hazard warning lights during emergency braking)
- Upholstery: Cloth
- Radio: Media System 8.25" (Audio system with 8.25" color touchscreen - USB-C interface - Bluetooth interface with integrated hands-free system and audio streaming)
- Wheels: Tyre fit
- Rear seat backrest can be folded down completely as a single unit.
- Seats: Driver's seat with height adjustment
- Sun visor on passenger side
- Sun visor on driver's side with slot for parking disc
- Start-stop system
- Bumpers in body color
- Door handles in car color
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Passenger airbag deactivation
- Airbag: Head airbag system, front and rear
- Electrically adjustable exterior mirrors
- Outdoor temperature display
- Turn signals integrated into the exterior mirrors
- Third brake light (integrated into the rear spoiler)
- Electronic Stability Control (ESC) including Anti-lock Braking System (ABS) (with Electronic Brakeforce Distribution (EBD), Traction Control (ASR), Hydraulic Brake Assist (HBA) and Electronic Differential Lock (XDS))
- Cup holders, 2 front
- Rear window wiper/washer system (with intermittent function)
- ISOFIX child seat restraint system in the 2nd row, left and right (including Top Tether anchor points)
- trunk light
- LED technology for headlights and daytime running lights
- Steering column with height and reach adjustment
- light sensor
- Fatigue detection
- Emergency call service (no registration required, service is activated upon delivery)
- Radio accessories: Digital radio reception DAB+
- Wheels: Tire pressure monitoring system
- Wheels: Steel wheels 5.5 J x 15, wheel covers "Urban 20/1" (with tires 185/65 R 15)
- Power steering (electromechanical)
- Seat belts: Three-point automatic fastening front and rear (belt pretensioners on the front seats and rear side seats - warning tone for unfastened seat belt, front and rear)
- Lane departure warning system
- 12V socket at the front
- Rear drum brakes
- Front Assist area monitoring system with City Emergency Braking function and pedestrian detection
- Central locking with remote control and comfort closing

Extra equipment

- Air conditioning (including pollen filter)
- Package: Reference Plus Package (Ultrasonic parking aid, rear - Fog lights - Electric rear windows with anti-pinch protection and one-touch function - Rear seat backrest split 1/3 to 2/3, foldable)
- Wheels: Alloy wheels (4) 5.5 J x 15 "Enjoy 20/1" (With tires 185/65 R 15)
- Paint finish: Metallic
- Package: Winter (Heated front seats - Heated and electrically folding exterior mirrors - Height-adjustable passenger seat)
- Radio accessories: FullLink (Android Auto (Wired) - Apple CarPlay (including Full Link Wireless))



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Screen cleaning	Wiper arm - rear (Kappe fehlt) - Differs from the original configuration - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Wing mirror - left side	Mirror glass - Scratch(es) - Replace
4	Front bumper	Front bumper - Scratch(es) - Paint
5	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction
3	Rear bumper	Spoiler - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Damage 1: Screen cleaning: Wiper arm - rear (Kappe fehlt) - Differs from the original configuration - Replace



Damage 1: Screen cleaning: Wiper arm - rear (Kappe fehlt) - Differs from the original configuration - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Wing mirror - left side: Mirror glass - Scratch(es) - Replace



Damage 3: Wing mirror - left side: Mirror glass - Scratch(es) - Replace



Damage 4: Front bumper: Front bumper - Scratch(es) - Paint




Damage 4: Front bumper: Front bumper - Scratch(es) - Paint



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 5: Vehicle glazing: Windscreen - Broken / torn - Replace



Wear and tear 3: Rear bumper: Spoiler - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Spoiler - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VSSZZZKJZNR047587
Hersteller / Modell: SEAT SEAT Ibiza 1.0 MPI S&S Reference

Datum	KM-Stand	Beschreibung
29.12.2025	100.420	Systemtest/Eigendiagnose
02.09.2025	91.538	AU; Bremse Sonstiges; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.08.2024	64.209	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
10.03.2023	30.048	Motoröl b. Wartung; Regelwartungsdienst