



Expertise

Protocol number: 46431369
Order No. / Reference: 26412223
Inspection date: 9 Jul 2026

Manufacturer: Opel

Model: Combo Life 1.2 Turbo Start/Stop Edition

VIN: W0VERHNP2NJ754905



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Combo Life 1.2 Turbo Start/Stop Edition

Vehicle Identification number	W0VERHNP2NJ754905
Mileage (Read)	54,457 km
First registration	24 Nov 2022
Number of holders	1
Next periodical technical inspection	03/2028
(Report on hand)	

Power / Engine displacement	81 kw / 1,199 ccm
Fuel type / Cylinder	Petrol / 4
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Tiefquarz Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	-140 km
Last service on / at	11/2024 at 37,016 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN200054
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / AHI 00362		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,050 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 92H	All-season tyres on Steel rim with wheel cover	Goodyear	3mm / 3mm
2)	205/60 R16 92H	All-season tyres on Steel rim with wheel cover	Goodyear	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Low beam automatically
- Airbag system
- Exterior mirrors, electrically adjustable, heated and manually foldable
- On-board computer
- Tachometer
- Electric front windows
- Luggage compartment cover
- Intelligent speed control and limiter
- Glazed tailgate, with rear window wiper and heater
- Interior lighting, 1st and 2nd row of seats
- Instruments, 3.5" LCD driver information display
- Front headrests
- Steering wheel: Comfort steering wheel (PU), flattened at the bottom, with steering wheel remote control
- Otto particulate filter
- Radio: BT with 5-inch touchscreen
- Tire repair kit
- Wheels: Steel 6.5 J x 16 with tires 205/60 R16
- Side protection strips
- Power steering
- Safety steering column, height and length adjustable
- Seats: Comfort driver's seat
- Seats: Bench seat in the 2nd row with 3 seats
- Spoiler in black
- 12V power outlet in the center console, front
- Traction control (TC Plus)
- Traffic sign recognition
- Pre-wiring for ISOFIX child seat mounting system
- Heat-insulating glazing, tinted
- Ignition key (2)
- Storage compartments
- Anti-lock braking system (ABS)
- Exterior mirror housings in black
- Hill Start Assist
- Third brake light
- Electronic Stability Program (ESP Plus)
- Front collision warning system with automatic emergency braking and pedestrian detection
- Transmission: 6-speed manual transmission
- Heating and ventilation system, front, with particle and odor filter
- Child safety lock in the rear doors, manual
- Rear headrests (3 pieces)
- Fatigue detection
- Fog light
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Tire pressure monitoring system
- Sliding door on driver and passenger side
- Service interval indicator
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort passenger seat
- Seats: Rear seat backrest split 60:40, foldable
- Sun visors driver and passenger side,
- Lane Keeping Assist
- Daytime running light
- Exterior door handles, in car color
- Tie-down points 4 in the luggage compartment
- Immobiliser
- Central locking with remote control

Extra equipment

- All-weather tires
- Automatic climate control, two zones (front, with particle and odor filter - recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - visibility package)
- Package: Winter (Seat heating for driver and front passenger - Leather steering wheel, flattened at the bottom - Steering wheel heating - Windshield, partially heated)
- ParkPilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards)
- Custom-fit rubber mats
- Reversing camera: 180-degree panoramic reversing camera (display of the area behind the vehicle, including steering guidelines, when reverse gear is engaged in the color display of the infotainment system)
- Trailer hitch
- Paint finish: Metallic
- Navigation system: Multimedia Navi Pro with 8" color touchscreen, voice control for audio, telephone, and navigation (automatic music recognition for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, display of phonebook and call lists, up to 10 mobile phones can be paired, image display via USB port, navigation with integrated memory, road map of Europe (including Russia and Turkey), 3D map display, dynamic route guidance, Apple CarPlay and Android Auto, text message reading and dictation, USB interfaces, dual tuner, 6 speakers)
- Visibility equipment (rain sensor, interior rearview mirror, automatically dimming, high beam assistant, instruments, 3.5-inch color driver information display, 2 folding ignition keys)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - rear left side - Scratch(es) - Replace
2	Wheel / tyres	Wheel cover - rear right side - Scratch(es) - Replace
3	Wheel / tyres	Wheel cover - front right side - Scratched - Replace
4	Door - rear left side	Door handle - outside - Scratch(es) - Smart repair
5	Sill - left side	Sill - dent(s) - Smooth repair work
6	Body	B-pillar - left side - dent(s) - Smooth repair work
7	Mudguard - right side	Mudguard - right side - dent(s) - Smooth repair work
8	Front bumper	Spoiler - Scratch(es) - Smart repair
9	Trim / covers	A-pillar - trim - interior, left side - Holes - Replace
10	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - Replace
11	Cab	Door rubber seal - left side - Broken / torn - Replace
12	Misc.	Inspection / maintenance - Due - Perform
13	Interior	Rear shelf (Halter) - Broken / torn - Replace
14	Rear bumper	Rear bumper - Scratched - Paint
15	Seat - front	Backrest cover - left side - Broken / torn - Replace
16	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
17	Seat - front	Backrest cover - right side - Broken / torn - Replace
18	Sliding door, right	Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint
19	Side panel - rear right side	Side panel (Verkratzt) - Deformed - Repair and paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Interior	Cargo area floor (Laderaum) - Scratch(es) - No deduction
3	Door - front left side	Brightware - lower - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 30 Sept 2025	6.259,22 €



Repainting

No. Repainting

- 1 Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
- 2 Door - front right side, Professionally carried out, Invoice of repair done Non-existent
- 3 Door - rear right side, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	302 µm	Door - rear right side	228 µm
Door - front right side	170 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Damage 1: Wheel / tyres: Wheel cover - rear left side - Scratch(es) - Replace



Damage 1: Wheel / tyres: Wheel cover - rear left side - Scratch(es) - Replace



Damage 2: Wheel / tyres: Wheel cover - rear right side - Scratch(es) - Replace



Damage 2: Wheel / tyres: Wheel cover - rear right side - Scratch(es) - Replace



Damage 3: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Wheel cover - front right side - Scratched - Replace




Damage 3: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 4: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair



Damage 4: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair




Damage 5: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 5: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 6: Body: B-pillar - left side - dent(s) - Smooth repair work




Damage 6: Body: B-pillar - left side - dent(s) - Smooth repair work



Damage 7: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work




Damage 7: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work



Damage 8: Front bumper: Spoiler - Scratch(es) - Smart repair




Damage 8: Front bumper: Spoiler - Scratch(es) - Smart repair



Damage 8: Front bumper: Spoiler - Scratch(es) - Smart repair



Damage 8: Front bumper: Spoiler - Scratch(es) - Smart repair



Damage 9: Trim / covers: A-pillar - trim - interior, left side - Holes - Replace



Damage 9: Trim / covers: A-pillar - trim - interior, left side - Holes - Replace



Damage 10: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace




Damage 10: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace




Damage 10: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace




Damage 10: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace




Damage 11: Cab: Door rubber seal - left side - Broken / torn - Replace




Damage 11: Cab: Door rubber seal - left side - Broken / torn - Replace



Damage 11: Cab: Door rubber seal - left side - Broken / torn - Replace



Damage 12: Misc.: Inspection / maintenance - Due - Perform




Damage 12: Misc.: Inspection / maintenance - Due - Perform



Damage 13: Interior: Rear shelf (Halter) - Broken / torn - Replace



Damage 13: Interior: Rear shelf (Halter) - Broken / torn - Replace



Damage 14: Rear bumper: Rear bumper - Scratched - Paint



Damage 14: Rear bumper: Rear bumper - Scratched - Paint




Damage 14: Rear bumper: Rear bumper - Scratched - Paint




Damage 14: Rear bumper: Rear bumper - Scratched - Paint



Damage 14: Rear bumper: Rear bumper - Scratched - Paint



Damage 15: Seat - front: Backrest cover - left side - Broken / torn - Replace



Damage 15: Seat - front: Backrest cover - left side - Broken / torn - Replace




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 16: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 17: Seat - front: Backrest cover - right side - Broken / torn - Replace




Damage 17: Seat - front: Backrest cover - right side - Broken / torn - Replace




Damage 18: Sliding door, right: Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint



Damage 18: Sliding door, right: Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint



Damage 18: Sliding door, right: Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint



Damage 18: Sliding door, right: Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint



Damage 18: Sliding door, right: Sliding door with glass panel (Wellig, Einschlüsse) - Unprofessionally repaired - Repair and paint



Damage 19: Side panel - rear right side: Side panel (Verkratzt) - Deformed - Repair and paint




Damage 19: Side panel - rear right side: Side panel (Verkratzt) - Deformed - Repair and paint




Damage 19: Side panel - rear right side: Side panel (Verkratzt) - Deformed - Repair and paint



Damage 19: Side panel - rear right side: Side panel (Verkratzt) - Deformed - Repair and paint



Damage 19: Side panel - rear right side: Side panel (Verkratzt) - Deformed - Repair and paint



Wear and tear 3: Door - front left side: Brightware - lower - Scratch(es) - No deduction



Wear and tear 3: Door - front left side: Brightware - lower - Scratch(es) - No deduction



Wear and tear 3: Door - front left side: Brightware - lower - Scratch(es) - No deduction



Repainting 1: Side panel - rear right side



Repainting 2: Door - front right side



Repainting 3: Door - rear right side