



Expertise

Protocol number: 46593844
Order No. / Reference: 26685214
Inspection date: 20 Jul 2026

Manufacturer: Mercedes-Benz
VIN: W1V44760314135152

Model: Vito 114 CDI Lang HA PRO



Vehicle details	
Manufacturer / Type / Model / Equipment	
Mercedes-Benz Vito 114 CDI Lang HA PRO	
Vehicle Identification number	W1V44760314135152
Mileage (Read)	54,749 km
First registration	19 Aug 2022
Number of holders	1
Next periodical technical inspection	09/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	100 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	ARKTIKWEISS
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	51 Tag(e)
Last service on / at	08/2024 at 31,902 km		
Key is / should be	1 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM190374
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / BBI 05327		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,800 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109T	Winter tyres on Light alloy	Pirelli	8mm / 8mm
2)	225/55 R17 109T	Winter tyres on Light alloy	Pirelli	8mm / 8mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 109H	Summer tyres on Steel rim with wheel cover	Dunlop	7mm / 7mm
2)	225/55 R17 109H	Summer tyres on Steel rim with wheel cover	Dunlop	7mm / 7mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	225/55 R17 109H C	Summer tyres on Steel	Continental	9 mm
Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.				

Equipment

Standard equipment

- Screw-in towing eye front/rear
- Passenger side airbag
- ATTENTION ASSIST (ATTENTION ASSIST can assist the driver on long, monotonous journeys by monitoring attention. If signs of fatigue or increasing inattention are detected, it suggests a break.)
- Battery: fleece battery 12 V / 92 Ah
- Hill start assist
- Brake lights, adaptive
- Front cupholder
- Diesel particulate filter
- Entry grab handle for the cargo area sliding door
- Electronic Stability Program (ADAPTIVE ESP) with integrated Anti-lock Braking System (ABS)
- HVO-capable vehicle
- Parking brake
- Generator management
- Transmission: 6-speed manual transmission TSG 380
- Seatbelt warning device for front passenger seat
- Lockable glove box
- Interior trim of cargo area, side
- Instrument cluster with pixel matrix display
- Headrests (2), front
- Steering wheel adjustable for tilt and height
- Mercedes-Benz emergency call system (communication module (LTE) for digital services breakdown management)
- Package: BlueEFFICIENCY (Efficiency Package)
- Upholstery: Caluma fabric, black
- Radio: Digital Radio DAB
- Full wheel cover
- Tires: Tires without specified make
- Wheels: Steel rims 6.5 J x 16
- Sliding door on the right, cargo/passenger compartment
- Crosswind Assist
- Seat: Lumbar support driver's seat
- Seats: Comfort driver's seat
- 12V socket
- continuous partition wall
- Pre-installation for Remote Services Plus
- Maintenance interval indicator >>ASSYST<
- Heat-insulating glass all around
- Registration as a truck
- Axle ratio $i = 3.267$
- Driver's side airbag
- Electrically adjustable and heated exterior mirrors, left and right
- Outdoor temperature display
- Battery: Backup battery for starting process
- Fixing points in the roof frame
- third brake light
- COC documents
- Comfort roof control unit
- Electronic tachometer
- Electrical components for trailer socket
- Driving light assistant
- Chassis: Standard chassis
- Electric windows, driver/passenger
- Generator 14 V / 250 A
- Speed limit 210 km/h
- Weight variant 2,800 kg
- Seatbelt warning device for driver's seat
- Main tank 57 liters
- Tempmatic controlled air conditioning
- Communication module (LTE) for digital services
- Paint finish: Solid color paint
- Headlight range control
- Multifunctional steering wheel
- Halogen fog lights
- Breakdown management
- Radio/Telematics, Audio 10 (DAB Digital Radio - 3.5-inch LCD display - Bluetooth hands-free system - 2-way front speakers)
- Tires: Premium protection tires (3 years)
- Headlights: halogen technology
- Key: 3-button remote control
- electromechanical power steering
- Seats: Driver's seat Plus with flat seat surface
- Start-stop function
- Cruise control
- First aid kit
- Warning triangle
- Immobiliser
- Central locking with radio remote control
- Registration certificate, Part II



Extra equipment

- Towbar (fixed ball head)
- Sortimo installation
- LED light strip in the cargo area
- Tires: 225/55R17
- Tires: M+S 225/55 R 17
- Spare wheel under the rear of the vehicle with jack
- Rear door, double-leaf, 180° opening, without window
- Elimination of rear lettering
- Upgrading/downgrading (upgrading to 3.05 t GVW)
- Grab handle for entry of driver and passenger
- Parktronic (with optical and acoustic warning signals, PARKTRONIC assists the driver when parking and maneuvering)
- Wheels: Steel rims 6.5 J x 17
- Seats: Passenger seat, two-seater
- Cargo area ventilation

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - dent(s) - Smart repair
2	Boot lid / rear door	Rear door - right side - dent(s) - Smart repair
3	Instrument panel	Air nozzle - centre (links) - Broken / torn - Replace
4	Sliding door, right	Sliding door - dent(s) - Smart repair
5	Rear bumper	Bumper with Parktronic - Deformed - Loss in value
6	Body	Body (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise
7	Boot lid / rear door	Rear door - left side - dent(s) - Repair and paint
8	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
9	Roof	Roof - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
2	Bonnet	Bonnet - Dent / paintcoat damage - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - Vehicle key with remote control



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Damage 1: Door - front left side: Door - dent(s) - Smart repair



Damage 1: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair



Damage 2: Boot lid / rear door: Rear door - right side - dent(s) - Smart repair




Damage 3: Instrument panel: Air nozzle - centre (links) - Broken / torn - Replace



Damage 3: Instrument panel: Air nozzle - centre (links) - Broken / torn - Replace



Damage 4: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 4: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 4: Sliding door, right: Sliding door - dent(s) - Smart repair



Damage 5: Rear bumper: Bumper with Parktronic - Deformed - Loss in value



Damage 5: Rear bumper: Bumper with Parktronic - Deformed - Loss in value



Damage 5: Rear bumper: Bumper with Parktronic - Deformed - Loss in value



Damage 6: Body: Body (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise




Damage 6: Body: Body (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body (Zusatzkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 7: Boot lid / rear door: Rear door - left side - dent(s) - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - dent(s) - Repair and paint



Damage 7: Boot lid / rear door: Rear door - left side - dent(s) - Repair and paint




Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 9: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 9: Roof: Roof - Dent / paintcoat damage - Repair and paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1V44760314135152

Hersteller / Modell: MERCEDES-BENZ MERCEDES-BENZ Vito 114 CDI Lang HA
PRO

Datum	KM-Stand	Beschreibung
09.09.2024	31.903	HU + AU
30.08.2024	31.902	Regelwartungsdienst