



Expertise

Protocol number: 47216325
Order No. / Reference: 26861449
Inspection date: 20 Aug 2026

Manufacturer: Opel

Model: Astra 1.5 D Start/Stop Business Edition

VIN: W0VBD6EU1NG028552



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Start/Stop Business Edition	
Vehicle Identification number	W0VBD6EU1NG028552
Mileage (Read)	139,323 km
First registration	21 Feb 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,496 ccm / 3
Power	77 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Onyxschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	6 Monat(e)
Last service on / at	02/2026 at 122,166 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC790209
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALF 00129		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	1,880 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Steel	Continental	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Steel	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|---|
| <ul style="list-style-type: none"> • 2 ignition keys • Airbag for driver and passenger side • Airbag: Head airbags, 1st and 2nd row (outer seats) • Anti-lock braking system (ABS) • Electrically adjustable and heated exterior mirrors for driver and passenger side • third brake light • Decorative trim strips Antelao Sand/Polar Silver • Tachometer • Electric windows front and rear • Transmission: 6-speed manual transmission • rear window wiper • Instruments, black, with high-gloss chrome rings, 3.5" driver information display • Rear headrests (3) • Cargo area cover • LED daytime running lights • Steering column, height and reach adjustable • Fog light • Pedals: Disengaging safety pedals • Quickheat rapid heating system • Radio: Multimedia radio with 7" touchscreen color display • Tire pressure monitoring system • Rear seat backrest folds forward in a 60:40 split • Seat belts: Three-point seat belts in all seats • Seats: Comfort seats, front • 12V power outlet in the center console • Pre-installation for child seat mounting system "ISOFIX" • Heat-insulating glazing, green tinted, and windshield | <ul style="list-style-type: none"> • Storage compartments • Airbag: Chest-pelvis side airbag for driver and front passenger side • Automatic activation of the hazard warning lights • Hill Start Assist • On-board computer • Roof design line, above in black • Diesel particulate filter (DPF) • Electronic Stability Program Plus (ESP Plus) • Speed controller with limiter • Back window, heater • Interior lighting, front and rear • Air conditioning • trunk light • Front headrests • LED headlights • Steering wheel: Leather steering wheel • Lighting equipment • Parkpilot, rear parking aid • Upholstery: Cloth • Radio: Digital radio reception DAB/DAB+/DMB-R • Tire repair kit • Wheels: Designer wheels, 7 J x 16 with tires 205/55 R16 • Power steering • Visibility equipment • Start/Stop System • Traction Control (TC) Plus • Immobiliser • Central locking with remote control and interior switches |
|--|---|

Extra equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Paint finish: Metallic • Parkpilot, front and rear parking aid (with acoustic warning signal when parking forwards and backwards) | <ul style="list-style-type: none"> • Package: Navigation Package 1 (Multimedia Navigation - Reversing Camera - Fog Lights) • Solar Protect heat-insulating glazing (in the rear, heavily tinted) |
|--|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Instrument panel	Stowage compartment (Kleberreste) - Soiled - Replace
2	Wheel / tyres	Wheel cover - front right side - Scratched - Replace
3	Roof	Stub aerial - Broken / torn - Replace
4	Equipment	Tirefit filler - Expired - Replace
5	Wing mirror - right side	Cap - Scratch(es) - Smart repair
6	Door - front left side	Door edge - Scratch(es) - Smart repair
7	Roof	Roof rail - right side - dent(s) - Smooth repair work
8	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
9	Roof	Roof - dent(s) - Smooth repair work
10	Door - rear left side	Door - Scratch(es) - Paint
11	Headlight	Headlight - right side - Scratch(es) - Replace
12	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
13	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
14	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Professionally repaired, Invoice of repair done Non-existent, from 6 Mar 2024	1.228,62 €
2	Rear, Professionally repaired, Invoice of repair done Non-existent, from 1 Feb 2024	4.353,98 €

Repainting

No.	Repainting
1	Roof, Professionally carried out, Invoice of repair done Non-existent
2	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Roof	179 µm	Boot lid / rear door	180 µm
------	--------	----------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Der beiliegende Winterradsatz ist kein Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 1: Instrument panel: Stowage compartment (Kleberreste) - Soiled - Replace



Damage 1: Instrument panel: Stowage compartment (Kleberreste) - Soiled - Replace



Damage 2: Wheel / tyres: Wheel cover - front right side - Scratched - Replace




Damage 2: Wheel / tyres: Wheel cover - front right side - Scratched - Replace



Damage 3: Roof: Stub aerial - Broken / torn - Replace



Damage 3: Roof: Stub aerial - Broken / torn - Replace



Damage 4: Equipment: Tirefit filler - Expired - Replace



Damage 5: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 5: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 7: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 7: Roof: Roof rail - right side - dent(s) - Smooth repair work



Damage 8: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 8: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 8: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 8: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work




Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 9: Roof: Roof - dent(s) - Smooth repair work



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 10: Door - rear left side: Door - Scratch(es) - Paint



Damage 11: Headlight: Headlight - right side - Scratch(es) - Replace




Damage 11: Headlight: Headlight - right side - Scratch(es) - Replace



Damage 11: Headlight: Headlight - right side - Scratch(es) - Replace




Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 12: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 14: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Repainting 1: Roof



Repainting 2: Boot lid / rear door



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD6EU1NG028552

Hersteller / Modell: OPEL OPEL Astra 1.5 D Start/Stop Business Edition

Datum	KM-Stand	Beschreibung
01.07.2026	138.847	Systemtest/Eigendiagnose
23.04.2026	131.356	Systemtest/Eigendiagnose
11.02.2026	122.166	Bremse Sonstiges; Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
20.11.2025	114.745	Systemtest/Eigendiagnose
24.09.2025	108.298	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
17.06.2025	100.944	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
27.01.2025	87.420	HU + AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/Eigendiagnose; Wartung Sonstiges
13.09.2024	77.298	Systemtest/Eigendiagnose
12.08.2024	73.976	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges
08.05.2024	67.783	Reparatur Sonstiges; Systemtest/Eigendiagnose
20.03.2024	61.682	Bremsflüssigkeit; Bremsflüssigkeit ern; Bremsklötze hinten; Bremsklötze vorne; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
02.02.2023	27.066	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges