



Expertise

Protocol number: 46695337
Order No. / Reference: 26760069
Inspection date: 21 Jul 2026

Manufacturer: Opel

Model: Insignia Sports Tourer 2.0 Diesel Business

VIN: W0VZT8EP3N1002903



Vehicle details

Manufacturer / Type / Model / Equipment

Opel Insignia Sports Tourer 2.0 Diesel Business

Vehicle Identification number W0VZT8EP3N1002903
Mileage (Read) 156,799 km
First registration 28 Mar 2022
Number of holders 1
Next periodical technical inspection 02/2028
(Report not on hand)

Fuel type Diesel
Engine displacement / Cylinder 1,995 ccm / 4
Power 128 kW
Gearbox / Number of gears Manual / 6
Type of drive Front drive
Type of vehicle Station wagon

Colour / colour code Jade Weiß
Doors / Seats 5 / 5
Upholstery type Cloth / leather combination
Colour of upholstery Black



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	92 %
Last service on / at	06/2026 at 154,840 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ638837
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	Conditional: Light/moisture/dirt	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Not possible
Manufacturer key number/ type code number	1844 / AMC 00241		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,205 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	245/45 R18 100Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 101V	Winter tyres on Light alloy	Fulda	5mm / 5mm
2)	225/55 R17 101V	Winter tyres on Light alloy	Sonstige	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Automatic climate control, two zones
- Center armrest, front
- Decorative strip hexagon
- Electric parking brake (including 12-volt socket)
- Electronic Stability Program (ESP Plus)
- Front collision warning system with pedestrian detection and automatic emergency braking
- Glasses compartment in the headliner
- Lane Keeping Assist (warning in case of unintentional lane departure (between 60 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- LED daytime running lights including LED indicators, front and LED taillights
- LED headlights (automatic headlight range control)
- Luggage compartment cover (extendable with comfort operation)
- Parkpilot, front and rear parking aid
- Power steering (speed-dependent)
- Quickheat rapid heating system
- Radio: Digital radio reception DAB+
- Radio: Multimedia Navi Pro with 8" color touchscreen display (voice control for audio, telephone and navigation, USB port, Bluetooth audio streaming, navigation system with SD card storage, connected navigation services, predictive navigation, online map updates, real-time traffic information, 8" driver information display, steering wheel controls, Apple CarPlay and Android Auto)
- Rear headrests (3 pieces) (height adjustable)
- Rear seat backrest folds forward in a 60:40 split
- rear window wiper
- Safety net (for installation behind the 1st or 2nd row of seats)
- Storage compartments (storage compartment in the center console, pockets in the front doors suitable for 1.5-liter beverage bottles, pockets in the rear doors suitable for 1-liter beverage bottles, cup holder in the center console, illuminated glove compartment)
- Tachometer
- Traffic sign assistant (recognition of speed limits, no-overtaking zones and their cancellation, additional information signs (e.g., for wet conditions, slippery surfaces, left/right directions) on standard traffic signs, beginning and end of motorways, expressways and traffic-calmed areas, display of the recognized sign in the driver information display (depending on traffic sign quality, visibility and weather conditions).)
- Transmission: 6-speed manual transmission
- Visibility equipment (rain sensor, front)
- Adaptive brake light
- Airbag: Front and rear outer head airbags
- Airbag: Front and side airbags, driver and front passenger (front and side airbag, passenger, deactivatable)
- Ambient lighting (dashboard and doors (front))
- Back window, heater
- Bumpers painted in body color
- Central locking with remote control (and interior switches)
- Child safety lock in the rear doors, manual
- Diesel particulate filter
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable)
- Electronic brake force distribution (EBD)
- Front headrests (height adjustable)
- Hill Start Assist
- Illuminated makeup mirrors in both sun visors
- Immobiliser
- LED fog lights
- Noise-reducing, laminated front side windows
- Package: Winter 1 (AGR, driver) (Heated seats, multi-stage, driver and front passenger - Heated leather steering wheel - 60:40 split-folding rear seat backrest - Ergonomic active seat (AGR), driver (length, height and backrest angle manually adjustable, seat tilt electrically adjustable, electro-pneumatic lumbar support adjustable in height and length, extendable thigh support manually, headrest height and tilt adjustable) - Heated ThermoTec windshield)
- Paint finish: Solid
- Pedestrian protection including active hood
- Pre-installation for child seat mounting system "ISOFIX" (rear)
- Roof rails, silver anodized
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Speed controller
- Start/Stop system (reinforced starter, high-performance battery, brake energy recuperation, switch to deactivate the start/stop function)
- Steering column adjustable for height and reach
- Thermal insulation glazing, green tinted
- third brake light
- Tire pressure display (with tire pressure warning - direct system with automatic calibration after wheel change)
- Tire repair kit (including tire sealant and 12-volt compressor (without jack))
- Traction Control (TC) Plus (traction control with engine and brake intervention)



Extra equipment

- Upholstery: Monita fabric/Premium leather look including Winter Package 2 (Ergonomic active seat, certified by the Campaign for Healthy Backs (AGR), front/front seat heating, multi-stage, front/front heated leather steering wheel, heated ThermoTec windshield, Seat Comfort Equipment 1: 8-way electrically adjustable driver's seat, electro-pneumatically adjustable lumbar support, memory function - driver and exterior mirrors, massage function, front exterior mirrors, electrically adjustable, heated, folding rear seat backrest with FlexFold function, 40:20:40 split, Charging Package: Wireless charging, 2 USB ports)
- Package: Sound (Bose sound system)
- Swiveling trailer hitch (including trailer stability program)
- Wheels: 8.5 J x 18 alloy wheels in high-gloss black (multi-spoke) (with 245/45 R 18 tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run could not be performed. This is due to the following reason.: Dreht, aber startet nicht, Instandsetzung laut KVA

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (1.,2. und 5. Wartung überzogen)
2	Equipment	Tirefit filler - Expired - Replace
3	Front bumper	Front bumper - Scratch(es) - Smart repair
4	Vehicle glazing	Windscreen - Broken / torn - Replace
5	Engine	Engine - Damaged - repair according to calculation

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Unterbodenbesichtigung nicht möglich-Mehrkosten können entstehen. Antriebsstrang konnte nicht getestet werden-Mehrkosten möglich.

elektrische Verbraucher konnten nicht getestet werden-mehrkosten möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair




Damage 4: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 4: Vehicle glazing: Windscreen - Broken / torn - Replace




Damage 4: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 5: Engine: Engine - Damaged - repair according to calculation



Damage 5: Engine: Engine - Damaged - repair according to calculation



Damage 5: Engine: Engine - Damaged - repair according to calculation



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZT8EP3N1002903
Hersteller / Modell: OPEL Insignia Sports Tourer 2.0 Diesel Business

Datum	KM-Stand	Beschreibung
10.07.2026	156.788	Systemtest/Eigendiagnose
16.06.2026	154.840	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.09.2025	124.087	Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
31.03.2025	102.555	AU
12.12.2024	92.794	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
11.03.2024	66.263	Bremsklötze hinten; Bremsscheiben + Klötze h; Bremsscheiben hinten
07.02.2024	62.899	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.03.2023	31.965	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges