



Expertise

Protocol number: 46433733
Order No. / Reference: 26652040
Inspection date: 7 Jul 2026

Manufacturer: Opel

Model: Movano 2.2 BlueHDi 140 L2H2 VA Autm.

VIN: VXEYCF8F2SG027474



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Movano 2.2 BlueHDi 140 L2H2 VA Autm.	
Vehicle Identification number	VXEYCF8F2SG027474
Mileage (Read)	37,668 km
First registration	10 Jun 2025
Number of holders	1
Power / Engine displacement	103 kw / 2,184 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Casablancaweiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	Available / incomplete	Next maintenance in	12,332 km
Last service on / at	12/2025 at 25,719 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HG585705
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	3003 / BAM 02343		
Emission standard	EURO6;WLTP;EA;PI/CI;M, N1, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/75 R16 116R	Winter tyres on Steel	Pirelli	5mm / 5mm
2)	215/75 R16 116R	Winter tyres on Steel	Pirelli	8mm / 8mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/75 R16 116R	Summer tyres on Steel	Nexen	5mm / 5mm
2)	215/75 R16 116R	Summer tyres on Steel	Nexen	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	215/75 R16 116R C	Summer tyres on Steel	Nexen	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Storage compartments: Cup holders (lower center console) and central storage compartment in the dashboard • Exterior mirrors, electrically adjustable and heated • Reinforced battery (95 Ah) • On-board computer • Tachometer • Electronic Stability Control (ESP) (Crosswind Assist - Trailer Stability Control - Post Collision Braking - Rollover Prevention - Traction Control (ASR) - Hydraulic Brake Assist (HBA) - Hill Start Assist - Adaptive Load Control (LAC) (Adaptation of ABS, ASR and ESP functions to vehicle load)) • Air conditioning • Headrests (3) • Radiator grille surround in body color • 180A alternator • Radio: Audio system DAB (5" color display, digital radio; Bluetooth hands-free system, steering wheel controls, BTA (telematics box module), USB) • Electric power steering • Safety kit (Emergency Brake Assist (Pedestrian and Cyclist Detection) - Lane Keeping Assist - Traffic Sign Recognition - Driver Fatigue Warning - Intelligent Speed Assist - Event Data Recorder (EDR) / Black Box) • Doors: Rear doors with a 180° opening angle • Doors: Sliding door on the right, sheet metal cladding • Warning tone and light for unfastened seat belts, front • Immobiliser | <ul style="list-style-type: none"> • Passenger side airbag • Driver's side airbag • Anti-lock braking system (ABS) • Exterior mirrors: Short mirror arm - for vehicle widths up to 2.20 m • third brake light • Rear parking aid (acoustic) • Electric front windows • Pedestrian warning (acoustic) at the rear • Speed controller and limiter • Transmission: 8-speed automatic • Hooks for securing goods in the cargo area • Halogen headlights with halogen daytime running lights (DRL) • Fuel tank 90 l (AdBlue tank 19 liters) • Paint finish: Solid color paint • Particulate filter: Diesel particulate filter with SCR (AdBlue) • Radio: DAB antenna on the roof • Indirect tire pressure monitoring system (TPMS) • Wheels: Steel wheels 6J x 16 (tires 215/75 R16C 116/114R) • Seats: Driver's seat with armrest and lumbar support, double passenger seat (double passenger seat with folding function in the middle backrest) • Partition wall clad in sheet metal • Doors: Rear doors, sheet metal • Door interior trim with storage compartments including 1.5-liter bottle holder and speaker housing • Central locking with remote control + 1 mechanical key |
|---|---|

Extra equipment

- | | |
|---|--|
| <ul style="list-style-type: none"> • lettering • Package: Spare wheel (spare wheel - winch - jack) • Package: Winter (programmable Webasto auxiliary heater - heated driver's seat - heated windshield - preheating device for oil vapor recirculation - keyless entry and start (Keylessentry & go) - electric parking brake - central glove compartment (lockable)) • Rails, roof, floor including plate • Movable partition net | <ul style="list-style-type: none"> • Package: "CITY PLUS VISIBILITY" (Blind Spot Assist + Cross Traffic Alert when reversing - Electrically folding exterior mirrors - Digital rearview mirror - 360° parking sensors + parking assist - Light and rain sensor + high beam assist - Fog lights with cornering function) • Upholstery: Fabric (Crepe Black fabric - backrest pattern - double silver side seams) • Side paneling |
|---|--|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.



Value reducing factors

No.	Component group	Description
1	Steering system	Steering wheel sheath - Scratch(es) - Loss in value
2	Instrument panel	Instrument panel (Klackgeräusch mittig) - Functional / admissibility - Perform diagnosis
3	Wing mirror - right side	Mirror housing - Broken / torn - Replace
4	Side panel - rear left side	Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Mudguard - right side	Mudguard - right side - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, not professionally repaired	

Repainting

No.	Repainting
1	Side panel - rear left side, Unprofessionally carried out

Paint coat thickness measurement

Side panel - rear left side	2,990 µm
-----------------------------	-------------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

An unprofessionally repaired previous damage was found at the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

Da nicht erkennbar ist ob die Standheizung eine Fernbedienung hat wurde eine solche nicht berechnet. Eventuell muss dies nachbelastet werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Steering system: Steering wheel sheath - Scratch(es) - Loss in value




Damage 1: Steering system: Steering wheel sheath - Scratch(es) - Loss in value



Damage 1: Steering system: Steering wheel sheath - Scratch(es) - Loss in value




Damage 1: Steering system: Steering wheel sheath - Scratch(es) - Loss in value



Damage 3: Wing mirror - right side: Mirror housing - Broken / torn - Replace



Damage 3: Wing mirror - right side: Mirror housing - Broken / torn - Replace



Damage 3: Wing mirror - right side: Mirror housing - Broken / torn - Replace



Damage 3: Wing mirror - right side: Mirror housing - Broken / torn - Replace



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Damage 4: Side panel - rear left side: Side panel (Heckecke, falscher Lackton und Spachtelmasse eingefallen) - Unprofessionally repaired - Repair and paint



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXEYCF8F2SG027474

Hersteller / Modell: OPEL OPEL Movano 2.2 BlueHDi 140 L2H2 VA

Datum	KM-Stand	Beschreibung
11.12.2025	25.719	Motoröl b. Wartung; Ölfilter ern; Ölwechsel; Wartung Sonstiges