



Expertise

Protocol number: 46416444
Order No. / Reference: 26678563
Inspection date: 9 Jul 2026

Manufacturer: Ford

Model: Transit 350 L4H3 Lkw HA Trend

VIN: WF0EXXTTREL54754



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Transit 350 L4H3 Lkw HA Trend

Vehicle Identification number WF0EXXTTREL54754

Mileage (Read) 50,430 km

First registration 28 Jul 2020

Number of holders 1

Next periodical technical inspection 08/2026
(Report not on hand)

Power / Engine displacement 96 kw / 1,995 ccm

Fuel type / Cylinder Diesel / 4

Gearbox / Number of gears Manual / 6

Type of drive Rear drive

Type of vehicle Van

Colour / colour code Frozen White

Doors / Seats 4 / 3

Upholstery type Cloth

Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	25,000 km
Last service on / at	08/2025 at 43,991 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FV055227
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BNG 09259		
Emission standard	EURO6;WLTP;CI;PI/CI;N1 III, N2	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm
2)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel	Sonstige	5mm / 5mm
2)	235/65 R16 115R	Winter tyres on Steel	Falken	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, high
- Double-leaf rear doors with a 256° opening angle (without windows)
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Cargo area floor: Vinyl floor covering "Easy Clean" including wheel arch lining
- Fog light
- Front and rear parking pilot system
- Radio: Audio system 13
- Wheels: Tire repair kit
- Headlights with static cornering lights
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Start-stop system
- Daytime running light
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Second key with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Tachometer
- Third brake light
- Front electric windows
- Ford Easy Fuel
- Generator, high-performance version
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting
- Steering column, adjustable in height and reach
- MyKey key system
- Emergency brake assist including emergency brake light
- Particulate filter: diesel particulate filter
- Wheels: Wheel trims
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Headlights with delayed shut-off
- Sliding door: Sliding door, right
- Rear mud flaps
- Side wall cladding up to the roof
- Seat belts
- Rear bumper with integrated step
- Partition wall to the cargo area without window
- Immobiliser
- Central locking with remote control
- Front overhead storage compartment

Extra equipment

- Airbag (passenger side)
- LED lights in the cargo area
- Package: Load securing package (airline rails on the side walls, right and left, at heights of 550/1575 mm (rear-wheel drive) and 650/1675 mm (front-wheel drive) - allsafe JUNGFALK load securing set including 2 ratchet straps - 2 hooks (KERL Butler) for use in combination with the airline rails - hardwood cargo floor (Delignit))
- Power outlet: 12-volt connection in the cargo area (D-pillar)
- Package: Visibility Package II (Electrically adjustable and heated exterior mirrors - Heated windscreen - Windscreen washer sensor - Electrically folding exterior mirrors - Adjustable instrument lighting - Fog lights - Rain-sensing wipers - Headlight assistant with day/night sensor)
- Seats: Seat Package 15 (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated (fold-out) tray in the double passenger seat - Heated driver's seat - Heated passenger seat - Interior armrest for driver - Manual lumbar support (driver's seat) - Seat upholstery: fabric)

Retrofitted equipment

- All-weather floor mats in a custom fit
- Protective covers in Transit EK fit
- Car fire extinguisher 2 kg, testable
- Winter complete wheels steel rim Transit



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Due - Replace
2	Trim / covers	Boot lining - Soiled - Clean
3	Boot lid / rear door	Rear door - left side - dent(s) - Smart repair
4	Body	Body - Glued / labelled - De-glue / neutralise
5	Boot lid / rear door	Rear door - right side - Scratch(es) - Smart repair
6	Engine	Engine cover - Broken / torn - Replace
7	Braking system	Brake discs and pads - rear - Corrosion - Replace
8	Sliding door, right	Sliding door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Roof	Roof - dent(s) - No deduction
2	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Rear, Side - left

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Damage 1: Equipment: Tirefit filler - Due - Replace



Damage 2: Trim / covers: Boot lining - Soiled - Clean



Damage 2: Trim / covers: Boot lining - Soiled - Clean



Damage 2: Trim / covers: Boot lining - Soiled - Clean



Damage 3: Boot lid / rear door: Rear door - left side - dent(s) - Smart repair



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 4: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Boot lid / rear door: Rear door - right side - Scratch(es) - Smart repair




Damage 5: Boot lid / rear door: Rear door - right side - Scratch(es) - Smart repair



Damage 6: Engine: Engine cover - Broken / torn - Replace



Damage 6: Engine: Engine cover - Broken / torn - Replace




Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 7: Braking system: Brake discs and pads - rear - Corrosion - Replace



Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint




Damage 8: Sliding door, right: Sliding door - Scratch(es) - Paint



Wear and tear 1: Roof: Roof - dent(s) - No deduction



Wear and tear 1: Roof: Roof - dent(s) - No deduction




Wear and tear 2: Body: Body - Scratch(es) - No deduction




Wear and tear 2: Body: Body - Scratch(es) - No deduction



Accident 1: Rear, Side - left




Accident 1: Rear, Side - left




Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left




Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Accident 1: Rear, Side - left



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0EXXTTREL54754
Hersteller / Modell: FORD FORD Transit 350 L4H3 Lkw HA Trend

Datum	KM-Stand	Beschreibung
25.08.2025	43.991	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
21.08.2024	38.825	AU; Kraftstofffilter ern; Luftfiltereinsatz ern; Regelwartungsdienst
18.09.2023	32.826	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst
17.08.2022	22.035	AU; Motoröl b. Wartung; Regelwartungsdienst