



Expertise

Protocol number: 46403894
Order No. / Reference: 26577257
Inspection date: 8 Jul 2026

Manufacturer: Citroën

Model: C5 Aircross Hybrid 225 e.EAT8 SHINE PACK

VIN: VR7A4DGZSNL022256



Vehicle details

Manufacturer / Type / Model / Equipment

Citroën C5 Aircross Hybrid 225 e.EAT8 SHINE PACK

Vehicle Identification number VR7A4DGZSNL022256
Mileage (Read) 81,017 km
First registration 31 May 2022
Number of holders 1
Next periodical technical inspection 07/2027
(Report on hand)

Power / Engine displacement 133 kw / 1,598 ccm
Fuel type / Cylinder Hybr.B/E ext.aufll / 4
Gearbox / Number of gears Automatic / 8
Type of drive Front drive
Type of vehicle SUV

Colour / colour code Platinum-Grau Metallic
Doors / Seats 5 / 5
Upholstery type Leather
Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	7 Tag(e)
Last service on / at	07/2025 at 76,630 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA818554
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / ACO 00010		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,300 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R19 97V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	205/55 R19 97V	Summer tyres on Light alloy	Michelin	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	225/55 R18 102V	Winter tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver and passenger side
 - Airbag: Front side airbags
 - Anti-lock braking system (ABS) with electronic brake force distribution (EBD) and brake assist
 - Electrically adjustable, heated and electrically folding exterior mirrors
 - Display: 31-cm/12.3-inch digital instrument cluster
 - Electric parking brake
 - Driving modes
 - Chassis: CITROËN ADVANCED Comfort suspension
 - Full LED headlights
 - front and rear floor mats
 - Transmission: 8-speed automatic
 - rear window wiper
 - Interior mirror automatically dimming
 - Keyless system
 - Automatic climate control with separate settings for driver/passenger
 - Rear headrests (3)
 - LED flashing lights
 - Navigation: CITROËN Connect Nav with DAB/DAB+
 - Otto particulate filter
 - Package: Parking Package
 - Package: Style Package Silver
 - Tire pressure monitoring system
 - Wheels: Tire repair kit
 - Power steering
 - Seats: 3 individual seats in the second row
 - Seats: Driver's seat, electrically adjustable
 - Seats: Heated front seats
 - Stop & Start System
 - Central locking with remote control
- Airbag: Front and rear head airbags
 - Acoustic pedestrian warning system (AVAS)
 - Automatic headlight activation and windscreen wipers with rain sensor, Macis Wash
 - Hill start assist
 - On-board computer
 - Third brake light
 - Electronic Stability Program (ESP) with Traction Control (ASR)
 - Electric windows front and rear
 - Brake and e-Save functions
 - Speed controller and speed limiter
 - Rear and side windows tinted darker
 - Heated rear window
 - Frameless interior mirror with blue LED lighting in electric mode
 - Boot floor in one position (not height adjustable)
 - Front headrests (2)
 - Paint finish: Solid
 - Steering wheel: Steering wheel covered in split leather
 - Fog lights with static cornering lights
 - Package: Drive-Assist Package 5 (EAT8 and 8-EAT8 transmissions)
 - Upholstery: Metropolitan Grey
 - Wheels: 19-inch "ART" alloy wheels, two-tone
 - Front side windows with laminated glass
 - Seat belts: Three-point harnesses on all seats
 - Seats: Driver's seat with lumbar support
 - Seats: Driver's seat/passenger seat adjustable in length, height and tilt
 - Immobiliser

Extra equipment

- Detachable towbar
 - Hands-free tailgate operation (with foot control)
 - Mode 3 charging cable - wallbox charging cable (up to 7.4 kW - single-phase)
 - Upholstery: Hype Black (Advanced Comfort Seats - Nappa Leather in Black/Grey - Driver and Passenger Seats with Massage Function)
- Roof: Panoramic sliding sunroof (with electric sunshade)
 - Paint finish: Metallic
 - On-board charger 7.4 kW, 1-phase
 - Package: Safety Package (360-degree parking assist package (automatic parking) with front and rear parking aid and 360-degree camera)



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Brightware - lower - Scratch(es) - Loss in value
2	Door - rear right side	Door - Scratch(es) - Smart repair
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Door - rear left side	Door - Scratch(es) - Paint
5	Door - front right side	Door - Scratch(es) - Paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Damage 1: Door - front right side: Brightware - lower - Scratch(es) - Loss in value



Damage 1: Door - front right side: Brightware - lower - Scratch(es) - Loss in value




Damage 2: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 2: Door - rear right side: Door - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 4: Door - rear left side: Door - Scratch(es) - Paint




Damage 4: Door - rear left side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Damage 5: Door - front right side: Door - Scratch(es) - Paint



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VR7A4DGZSNL022256

Hersteller / Modell: CITROEN CITROEN C5 Aircross Hybrid 225 e.EAT8 SHINE PACK

Datum	KM-Stand	Beschreibung
14.07.2025	76.630	AU; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges
09.07.2024	54.046	Bremsflüssigkeit; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Wartung Sonstiges; Zündkerzen ern
06.07.2023	32.133	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges