

Vehicle details

VIN	W0VEFYHWC MJ703899	Brand	OPEL	Maintenance date	01/01/1900
Licence Plate	[REDACTED]	Model	COMBO L1H1 1.5D 56kW Edition	Maintenance mileage	-
Registration date	28/05/2021	Year	2021	Exterior Color	Silver Metallic
Odometer	105 387 km	Engine size	1499	Interior Color	Black
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	2	Transmission	Manual	CO2	-
Doors	4	Gears	-		



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel (wheel & tyre)	✓
----------------------------	---

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Sat Nav CD ROM Software	✓

Tyres



Exterior

1		<table border="1"> <tr><td>Part</td><td>Tailgate / Boot door</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Dent & Chips</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Tailgate / Boot door	Position	Back left	Damages	Dent & Chips	Severity	Diameter (mm) > 20	Repair mode	Repair	2		<table border="1"> <tr><td>Part</td><td>Door moulding</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door moulding	Position	Back right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair
Part	Tailgate / Boot door																								
Position	Back left																								
Damages	Dent & Chips																								
Severity	Diameter (mm) > 20																								
Repair mode	Repair																								
Part	Door moulding																								
Position	Back right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
3		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair	4		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Front left</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Front left	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Wing																								
Position	Left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
Part	Wing																								
Position	Front left																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								
5		<table border="1"> <tr><td>Part</td><td>Door</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>Length (cm) > 10</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Door	Position	Back right	Damages	Scratched	Severity	Length (cm) > 10	Repair mode	Repair	6		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 20</td></tr> <tr><td>Repair mode</td><td>Smart Repair</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Severity	Diameter (mm) > 20	Repair mode	Smart Repair
Part	Door																								
Position	Back right																								
Damages	Scratched																								
Severity	Length (cm) > 10																								
Repair mode	Repair																								
Part	Wing																								
Position	Back right																								
Damages	Dented																								
Severity	Diameter (mm) > 20																								
Repair mode	Smart Repair																								