

Vehicle details

VIN	VR3UKZXZ MJ895450	Brand	PEUGEOT	Maintenance date	-
		Model	e-2008 GT EV 50kWh 136	Maintenance mileage	-
Registration date	31/12/2021	Year	2021	Exterior Color	Black Metallic
Odometer	194 031 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 10/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✗

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/60/17 Summer 4.0 mm



Michelin 215/60/17 Summer 4.0 mm



Michelin 215/60/17 Summer 4.0 mm

Michelin 215/60/17 Summer 4.0 mm

Exterior

2



Part

Position

Damages

Severity

Repair mode

Door

Front left

Dent & Chips

-

Repair

3



Part

Position

Damages

Severity

Repair mode

Door


Back left

Dent & Chips

-

Repair

4



Part

Position

Damages

Severity

Repair mode

Alloy wheel 17"


Back left

Scratched

-

Lumpsum repair

6



Part

Position

Damages

Severity

Repair mode

Roof


-

Scratched

-

Repair

7



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Dented

Diameter (mm) > 20

Smart Repair

8



Part

Position

Damages

Severity

Repair mode

Bumper moulding

Back

Broken

-

Replace

9



Part

Position

Damages

Severity

Repair mode

Unpainted bumper


Back

Dented

Diameter (mm) > 20

Smart Repair

10



Part

Position

Damages

Severity

Repair mode

Door


Back right

Dent & Chips

-

Repair

11



Part

Position

Damages

Severity

Repair mode

Door

Front right

Dent & Chips

-

Repair

12



Part

Position

Damages

Severity

Repair mode

Windscreen

-

Stone impact

-

For info

13



Part

Position

Damages

Severity

Repair mode

Bonnet

-

Scratched

-

Repair

14



Part

Position

Damages

Severity

Repair mode

Spoiler

Back

Chemical deposit

-

Lumpsum repair

Interior damage

5



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

Others

1		Part	Wireless charger
		Position	-
		Damages	Missing
		Severity	-
		Repair mode	For info