



Skoda Octavia (UKL): 2CES354

Vinnumber:	TMBJG7NX5NY079477	Versionname:	Octavia Combi Clever+ 2.0TDi 115pk/cv 5p
First Registrationdate:	27/06/2022	Fiscalpower:	
Expertise Mileage:	108126	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	+ 23100 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/55/17/91 V				
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/55 R 17 91 V
Tyre size FR				205/55 R 17 91 V
Tyre size RL				205/55 R 17 91 V
Tyre size RR				205/55 R 17 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Missing, Replace



Seat cover FR, Stain, Cleaning



Alloy rim RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable




Door FL, Scratch(es), Acceptable



Alloy rim FL, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Spot repair



Bumper R, Scratch(es), Acceptable



Rear light R, Scratch(es), Polish



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Paintless dent repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Kenteken	2CES354
Merk Model	Skoda Octavia Combi Clever+ 2.0TDi 115pk/cv 5p
Brandstofsoort	Diesel
Datum deel1	6/27/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
4/16/26	102,974	diagnose	Uitvoeren
4/16/26	102,974	klein materiaal	
4/16/26	102,974	NOx sensor	Vervangen
3/6/26	100,081	brandstof hoofdfilter	Vervangen
3/6/26	100,081	klein materiaal	
3/6/26	100,081	koelwatervloeistof	Bijvullen/-laden
3/6/26	100,081	luchtfILTER	Vervangen
3/6/26	100,081	ruitenswisserrubber achter	Vervangen
3/6/26	100,081	ruitenswisserrubber vooraan	Vervangen
3/6/26	100,081	ruitenswisservloeistof	Bijvullen/-laden
3/6/26	100,081	Tussentijds onderhoud (vast interval)	Uitvoeren
11/16/25	92,223	accu	Vervangen
8/5/25	86,074	batterij	Vervangen
8/5/25	86,074	klein materiaal	
8/5/25	86,074	koelwatervloeistof	Bijvullen/-laden
8/5/25	86,074	Onderhoudsbeurt (variabel interval)	Uitvoeren
8/5/25	86,074	remblokken achter	Vervangen
8/5/25	86,074	remblokken vooraan	Vervangen
8/5/25	86,074	ruitenswisservloeistof	Bijvullen/-laden
1/27/25	70,521	klein materiaal	
1/27/25	70,521	koelwatervloeistof	Bijvullen/-laden
1/27/25	70,521	ruitenswisserrubber achter	Vervangen
1/27/25	70,521	ruitenswisserrubber vooraan	Vervangen
1/27/25	70,521	ruitenswisservloeistof	Bijvullen/-laden
1/27/25	70,521	Tussentijds onderhoud (vast interval)	Uitvoeren
7/5/24	55,323	batterij	Vervangen
7/5/24	55,323	klein materiaal	Uitvoeren
7/5/24	55,323	koelwatervloeistof	Bijvullen/-laden
7/5/24	55,323	luchtfILTER interieur	Vervangen
7/5/24	55,323	Onderhoudsbeurt met oliewissel (variab	Uitvoeren
7/5/24	55,323	remvloeistof	Vervangen
7/5/24	55,323	ruitenswisservloeistof	Bijvullen/-laden
7/5/23	29,392	Onderhoudsbeurt met oliewissel (variab	Uitvoeren