



Expertise

Protocol number: 46762528
Order No. / Reference: 26716035
Inspection date: 29 Jul 2026

Manufacturer: MAN

Model: TGE 3.140 4X2F SB

VIN: WMA03VUY5P9022041



Vehicle details

Manufacturer / Type / Model / Equipment

MAN TGE 3.140 4X2F SB

Vehicle Identification number	WMA03VUY5P9022041
Mileage (Read)	112,512 km
First registration	16 May 2023
Number of holders	1
Next periodical technical inspection	06/2027
(Report on hand)	

Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	103 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van

Colour / colour code	Candy Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black

Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	26,300 km
Last service on / at	06/2025 at 104,227 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GW442249
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1516 / AYN 61613		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	3,500 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Sonstige	8mm / 8mm
2)	205/75 R16 113R	All-season tyres on Steel rim with wheel cover	Sonstige	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/75 R16 113R C	All-season tyres on Steel	Continental	8 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Extra equipment

- Airbag for driver and front passenger with passenger
- C-rails on the side walls in the loading area
- All-season tyres
- MAN Media Van package with 4 speakers
- Smoker's version: 12V socket with cigarette lighter
- Rear View camera
- Single airline points sliding door
- Rear step, across the entire width
- Battery with increased capacity
- Cab doors, additionally reinforced
- Wooden floor in the cargo area with wheel arch trim
- Center wheel cover with chrome emblem
- Spare wheel in driving tire size, steel as well as
- Side interior paneling in the cargo area (plastic)
- 'Comfort' seat on the left, in the 1st row.



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Interior	Interior (Laderaumverkleidungen) - Broken / torn - Replace
2	Rear of vehicle	Wooden floor - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Door - front right side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Damage 1: Interior: Interior (Laderaumverkleidungen) - Broken / torn - Replace




Damage 1: Interior: Interior (Laderaumverkleidungen) - Broken / torn - Replace




Damage 2: Rear of vehicle: Wooden floor - Scratched - Loss in value



Damage 2: Rear of vehicle: Wooden floor - Scratched - Loss in value



Damage 2: Rear of vehicle: Wooden floor - Scratched - Loss in value



Damage 2: Rear of vehicle: Wooden floor - Scratched - Loss in value



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WMA03VUY5P9022041
Hersteller / Modell: MAN MAN TGE 3.140 4X2F SB

Datum	KM-Stand	Beschreibung
06.08.2025	108.643	Bremsbelagfühler ern; Bremsklötze hinten; Bremsklötze vorne; Bremssattel ern/inst
26.06.2025	104.227	AU; Bremsflüssigkeit; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Reparatur Sonstiges; Wartung Sonstiges
07.11.2024	71.694	Motoröl b. Wartung; Ölwechsel; Systemtest/Eigendiagnose
17.06.2024	51.784	Regelwartungsdienst; Reparatur Sonstiges; Systemtest/Eigendiagnose
21.02.2024	34.684	Luftfiltereinsatz ern; Motoröl b. Wartung; Regelwartungsdienst; Reparatur Sonstiges