



Expertise

Protocol number: 46478526
Order No. / Reference: 26603139
Inspection date: 13 Jul 2026

Manufacturer: Opel

Model: Grandland X Plug-in-Hybrid 1.6 DI Start/Stop Aut Business
Elegance

VIN: W0VZ4DGZ2MS037784



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Grandland X Plug-in-Hybrid 1.6 DI Start/Stop Aut Business Elegance	
Vehicle Identification number	W0VZ4DGZ2MS037784
Mileage (Read)	150,800 km
First registration	1 Apr 2021
Number of holders	1
Next periodical technical inspection (Report on hand)	05/2028
Power / Engine displacement	133 kw / 1,598 ccm
Fuel type / Cylinder	Hybr.B/E ext.aufl / 4
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mondstein Grau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	17,200 km
Last service on / at	05/2026 at 148,868 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FW993633
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1844 / ALW 00015		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	2,290 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	225/55 R18 102V	Winter tyres on Light alloy	Goodyear	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	225/55 R18 102V	Summer tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- 230V equipment
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- On-board computer
- Roof design line in chrome
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Luggage compartment cover
- Cruise control with intelligent speed limiter
- Rear window wiper
- Interior lighting, front and rear, with reading lights front and rear
- Rear headrests (3), height adjustable
- LED headlights
- Steering wheel, height and reach adjustable
- Illuminated makeup mirrors in both sun visors
- Mode 2 charging cable
- Fog light
- Otto particulate filter
- Parkpilot, front and rear parking aid
- Radio: Navi 5.0 IntelliLink with 8" color touchscreen display
- Tire pressure warning
- Wheels: Tire repair kit
- Service interval indicator
- Speed-sensitive power steering
- Visibility equipment
- Seats: Premium ergonomic seats with AGR seal of approval, driver and front passenger (plug-in hybrid)
- Lane Assist
- 12-volt power outlet
- Blind spot warning system
- Traffic sign recognition
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer
- Central locking with remote control and interior switches

Extra equipment

- Detachable trailer hitch (trailer stability program)
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)

- Low beam automatically
- Adaptive Forward Lighting (AFL) with LED technology
- Airbag: Chest-pelvis-side airbags, driver and front passenger
- Electrically folding exterior mirrors
- Hill Start Assist
- Braking system: Regenerative
- Decorative trim strips, Toba Grey
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning system with automatic emergency braking and pedestrian detection
- Transmission: 8-speed automatic
- Interior features
- Child safety lock in the rear doors, manual
- Dual-zone automatic climate control
- Front headrests, height adjustable
- Leather steering wheel including remote control
- Steering wheel: flattened, with paddle shifters
- Center armrest, sliding, front, including storage compartment and cup holder
- Onboard charger
- Park & Go Premium
- Upholstery: Leather
- Radio accessories: Digital radio reception DAB+
- Wheels: Light alloy 7.5 J x 18 with 5 spokes
- Keyless locking and starting system "Keyless Open & Start"
- Seat belts
- Seats: 5 seats
- Seats: Heated seats, multi-stage, driver and front passenger
- Start/Stop System
- Phone: Wireless Charging
- Underride protection look, front and rear, in silver
- Lashing eyes in the luggage compartment (4)
- Immobiliser
- Tinted heat-insulating glazing

- Paint finish: Metallic



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
2	Seat - front	Seat cover - left side - Porous / cracked - Smart repair
3	Interior	Interior (Hundegeruch) - Odour - Ozone treatment
4	Interior	Interior (Hundehaare) - Soiled - Conditioning
5	Boot lid / rear door	Rear spoiler - Dent / paintcoat damage - Smart repair
6	2nd wheel set	2 alloy rims - Scratched - Loss in value
7	Engine	Engine (Wackelt, nicht fahrbereit) - Noise - Perform diagnosis
8	Rear bumper	Rear bumper (Ecke) - Scratch(es) - Paint
9	Interior	Cargo area floor (Beschädigt) - Deformed - Replace
10	Front bumper	Front bumper - Scratch(es) - Paint
11	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
12	Door - rear left side	Door - Scratch(es) - Paint
13	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
14	Door - front left side	Door - Scratch(es) - Paint
15	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace
16	Roof	Roof - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
2	Wheel / tyres	Wheel rims - complete set - Scratched - No deduction
3	Interior	Interior - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 29 Mar 2023	8.906,97 €
2	Side right, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Mudguard - right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.





Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.




Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 1: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Seat - front: Seat cover - left side - Porous / cracked - Smart repair




Damage 2: Seat - front: Seat cover - left side - Porous / cracked - Smart repair



Damage 4: Interior: Interior (Hundehaare) - Soiled - Conditioning



Damage 5: Boot lid / rear door: Rear spoiler - Dent / paintcoat damage - Smart repair



Damage 5: Boot lid / rear door: Rear spoiler - Dent / paintcoat damage - Smart repair



Damage 6: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 6: 2nd wheel set: 2 alloy rims - Scratched - Loss in value



Damage 6: 2nd wheel set: 2 alloy rims - Scratched - Loss in value




Damage 6: 2nd wheel set: 2 alloy rims - Scratched - Loss in value




Damage 8: Rear bumper: Rear bumper (Ecke) - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper (Ecke) - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper (Ecke) - Scratch(es) - Paint



Damage 9: Interior: Cargo area floor (Beschädigt) - Deformed - Replace



Damage 9: Interior: Cargo area floor (Beschädigt) - Deformed - Replace



Damage 9: Interior: Cargo area floor (Beschädigt) - Deformed - Replace




Damage 10: Front bumper: Front bumper - Scratch(es) - Paint



Damage 10: Front bumper: Front bumper - Scratch(es) - Paint




Damage 11: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 11: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint




Damage 12: Door - rear left side: Door - Scratch(es) - Paint



Damage 12: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint



Damage 14: Door - front left side: Door - Scratch(es) - Paint




Damage 15: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace




Damage 15: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 16: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 16: Roof: Roof - Dent / paintcoat damage - Repair and paint



Damage 16: Roof: Roof - Dent / paintcoat damage - Repair and paint




Wear and tear 1: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper (unpainted) - Scratch(es) - No deduction



Wear and tear 4: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Wear and tear 4: Side panel - rear left side: Side panel - Scratch(es) - Cover / polish



Repainting 1: Mudguard - right side, Door - front right side



Repainting 1: Mudguard - right side, Door - front right side



Repainting 1: Mudguard - right side, Door - front right side



Repainting 1: Mudguard - right side, Door - front right side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VZ4DGZ2MS037784

Hersteller / Modell: OPEL OPEL Grandland X Plug-in-Hybrid 1.6 DI Start/Stop Aut
Business Elegance

Datum	KM-Stand	Beschreibung
04.05.2026	148.868	Bremsinspektion vo + hi; AU; Bremsklötze hinten; Bremsklötze vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
08.01.2026	132.905	Keilrippenriemen; Spannrolle ern; Systemtest/Eigendiagnose
12.06.2025	118.470	Batterie ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges; Zündkerzen ern
11.09.2024	79.261	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
17.05.2024	67.691	AU
25.10.2023	53.286	Reparatur Sonstiges; Systemtest/Eigendiagnose
18.09.2023	50.655	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges