



Expertise

Protocol number: 46442996
Order No. / Reference: 26566824
Inspection date: 10 Jul 2026

Manufacturer: Seat	Model: Cupra Born 170kW/77kWh
VIN: VSSZZK10RP029475	



Vehicle details	
Manufacturer / Type / Model / Equipment	
Seat Cupra Born 170kW/77kWh	
Vehicle Identification number	VSSZZK10RP029475
Mileage (Read)	10,793 km
First registration	20 Jun 2024
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Power / Engine displacement	70 kw / 0 ccm
Fuel type / Cylinder	Electric / 0
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Saloon car
Colour / colour code	Lava Blau (W5Q)
Doors / Seats	5 / 4
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy



Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	Next maintenance in	-78 Tag(e)
Last service on / at	05/2026 at 10,440 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB618148
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	7593 / ASN 00053		
Emission standard	2017/1151;WLTP;reine Elektrofz	fine dust sticker	
Permitted total weight	2,320 kg	Empty weight	
Dimensions	4322 x 1809 x 1540		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	All-season tyres on Light alloy	Continental	5mm / 5mm
2)	215/50 R19 93T	All-season tyres on Light alloy	Continental	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger (center airbag - side airbags for driver and front passenger)
- Ambient lighting in the front door trim (including footwell lighting)
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- C-pillar with CUPRA design element
- CUPRA Drive Profile (driving profiles can be individually selected - Range, Comfort, Performance, Individual, CUPRA)
- CUPRA side skirts in Liquid Grey
- Decorative elements (decorative element on instrument panel Black, decorative stitching in Copper - decorative inlay in front doors, Dinamica Granite Grey, made from recycled materials - decorative elements in Copper)
- Luggage compartment lighting
- Speed limiter
- rear window wiper
- Rear bumper and diffuser in body color (with Liquid Grey accents)
- Interior mirror automatically dimming
- ISOFIX child seat restraint system, in the 2nd row left and right as well as on the front passenger seat (i-Size compatible - incl. top tether anchor points at the rear)
- Headrests, 2 front
- Headrests, 3 rear
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather with CUPRA Mode Selector (heated - CUPRA e-Boost Activator and paddles for recuperation setting)
- Front center armrest (in Dinamica Granite Grey, front, made from recycled materials)
- Center console with integrated storage compartment and cup holder (including roller shutter, in black)
- Emergency call service (no registration required - service is activated upon delivery)
- Rain sensor
- Tire pressure monitoring system
- Windscreen wiper interval control
- Seat belts - front and rear (warning buzzer and warning light for unfastened seat belts)
- Seats: 2 rear seats, rear seat backrest asymmetrically split and foldable, with center armrest
- Seats: CUPRA front sport bucket seats (made of SEAQUAL Yarn fabric, Black)
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Front Assist area monitoring system with City Emergency Braking function
- Airbag: Passenger airbag deactivation
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Exterior mirror housing in Liquid Grey
- third brake light
- CCS charging socket
- CUPRA e-Sound (AVAS Acoustic Vehicle Alert System, acoustic vehicle warning system) from 0-50 km/h
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC) (Anti-lock Braking System (ABS) - Traction Control System (ASR))
- Electric windows front and rear, with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- Rear spoiler in car color
- Manufacturer's warranty: 5 years or up to 150,000 km
- High-voltage battery warranty 8 years or maximum 160,000 km, with 70% Abattery power
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control (separate for driver and front passenger, with stationary air conditioning)
- Mode 3 Type 2 charging cable, 16 A
- Lights: Full headlights (full LED headlights with light sensor and automatic headlight control, cornering light function and bad weather light - full LED taillights with Infinite Light; dynamic LED light strip at the rear - turn signals with LED technology integrated into exterior mirrors including welcome light projection under the exterior mirrors - Ceremony Light)
- Fatigue detection
- Progressive steering
- Radio: Radio and multimedia systems (2 USB-C charging ports for the 2nd row of seats - 7 speakers - Virtual Cockpit-5, 3" fully digital instrument cluster - antenna for FM reception - Bluetooth interface with integrated hands-free system and audio streaming - Android Auto, Apple CarPlay incl. Full Link Wireless - 2 USB-C ports in the front - DAB+ - infotainment system with 12" color touchscreen - voice control - CUPRA CONNECT)
- Seats: Driver's seat with height adjustment
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color (with air intakes in Liquid Grey and trim in Copper)
- Electronic immobilizer
- thermal insulation glazing



Extra equipment

- AR Head-up Display (Augmented Reality Head-up Display projects driving data into the driver's field of vision)
- Heat pump (heat pump for efficient air conditioning and range optimization)
- Paint finish: Exclusive
- Privacy Glass: Side windows from the 2nd row of seats and rear window are dark tinted.
- Wheels: All-season tires TYPHOON 7.5J x 19" Black/Silver, diamond-cut (tires 215/50 R19 with self-sealing function)
- Package: Pilot XL Plus Pack (Adaptive Cruise Control (ACC) with predictive speed control - CUPRA CONNECT PLUS - prepared for activation of the Online Infotainment service package - High Beam Assist - Navigation system with 12" color touchscreen - Rear Traffic Alert (RTA) - Intelligent Park Assist (IPA) - Lane Keeping Assist Plus including Travel Assist, Emergency Assist and Traffic Jam Assist - Side Assist including Blind Spot Assist - Top View Camera - Trained Park Assist (TPA) - Traffic Sign Recognition)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
2	Misc.	Inspection / maintenance - Expired - Replace
3	Mudguard - left side	Mudguard - left side (Kante) - dent(s) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Damage 1: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value




Damage 1: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 2: Misc.: Inspection / maintenance - Expired - Replace



Damage 3: Mudguard - left side: Mudguard - left side (Kante) - dent(s) - Paint



Damage 3: Mudguard - left side: Mudguard - left side (Kante) - dent(s) - Paint