



Expertise

Protocol number: 46632691
Order No. / Reference: 26621611
Inspection date: 15 Jul 2026

Manufacturer: Mercedes-Benz

Model: GLC-Coupe 300 e 4Matic 9G-TRONIC Exclusive

VIN: W1N2533531G015324



Vehicle details

Manufacturer / Type / Model / Equipment

Mercedes-Benz GLC-Coupe 300 e 4Matic 9G-TRONIC Exclusive

Vehicle Identification number W1N2533531G015324
Mileage (Read) 140,887 km
First registration 16 Nov 2021
Number of holders 1
Next periodical technical inspection 12/2026
(Report on hand)

Fuel type Hybr.B/E ext.aufl
Engine displacement / Cylinder 1,991 ccm / 4
Power 155 kW
Gearbox / Number of gears Automatic / 9
Type of drive All-wheel drive
Type of vehicle SUV

Colour / colour code Designo selenitgrau magno
Doors / Seats 5 / 5
Upholstery type Artificial leather
Colour of upholstery Black



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	125 Tag(e)
Last service on / at	11/2025 at 121,534 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GF733352
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2222 / AKT 00069		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,610 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 107H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/60 R18 103H	Winter tyres on Light alloy	Bridgestone	5 mm
	235/60 R18 107H	Winter tyres on Light alloy	Pirelli	5 mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101V	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	235/55 R19 101V	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Acoustic environmental protection
- Anti-lock braking system (ABS)
- Automatic passenger airbag deactivation
- On-board computer
- Brake system with larger brake discs on the front axle
- Third brake light in LED technology
- EASY-Pack tailgate with electric operation for opening and closing
- Driving light assistant
- electric parking brake
- Transmission: 9G-TRONIC
- Black fabric headliner
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control with 2 climate zones
- Communication module (LTE) for the use of Mercedes me connect services
- Charging system: AC on-board charger 7.4 kW
- LED High Performance Headlights
- Steering wheel: Multifunction sports steering wheel in 3-spoke design in black leather
- Steering column mechanically adjustable in height and length
- Otto particulate filter
- Package: Chrome
- Radio accessories: Digital radio
- Radio accessories: Touchpad
- Remote Services Plus
- Windscreen wipers with rain sensor
- Seats: Rear seat backrests foldable
- Seats: Front seats electrically adjustable
- Pre-installation for roof rack systems
- Immobiliser
- Decorative elements: Linden wood, line structure, glossy brown
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- 4MATIC all-wheel drive
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Tachometer
- DYNAMIC SELECT
- EASY-Pack cargo cover (removable)
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Velour floor mats in interior color
- Rear window heated
- Instrument panel and door sills in ARTICO man-made leather
- Instrument cluster with 2 tubular round instruments, 13.97 cm (5.5") multifunction display
- Headrests 5-way
- Charging cable for household socket, 5m, smooth (This charging cable, also called Mode 2 cable, allows you to charge the vehicle battery at the household socket with up to 2.3 kW (230 V, 1-phase, 10 A) and fits sockets of type E/F CEE 7/7.)
- Mercedes-Benz emergency call system
- Navigation accessories: Extended MBUX functions
- Package: Storage
- Package: Interior light
- Radio accessories: Remote Online
- Tire pressure monitoring system (TPMS)
- Rear view camera
- Power steering
- Seats: i-Size child restraint system on the outer rear seats
- Cruise control
- High-visibility vest for drivers
- Central locking



Extra equipment

- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Paint finish: designo selenite grey magno
- Discount code for the removal of the wireless charging system
- Package: Advanced Assistance (Mirror Package: Electrically folding exterior mirrors, lowering right exterior mirror, automatic dimming function; Lane Package: Active Lane Keeping Assist, Blind Spot Assist, Active Distance Assist DISTRONIC)
- Package: Advanced Park (Parking package with reversing camera, active parking assistant with PARKTRONIC)
- Package: High-end infotainment (Media display with touch controls, smartphone integration: Apple CarPlay and Android Auto, connectivity package, navigation, traffic sign assistant: thanks to intelligent linking of camera and map data, it can recognize not only speed limits, no-overtaking zones and their cancellation, but also fully digital instrument display, wireless charging system for mobile devices in the storage compartment)
- Package: Night for standard exterior equipment (radiator grille with 2 louvers in high-gloss black with chrome inserts, 48.3 cm (19") 6-spoke alloy wheels, painted high-gloss black and polished with 235/55 R 19 tires on 8 J x 19 ET 38 rims, roof rails in black, front and rear underguards painted black, exterior mirror housings painted high-gloss black, beltline trim and window surrounds in high-gloss black, heat-insulating dark tinted glass from the B-pillar back)
- Running boards in aluminum look with rubber studs
- Head-up display
- KEYLESS-GO
- Charging cable for wallbox and public charging stations, 5m, smooth (This charging cable, also called Mode 3 cable, allows you to charge the vehicle battery at the wallbox or at public charging stations with up to 7.4 kW (Type 2, 3-phase, 20 A).)
- Package: Advanced Light (LED High Performance headlights and adaptive LED taillights, Adaptive Highbeam Assist)
- Package: Business (for plug-in hybrid vehicles) (Advanced Parking Package: Active Parking Assist PARKTRONIC with reversing camera; Advanced Infotainment Package: Media display with touch operation, smartphone integration - Apple CarPlay and Android Auto, connectivity package navigation, traffic sign assist; Comfort Package: Heated seats for driver and front passenger, seat comfort package - electric and manual adjustment options for the front seats; Public Charging Package)
- Package: High End Comfort (Seat heating for driver and front passenger, driver's seat electrically adjustable with memory function, front right seat electrically adjustable with memory function, multi-contour seat package: individually adjustable air chambers, massage effect in the lumbar region)
- Upholstery: ARTICO man-made leather
- Wheels: 48.3 cm (19") light alloy wheels, 4-way in multi-twin-spoke design (high-gloss black painted and polished with 235/55 R 19 on 8 J x 19 ET 38)
- Heat and sound insulating acoustic glass (The heat and sound insulating acoustic glass for the front side windows offers you greater noise comfort.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Scratched - Smart repair
2	Indicator - front	Mirror - right side - Scratched - Replace
3	2nd wheel set	1 tyre (Fremdkörper in Lauffläche) - Damaged - Replace
4	Wing mirror - right side	Cap (Mit Materialabtrag) - Scratched - Paint
5	2nd wheel set	1 alloy rim (Mit Materialabtrag) - Scratched - Loss in value
6	Headlight	Headlight - right side (Außerhalb des Leuchtbereichs) - Scratch(es) - Loss in value
7	Mudguard - right side	Mudguard - right side - Scratch(es) - Paint
8	Braking system	Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace
9	Door - front left side	Door - Scratch(es) - Paint
10	Bonnet	Bonnet - Stone chips - Paint
11	Rear bumper	Rear bumper - Deformed - Repair and paint
12	Side panel - rear left side	Side panel - Scratch(es) - Paint
13	Body	Body (Farbangleich) - Lacquer

Wear and tear

No.	Component group	Description
1	Door - rear right side	Door edge - Scratch(es) - No deduction
2	Door - front right side	Door edge - Scratch(es) - No deduction
3	Side panel - rear left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description

Equipment - charging cable (Ladekabel für Haushaltssteckdose)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Der angegebene Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.
- Ein Nachweis über die Zulässigkeit des montierten Radsatzes wurde nicht erbracht.
- Aufgrund der vorhandenen Mattlackierung ist eine partielle Instandsetzung nicht möglich, ohne sichtbare Abweichungen in Farbton, Struktur und Mattgrad zu riskieren. Zur Sicherstellung einer fachgerechten, optisch und herstellergerechten Reparatur ist daher eine Ganzlackierung des Fahrzeugs zwingend erforderlich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Wing mirror - right side: Mirror housing - Scratched - Smart repair



Damage 1: Wing mirror - right side: Mirror housing - Scratched - Smart repair



Damage 2: Indicator - front: Mirror - right side - Scratched - Replace



Damage 2: Indicator - front: Mirror - right side - Scratched - Replace



Damage 3: 2nd wheel set: 1 tyre (Fremdkörper in Lauffläche) - Damaged
- Replace



Damage 3: 2nd wheel set: 1 tyre (Fremdkörper in Lauffläche) - Damaged
- Replace



Damage 4: Wing mirror - right side: Cap (Mit Materialabtrag) - Scratched
- Paint



Damage 4: Wing mirror - right side: Cap (Mit Materialabtrag) - Scratched
- Paint



Damage 5: 2nd wheel set: 1 alloy rim (Mit Materialabtrag) - Scratched -
Loss in value



Damage 5: 2nd wheel set: 1 alloy rim (Mit Materialabtrag) - Scratched -
Loss in value



Damage 5: 2nd wheel set: 1 alloy rim (Mit Materialabtrag) - Scratched - Loss in value



Damage 6: Headlight: Headlight - right side (Außerhalb des Leuchtbereichs) - Scratch(es) - Loss in value



Damage 6: Headlight: Headlight - right side (Außerhalb des Leuchtbereichs) - Scratch(es) - Loss in value



Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 7: Mudguard - right side: Mudguard - right side - Scratch(es) - Paint



Damage 8: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 8: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace




Damage 8: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 8: Braking system: Brake discs and brake pads - front (Tragbild mangelhaft, Rost) - Corrosion - Replace



Damage 9: Door - front left side: Door - Scratch(es) - Paint




Damage 9: Door - front left side: Door - Scratch(es) - Paint




Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 10: Bonnet: Bonnet - Stone chips - Paint



Damage 11: Rear bumper: Rear bumper - Deformed - Repair and paint



Damage 11: Rear bumper: Rear bumper - Deformed - Repair and paint



Damage 12: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 12: Side panel - rear left side: Side panel - Scratch(es) - Paint



Wear and tear 1: Door - rear right side: Door edge - Scratch(es) - No deduction



Wear and tear 2: Door - front right side: Door edge - Scratch(es) - No deduction



Wear and tear 3: Side panel - rear left side: Sill - Scratch(es) - No deduction



Wear and tear 3: Side panel - rear left side: Sill - Scratch(es) - No deduction



Missing part 1: Equipment: charging cable (Ladekabel für Haushaltssteckdose) - Missing - Replace



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W1N2533531G015324

Hersteller / Modell: MERCEDES-BENZ MB GLC-Coupe 300 e 4Matic 9G-TRONIC
Exclusive

Datum	KM-Stand	Beschreibung
17.11.2025	121.534	Regelwartungsdienst
11.12.2024	97.841	AU; Regelwartungsdienst
31.08.2024	88.945	Kraftstoffpumpe ern; Systemtest/Eigendiagnose; Wartung Sonstiges
05.07.2024	87.041	Bremsklötze hinten
12.02.2024	73.083	Regelwartungsdienst
30.03.2023	46.839	Regelwartungsdienst
15.09.2022	23.222	Regelwartungsdienst