



Expertise

Protocol number: 46454173
Order No. / Reference: 26726995
Inspection date: 9 Jul 2026

Manufacturer: Opel

Model: Mokka 1.2 DI Turbo Business Elegance

VIN: VXXKUSHNEKPW010836



Vehicle details	
Manufacturer / Type / Model / Equipment	
Opel Mokka 1.2 DI Turbo Business Elegance	
Vehicle Identification number	VXXKUSHNEKPW010836
Mileage (Read)	87,043 km
First registration	23 Mar 2023
Number of holders	1
Next periodical technical inspection	04/2029
(Report not on hand)	
Power / Engine displacement	74 kw / 1,199 ccm
Fuel type / Cylinder	Petrol / 3
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Diamant Schwarz Metallic
Doors / Seats	5 / 4
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Light grey



Vehicle details			
Maintenance booklet / proof	digital proof / complete	Next maintenance in	0 km
Last service on / at	01/2026 at 63,222 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ370623
Previous damage / Accident	Detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	1889 / ADA 00021		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,700 kg	Empty weight	

Tyres				
Mounted tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 96H	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/60 R17 96H	Summer tyres on Light alloy	Continental	5mm / 5mm
Additional tyres				
#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 98H	Winter tyres on Light alloy	Dunlop	4mm / 4mm
2)	215/65 R16 98H	Winter tyres on Light alloy	Dunlop	6mm / 6mm
Replacement				
Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, both with remote control and foldable
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Exterior mirrors in black
- Exterior mirrors, electrically adjustable and heated, manually foldable
- Headliner, Grey
- Decorative strips, silver
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 6-speed manual
- rear window wiper
- Child safety lock in the rear doors, manual
- Front headrests and 3 rear headrests, height adjustable
- LED ambient lighting in the door storage compartments, front
- LED headlights
- Steering wheel: Leather steering wheel, flattened at the bottom
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Otto particulate filter
- Upholstery: Fabric/Premium leather look
- Radio: Multimedia Navigation
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black
- Side impact protection
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, front passenger seat and rear outer seats
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Tinted heat-insulating glazing
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Roof design line in chrome
- Roof spoiler, black
- Double boot floor
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- High Beam Assist
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Heated rear window
- Rear shelf
- automatic climate control
- Paint finish: Metallic
- LED indicators, front and rear
- LED taillights
- LED daytime running lights
- Steering column, height and tilt adjustable
- Reading lights, front
- Center armrest, front
- Fatigue detection
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Tire pressure warning
- Wheels: Tire repair kit
- "Mokka" lettering on the rear in chrome
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Immobiliser
- Central locking with remote control

Extra equipment

- Paint finish: Metallic special color
- Park & Go
- Opel Connect with telematics services
- Seats: Heated seats, driver and front passenger KA1



Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear right side	Door edge - Scratch(es) - Smart repair
2	Door - front right side	Door edge - Scratch(es) - Smart repair
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Rear bumper	Rear bumper - Scratch(es) - Smart repair
5	Misc.	Inspection / maintenance - Due - Perform
6	Bonnet	Bonnet - Dent / paintcoat damage - Repair and paint
7	Vehicle glazing	Rear window - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Roof, Front, Provided by user / customer, from 31 Dec 2025	1.553,05 €
2	Front, Provided by user / customer, from 7 Jan 2026	2.943,87 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.




Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.




Figure 45: Misc.




Figure 46: Misc.




Figure 47: Misc.



Figure 48: Misc.







Figure 49: Misc.



Damage 1: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - rear right side: Door edge - Scratch(es) - Smart repair




Damage 2: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 2: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 4: Rear bumper: Rear bumper - Scratch(es) - Smart repair




Damage 5: Misc.: Inspection / maintenance - Due - Perform



Damage 5: Misc.: Inspection / maintenance - Due - Perform



Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 6: Bonnet: Bonnet - Dent / paintcoat damage - Repair and paint



Damage 7: Vehicle glazing: Rear window - Scratch(es) - Replace




Damage 7: Vehicle glazing: Rear window - Scratch(es) - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction




Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction




Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction




Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wear and tear 2: Body: Body - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: VXXKUSHNEKPW010836

Hersteller / Modell: OPEL OPEL Mokka 1.2 DI Turbo Business Elegance

Datum	KM-Stand	Beschreibung
22.04.2026	76.496	AU
13.02.2026	5	Bremsinspektion vo + hi; Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Keilrippenriemen; Reparatur Sonstiges; Zahnriemen/Steuerkett ern
16.01.2026	63.222	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
11.03.2025	39.860	Zündkerzen ern
07.02.2025	37.052	Bremsflüssigkeit; Bremsflüssigkeit ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
06.03.2024	21.019	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges