



Expertise

Protocol number: 46917230
Order No. / Reference: 26685260
Inspection date: 3 Aug 2026

Manufacturer: Ford

Model: Mondeo Turnier 2.0 TDCi Start-Stopp Trend

VIN: WF0FXXWPCFNS70386



Vehicle details	
Manufacturer / Type / Model / Equipment	
Ford Mondeo Turnier 2.0 TDCi Start-Stopp Trend	
Vehicle Identification number	WF0FXXWPCFNS70386
Mileage (Read)	101,154 km
First registration	14 Apr 2022
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Frozen White
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite
Vehicle with smoke odor	no



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	9,000 km
Last service on / at	12/2025 at 89,248 km		
Key is / should be	3 / 3	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK785977
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BJB 00107		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,330 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tyres on Light alloy	Dunlop	6mm / 6mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Dunlop	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/60 R16 95H	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12-volt power outlet in the luggage compartment
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Central locking (including selective locking (one door/all doors), remote control and luggage compartment remote release, door lock only on driver's side)
- Daytime running light
- Diesel particulate filter (DPF)
- Driver information system - 5.8 cm monochrome display (on-board computer with fuel consumption and mileage information)
- Electro-mechanical speed-dependent power steering (EPAS - Electric Power Assisted Steering)
- Electronic Safety and Stability Program (ESP) (with traction control (ASR) and safety brake assist (EBA))
- Emergency brake light (pulsating illumination of the brake lights during hard braking)
- Fog lights (with static cornering lights)
- Front center console with padded armrests (storage compartment under the armrest - 2 cup holders)
- Headlight dipped beam with switch-off delay including "greeting function"
- headliner, light
- Immobiliser
- Intelligent Protection System (IPS): - Active headrests, front, height-adjustable - Front airbag for driver and front passenger - Knee airbag for driver - Head and shoulder airbags, front and rear - Side airbags for driver and front passenger - Seat belt tensioners and belt force limiters, front - 3-point seat belts on all seats, height-adjustable in the front)
- Lashing eyes in the luggage compartment floor
- luggage compartment cover
- Rear center armrest with ski pass-through function
- Rear headrests (3), height adjustable
- rear window wiper
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Start-stop system
- Steering wheel: Multifunction leather steering wheel
- Tires: 6.5 J x 16 steel rims with 215/60 R 16 tires (wheel trims)
- Transmission: 6-speed manual transmission
- Upholstery: Cloth
- 12-volt socket in the front interior
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Back window, heater
- Carpet floor mats in the front
- Deletion of heated windshield and windshield washer nozzles
- Electric child safety lock
- Electric front and rear windows (with anti-pinch protection and automatic opening and closing function)
- Electronic parking brake
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated (with integrated turn signals)
- Hill start assist
- Interior lighting with delay function (with reading lights, front and rear)
- Isofix mounting (including top tether anchor points on the outer seats of the 2nd row)
- Luggage compartment lighting
- MyKey key system (individually programmable second key) (setting options include: limiting the maximum speed and radio volume, speed warning, safety assistance systems cannot be deactivated, locking of ESP deactivation, extended warning system for unfastened seat belts)
- Paint finish: Solid
- Radio equipment: CD audio system (radio-CD player MP3-compatible, 8 speakers, USB port, diversity antenna and audio remote control - multifunction display with 10.7 cm screen diagonal)
- Roof rails, aluminum look
- Seats: Driver and front passenger seats, 4-way manually adjustable (with manually adjustable lumbar support)
- Seats: Rear seat backrest (foldable, 60:40 split with ski pass-through)
- Steering column, adjustable (adjustable in height and reach)
- Tachometer
- Tires: Spare wheel, emergency wheel (T 125/80 R16)
- Tires: Tire pressure monitoring system (TPMS)
- Warning system for unfastened seat belts in the front and second row of seats



Extra equipment

- 2 kg powder fire extinguisher
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated, including Visibility Package (with integrated turn signals and ambient lighting, electrically folding, with Blind Spot Assist including Cross Traffic Alert (when reversing out of parking spaces)). Visibility Package: - High Beam Assist - Windscreen wipers with rain sensor - Headlight Assist with day/night sensor - Interior mirror, automatically dimming)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- 3. Key
- Attachment points for safety partition grilles (attachment points 1st row of seats)
- Anti-theft alarm system including double locking (with interior monitoring) (also with independent power supply)
- Dräger: Standard labeling
- Dräger: transparent protective film for rear bumper
- Paint finish: Frost White
- Package: Business 3
- Safety partition for luggage compartment, 2nd row of seats

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Sill - right side	Trim - Scratch(es) - Loss in value
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Bonnet	Bonnet - Stone chips - Paint
5	Rear bumper	Rear bumper - Scratch(es) - Paint
6	Roof	Roof rail - left side (Orangenhaut.) - Unprofessionally repaired - Paint
7	Side panel - rear left side	Side panel (Orangenhaut) - Unprofessionally repaired - Paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 21 Aug 2023	8.760,19 €

Repainting

No.	Repainting
1	Roof rail - left side, Side panel - rear left side, Unprofessionally carried out, Invoice of repair done Non-existent



Paint coat thickness measurement

Roof rail - left side	235 µm	Side panel - rear left side	396 µm
-----------------------	--------	-----------------------------	--------

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.

- Das Fahrzeug befand sich zum Besichtigungszeitpunkt in nicht fachgerecht reparierten Zustand. Schadenausweitung möglich, Zusatzkosten können entstehen.

ALPHABET



Figure 1: Diagonal front (left)

ALPHABET



Figure 2: Diagonal front (right)

ALPHABET



Figure 3: Diagonal rear (left)

ALPHABET



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Sill - right side: Trim - Scratch(es) - Loss in value



Damage 2: Sill - right side: Trim - Scratch(es) - Loss in value



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 4: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 6: Roof: Roof rail - left side (Orangenhaut.) - Unprofessionally repaired - Paint




Damage 6: Roof: Roof rail - left side (Orangenhaut.) - Unprofessionally repaired - Paint



Damage 6: Roof: Roof rail - left side (Orangenhaut.) - Unprofessionally repaired - Paint



Damage 6: Roof: Roof rail - left side (Orangenhaut.) - Unprofessionally repaired - Paint



Damage 7: Side panel - rear left side: Side panel (Orangenhaut) - Unprofessionally repaired - Paint



Damage 7: Side panel - rear left side: Side panel (Orangenhaut) - Unprofessionally repaired - Paint



Damage 7: Side panel - rear left side: Side panel (Orangenhaut) - Unprofessionally repaired - Paint



Damage 7: Side panel - rear left side: Side panel (Orangenhaut) - Unprofessionally repaired - Paint



Damage 7: Side panel - rear left side: Side panel (Orangenhaut) - Unprofessionally repaired - Paint



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wear and tear 1: Trim / covers: Boot lid - interior trim - Scratch(es) - No deduction



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0FXXWPCFNS70386

Hersteller / Modell: FORD FORD Mondeo Turnier 2.0 EcoBlue Trend

Datum	KM-Stand	Beschreibung
08.12.2025	89.248	Bremse Sonstiges; Bremsklötze vorne; Bremsscheiben + Klötze v; Bremsscheiben vorne; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
14.05.2025	75.124	AU
13.09.2024	60.027	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
19.07.2023	30.647	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges