

2-FWF-888

2-FWF-888 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FWF-888	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTNADADBXM0J020868
Model	Corolla	Cylinder Capacity	1.798 ^{cm3}
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	16-09-2024
Color	Silver	Odometer	55.286 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	103	Number Headrests	5

Images



Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Left	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Front Right	4 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Right	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dislocated / Loose	Wielkuipbescherming	Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Midden gedeelte	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Previous Repair	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Rear	Small scratch(es)	Middenstuk	Acceptable	Yes