

smart #3





Vehicle information


Make:	smart	License:	
Gearbox:	Automatic	Body color:	
Model:	#3	VIN:	HESCA2C48RS266829
Fuel type:	Electric	Power:	
Version:	BRABUS	First registration	06/02/2026
Mileage:	11204 km	N° of doors:	5

Damage summary

Front	3
Left	1
Rear	2
Right	1

Commercial pictures





Options according to the inspector

Floor mats	OK	Panoramic roof	Yes	Type of GPS	GPS big screen color
Type of Tow bar	No Tow bar				

Damages

Alloy rim RR polished
Scratch(es)
Repair and paint (complete)
Right







Bonnet

Dent(s)

Repair and paint (complete)

Front





Bumper F

Scratch(es)

Spot repair

Front





Door RL

Scratch(es)

Spot repair

Left



Spoiler FR

Scratch(es)


Repair and paint (complete)

Front



Tailgate / Boot

Chemical polution
Polish
Rear



Tyre repair kit

Missing
Replace
Rear



Tyres

Front Left
Summer
245/40/20/100/V
Continental
5.0 mm
Front Right
Summer
245/40/20/100/V
Continental
5.0 mm
Rear Left
Summer
245/40/20/100/V
Continental
5.0 mm
Rear Right
Summer
245/40/20/100/V
Continental
5.0 mm

Checks

Car checked on car lift?	No	Certificate of Conformity	No
Cover trailer hitch	N/A	Fuel Level	75
Maintenance needed	No	Multi-media screen functioning?	Yes
Number head rests	3	Number of charging cables (rapid charge)	1
Number of doors	5	Number of keys total	1
Registration certificate original	Yes	Type of Emergency Tool	Repair kit missing
Type of Instructionbook	Digital Instructionbook	Type of Luggage cover	Luggage space cover present
Type of Maintenance book	Digital maintenance	Vehicle accident?	No

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.