



Expertise

Protocol number: 46709457
Order No. / Reference: 26725739
Inspection date: 24 Jul 2026

Manufacturer: Ford

Model: Tourneo Connect 2.0 EcoBlue TITANIUM

VIN: WF0DXXSKXNX001947



Vehicle details

Manufacturer / Type / Model / Equipment

Ford Tourneo Connect 2.0 EcoBlue TITANIUM

Vehicle Identification number	WF0DXXSKXNX001947
Mileage (Read)	69,179 km
First registration	19 Dec 2022
Number of holders	1
Next periodical technical inspection	01/2028
(Report on hand)	

Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	90 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van

Colour / colour code	Stardust Silver Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Dark grey



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	21,700 km
Last service on / at	01/2026 at 64,163 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GK826591
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	8566 / BVY 00034		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,220 kg	Empty weight	
Dimensions	4500 x 1855 x 1816		

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Light alloy	Hankook	5mm / 5mm
2)	205/60 R16 96H	Summer tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- | | |
|--|--|
| <ul style="list-style-type: none"> • Anti-lock braking system (ABS) with ESP, HLA and TCS • Exterior mirror caps, painted black • Tires: 6.5 J x 16 alloy wheels (4) with 205/60 R16 • Front overhead storage compartment • Diesel particulate filter (DPF) • Electric front windows • Transmission: 6-speed manual transmission • Glove compartment with lid, additionally illuminated • Rear swing door with heated rear window • Front interior lighting with delay function and two reading lamps • Isofix bracket • Front headrests, height adjustable • Steering wheel: Leather multifunction steering wheel, 4 spokes • Fatigue warning • Package: Driver Assistance Package 1 • Pollen and dust filter • Radio equipment: Audio system 2 • Tire Pressure Monitoring System (TPMS) • Headlight assistant with day/night sensor • Seats: Bench seat (in the 2nd row, 3 seats) • Start-stop system • Front bumper with chrome trim • Carpeted floor in the luggage compartment • Child safety lock on sliding doors • Door handles painted in car color • circulating air heating • USB port for the 2nd row of seats • Heat-insulating glazing, tinted (from the B-pillar) | <ul style="list-style-type: none"> • Electrically adjustable, heated, and additionally electrically folding exterior mirrors • third brake light • Roof rails, silver-colored • Tachometer • Ford Power Start function (keyless start) • Halogen headlights with daytime running lights • Tailgate handle, painted in body color • Rear interior light • Interior mirror automatically dimming • Intelligent Protection System (IPS) • Rear headrests, height adjustable • Leather gear knob • Steering column, adjustable in height and reach • Center console "Premium" • Fog light • Package: Seat Package 18 • Upholstery: Cloth • Tire repair kit, weight-saving • Windscreen wipers with rain sensor • Side windows fixed, 2nd row, right and left • Sun visor for driver and front passenger • Rear bumper, painted in body color • Carpet (1st and 2nd row) • Carpet floor mats for the front (2-piece set) • Doors: Sliding door, right and left • Front door interior trim with illuminated switches including door storage compartments for 1.5 L bottles • Electronic immobilizer • Central locking: Second remote control key (instead of conventional key) |
|--|--|

Extra equipment

- | | |
|---|---|
| <ul style="list-style-type: none"> • Heated windshield • Paint finish: Metallic | <ul style="list-style-type: none"> • Front air conditioning with automatic temperature control |
|---|---|

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Side panel - rear right side	Side panel - Glued / labelled - De-glue / neutralise
3	Trim / covers	Boot lid - interior trim - Broken / torn - Replace
4	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Smart repair
5	Front bumper	Front bumper - Scratched - Paint
6	Side panel - rear left side	Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint
7	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Repair and paint

Missing parts

Description

2nd wheel set - Wheel cover set - complete

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Side - left, Provided by user / customer, from 30 Mar 2026	4.706,29 €

Repainting

No. Repainting

1 Boot lid / rear door, Side panel - rear left side, Door - rear left side

Paint coat thickness measurement

Boot lid / rear door	197 µm	Side panel - rear left side	722 µm
Door - rear left side	197 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle



Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Side panel - rear right side: Side panel - Glued / labelled - De-glue / neutralise



Damage 2: Side panel - rear right side: Side panel - Glued / labelled - De-glue / neutralise



Damage 3: Trim / covers: Boot lid - interior trim - Broken / torn - Replace



Damage 3: Trim / covers: Boot lid - interior trim - Broken / torn - Replace



Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair



Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair




Damage 4: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Smart repair



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint




Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint



Damage 6: Side panel - rear left side: Side panel (Schleifspuren, wellig) - Unprofessionally repaired - Repair and paint




Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint




Damage 7: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Repair and paint



Missing part 1: 2nd wheel set: Wheel cover set - complete - Missing - Replace




Missing part 1: 2nd wheel set: Wheel cover set - complete - Missing - Replace



Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side




Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side



Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side



Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side



Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side



Repainting 1: Boot lid / rear door, Side panel - rear left side, Door - rear left side



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WF0DXXSKXNX001947

Hersteller / Modell: FORD FORD Tourneo Connect 2.0 EcoBlue TITANIUM

Datum	KM-Stand	Beschreibung
15.01.2026	64.163	AU; Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.04.2024	34.005	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges