

## Expertise

Protocol number: 46242168  
Order No. / Reference: 26509281  
Inspection date: 26 Jun 2026

Manufacturer: Opel

Model: Astra 1.6 D Start/Stop Sports Tourer Business

VIN: W0VBD8EF1K8057097



### Vehicle details

#### Manufacturer / Type / Model / Equipment

Opel Astra 1.6 D Start/Stop Sports Tourer Business

<b>Vehicle Identification number</b>	W0VBD8EF1K8057097
<b>Mileage (Read)</b>	75,255 km
<b>First registration</b>	25 Jul 2019
<b>Number of holders</b>	1
<b>Next periodical technical inspection</b>	08/2026
(Report on hand)	

<b>Power / Engine displacement</b>	81 kw / 1,598 ccm
------------------------------------	-------------------

<b>Fuel type / Cylinder</b>	Diesel / 4
-----------------------------	------------

<b>Gearbox / Number of gears</b>	Manual / 6
----------------------------------	------------

<b>Type of drive</b>	Front drive
----------------------	-------------

<b>Type of vehicle</b>	Station wagon
------------------------	---------------

<b>Colour / colour code</b>	Argonsilber Metallic
-----------------------------	----------------------

<b>Doors / Seats</b>	5 / 5
----------------------	-------

<b>Upholstery type</b>	Cloth
------------------------	-------

<b>Colour of upholstery</b>	Grey-Black
-----------------------------	------------



## Vehicle details

<b>Maintenance booklet / proof</b>	digital proof / complete	<b>Next maintenance in</b>	0 km
<b>Last service on / at</b>	06/2025 at 72,294 km		
<b>Key is / should be</b>	1 / 2	<b>FZG documents</b>	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		<b>Letter No.</b>	FK163886
<b>Previous damage / Accident</b>	None detectable	<b>Repainting</b>	None detectable
<b>Inspection conditions</b>	sufficient	<b>Lifting equipment / pit</b>	No
<b>Test drive</b>	Not performed	<b>Engine function test</b>	Performed
<b>Manufacturer key number/ type code number</b>	1844 / AFD 00740		
<b>Emission standard</b>	EURO6;WLTP;DG;PI/CI; M, N1 I	<b>fine dust sticker</b>	
<b>Permitted total weight</b>	1,930 kg	<b>Empty weight</b>	

## Tyres

### Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm

### Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm
2)	205/55 R16 91V	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm

### Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2024		

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**



## Equipment

### Standard equipment

- Storage compartments
- Airbag for driver and passenger side
- Airbag: Head airbags, 1st and 2nd row (outer seats)
- Anti-lock braking system (ABS)
- Hill Start Assist
- On-board computer
- black roof rails
- Diesel particulate filter (DPF)
- Electronic Stability Program Plus (ESP Plus)
- Pedestrian protection
- Transmission: 6-speed manual transmission
- rear window wiper
- Air conditioning
- Front headrests
- LED daytime running lights
- Steering wheel: Steering wheel remote control
- Parkpilot, rear parking aid
- PowerFlex Adapter
- Tire repair kit
- Wheels: Steel 6.5 J x 16 with tires 205/55 R16
- Power steering
- Luggage compartment safety net
- Start/Stop System
- 12V power outlet in the center console
- Tie-down points 4 in the luggage compartment
- Immobiliser
- Central locking with remote control and interior switches

- Adaptive brake light
- Airbag: Chest-pelvis side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Silver decorative strips
- Tachometer
- Electric windows, front and rear
- Speed controller with limiter
- Back window, heater
- Child safety lock in the rear doors, manual
- Rear headrests (3)
- Cargo area cover
- Steering wheel: Comfort steering wheel
- Steering column, height and reach adjustable
- Upholstery: Cloth
- Radio: R300 BT
- Tire pressure monitoring system
- Service interval indicator
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort seats, front
- 12V power outlet in the luggage compartment
- Traction Control (TC) Plus
- Pre-installation for child seat mounting system "ISOFIX"
- Heat-insulating glazing, green tinted, and windshield

### Extra equipment

- Business upgrade comfort (leather steering wheel with chrome trim - sliding center armrest, front - fog lights - front and rear parking sensors)
- Floor mats, velour, front and rear
- Paint finish: Metallic
- Quickheat rapid heating system (electric auxiliary heater)
- Business Upgrade Navigation Plus (Navi 4.0 IntelliLink with 7" touchscreen color display - front camera with traffic sign recognition, forward collision warning, distance indicator and lane keeping assist - visibility package with automatic headlights, tunnel detection, rain sensor, interior rearview mirror, automatically dimming - lighting package)

## Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.



## Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Front bumper - Scratch(es) - Smart repair
3	Door - front left side	Door edge - Scratch(es) - Smart repair
4	Door - rear left side	Door - Scratch(es) - Smart repair
5	Misc.	Inspection / maintenance - Due - Perform
6	Rear bumper	Rear bumper - Deformed - Replace

## Missing parts

### Description

Interior - Luggage net

Equipment - Vehicle key

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features  
(*Delivery by third-party service providers*)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.  
(*Functional testing of driver assistance systems is not included in the scope of services!*)
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



## Comments

Die Unterbodenbesichtigung war nur ebenerdig und eingeschränkt möglich. Mehrkosten möglich

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 3:** Door - front left side: Door edge - Scratch(es) - Smart repair



**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 5:** Misc.: Inspection / maintenance - Due - Perform



**Damage 6:** Rear bumper: Rear bumper - Deformed - Replace



**Damage 6:** Rear bumper: Rear bumper - Deformed - Replace



**Damage 6:** Rear bumper: Rear bumper - Deformed - Replace



**Damage 6:** Rear bumper: Rear bumper - Deformed - Replace



**Missing part 2:** Equipment: Vehicle key - Missing - Replace



# Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: W0VBD8EF1K8057097

Hersteller / Modell: OPEL OPEL Astra 1.6 D Start/Stop Sports Tourer Business

Datum	KM-Stand	Beschreibung
26.06.2025	72.294	Bremse Sonstiges; Bremsklötze hinten; Bremsklötze vorne; Keilrippenriemen; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
26.08.2024	65.482	HU + AU
16.04.2024	63.190	Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Luftfiltereinsatz ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
16.12.2022	49.956	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Systemtest/ Eigendiagnose; Wartung Sonstiges
27.08.2022	48.165	HU + AU
23.08.2021	18.212	Kleine Inspektion; Bremsflüssigkeit; Bremsflüssigkeit ern; Kraftstofffilter ern; Motoröl b. Wartung; Ölfilter ern; Wartung Sonstiges
02.07.2020	9.588	Kleine Inspektion; Motoröl b. Wartung