



Expertise

Protocol number: 47211654
Order No. / Reference: 26841787
Inspection date: 19 Aug 2026

Manufacturer: Kia

Model: Ceed SW 1.6 GDI DCT OPF Plug-in-Hybrid Spirit

VIN: U5YH581AGPL038981



Vehicle details

Manufacturer / Type / Model / Equipment

Kia Ceed SW 1.6 GDI DCT OPF Plug-in-Hybrid Spirit

Vehicle Identification number	U5YH581AGPL038981
Mileage (Read)	73,572 km
First registration	26 Jun 2023
Number of holders	1
Next periodical technical inspection	07/2028
(Report on hand)	

Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,580 ccm / 4
Power	77 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Zillinaschwarz Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black



Vehicle details			
Maintenance booklet / proof	Available / complete	Next maintenance in	3,557 km
Last service on / at	05/2026 at 71,015 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY684994
Previous damage / Accident	Detectable	Repainting	Detectable
Inspection conditions	sufficient	Lifting equipment / pit	yes
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	2234 / ABD 00014		
Emission standard	EURO6	fine dust sticker	
Permitted total weight	2,030 kg	Empty weight	

Tyres			
Mounted tyres			
#	Tyre size	Type of tyre	Tread depth
1)	205/55 R16 91H	All-season tyres on Light alloy	3mm / 3mm
2)	205/55 R16 91H	All-season tyres on Light alloy	5mm / 5mm

Replacement			
Typ	Tyre size	Type of tyre	Tread depth
	Tirefit	Expiration date 03/2028	

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.



Equipment

Standard equipment

- ABS (Anti-lock Braking System) with electronic brake force distribution
- Airbag: 2 curtain airbags
- Active brake light (Emergency Stop Signal, ESS)
- Alarm system
- Highway Driving Assist (HDA)
- Electrically folding exterior mirrors
- Exterior mirrors with integrated turn signals
- On-board computer
- Overhead console with glasses compartment
- Roof rails
- Tachometer
- Third brake light (LED) in the rear spoiler
- twilight sensor
- Inserts in glossy black
- Energy regeneration system
- Electric windows front and rear
- Front collision warning
- Luggage net eyelets
- Luggage compartment lighting
- Transmission: 6-speed direct-shift gearbox (DCT)
- Front and rear seatbelt warning system
- rear window wiper
- Rear Seat Alert (RSA)
- Automatic climate control, 2 zones, with anti-fog sensor
- Charging cable, Schuko plug to Type 2 plug
- LED fog lights
- LED daytime running lights at the rear
- Heated steering wheel
- Steering wheel: Multifunction steering wheel
- front center armrest
- Navigation: Kia map navigation (10.25 inch)
- Otto particulate filter
- Rear parking sensors (PDW-R)
- Cross-traffic alert system for detecting vehicles in the blind spot
- Radio accessories: 2 rear speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: USB interface
- Tire pressure monitoring system (TPMS)
- Wheels: 16-inch alloy wheels with 205/55 R16 tires
- Power steering
- Seats: Passenger seat height adjustable
- Seats: Lumbar support
- Seats: Heated front seats
- Smartphone interface Android Auto and Apple CarPlay with voice control
- Supervision instrument display with a 10.7 cm (4.2 inch) screen diagonal
- Virtual Engine Sound System (VESS) for pedestrian protection
- Airbag: 2 front airbags
- Airbag: 2 side airbags
- Active lane keeping assist with corrective steering intervention (Lane Keep Assist, LKA)
- Safe Exit Warner (SEW)
- Heated exterior mirrors
- Electrically adjustable exterior mirrors
- Hill Start Assist Control (HAC)
- Brake Assist (BAS)
- Front overhead console with reading lights and central lighting
- Three-point seat belts at all seats
- Drive Mode Select
- EcoDynamics (start-stop system ISG)
- Electronic Stability Control (ESC) with Traction Control System (TCS)
- High beam assist
- floor mat set
- luggage compartment cover
- Cruise control, navigation-based
- Front cup holder
- Back window, heater
- Auto-dimming interior rearview mirror
- ISOFIX mounts
- Headrests on all seats are height-adjustable.
- LED headlights
- LED taillights
- LED daytime running lights at the front
- Steering wheel: Leather steering wheel
- Armrest - centre, rear
- Fatigue warning
- Online services UVO CONNECT with Kia Live
- Electronic parking brake
- Upholstery: Cloth
- Radio: Kia radio with 8-inch touchscreen
- Radio accessories: 2 front speakers
- Radio accessories: 2 tweeters
- Radio accessories: DAB radio
- Rain sensor
- Tire repair kit
- Rear view camera
- Front seat belts are height-adjustable
- Seats: Driver's seat height adjustable
- Seats: Rear seat backrest split 60:40, foldable
- Smart Key and Start Button
- Sun visors with illuminated makeup mirrors
- 12V power outlet
- Blind Spot Assist with Brake Assist (BCA)
- Traffic sign recognition for speed limits
- Immobiliser
- Central locking with remote control



Extra equipment

- All-weather tires including installation
- Charging cable Type 2 to Type 2 plug (20 A)
- Package: P4 - Seat Comfort Package (seat covers in fabric-leather combination (with high-quality imitation leather): Black - driver's seat electrically adjustable with memory function - rear seat heating (outer seats) - rear seat bench foldable in a 40:20:40 ratio)
- Paint finish: Metallic paint
- Package: P2 - Technology (Intelligent parking system (Parking Assist-Perpendicular Reverse, PA-PDR) with parking assistant for parallel and perpendicular parking as well as parallel exiting - Inductive charging station (for smartphones) in the center console with charging indicator - Electric tailgate, sensor-controlled)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Bonnet	Bonnet (Vogelkotverätzung eingebrannt) - Paint defect - Cover / polish
2	Vehicle glazing	Rear window - Glued / labelled - De-glue / neutralise
3	Vehicle glazing	Windscreen - Stone chips - Smart repair
4	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - Replace
5	Front bumper	Front bumper - Scratched - Paint
6	Sill - left side	Sill - Dent / paintcoat damage - Repair and paint
7	Door - rear left side	Door - Scratch(es) - Paint
8	Door - rear right side	Door - Scratch(es) - Paint
9	Door - front left side	Door - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Body	Body (Waschanlagenkratzer) - Scratch(es) - No deduction
2	Side panel - rear right side	Sill - Scratch(es) - No deduction
3	Side panel - rear right side	Side panel - Scratch(es) - No deduction
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents



Figure 20: Documents



Figure 21: Documents



Figure 22: Navigation



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Damage 1: Bonnet: Bonnet (Vogelkotverätzung eingebrannt) - Paint defect - Cover / polish



Damage 1: Bonnet: Bonnet (Vogelkotverätzung eingebrannt) - Paint defect - Cover / polish



Damage 2: Vehicle glazing: Rear window - Glued / labelled - De-glue / neutralise



Damage 2: Vehicle glazing: Rear window - Glued / labelled - De-glue / neutralise



Damage 3: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 3: Vehicle glazing: Windscreen - Stone chips - Smart repair



Damage 4: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 4: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace




Damage 4: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 4: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 5: Front bumper: Front bumper - Scratched - Paint



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 6: Sill - left side: Sill - Dent / paintcoat damage - Repair and paint



Damage 7: Door - rear left side: Door - Scratch(es) - Paint




Damage 7: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Door - rear right side: Door - Scratch(es) - Paint



Damage 8: Door - rear right side: Door - Scratch(es) - Paint



Damage 8: Door - rear right side: Door - Scratch(es) - Paint




Damage 8: Door - rear right side: Door - Scratch(es) - Paint




Damage 8: Door - rear right side: Door - Scratch(es) - Paint



Damage 9: Door - front left side: Door - Scratch(es) - Paint




Damage 9: Door - front left side: Door - Scratch(es) - Paint



Damage 9: Door - front left side: Door - Scratch(es) - Paint



Wear and tear 3: Side panel - rear right side: Side panel - Scratch(es) -
No deduction



Wear and tear 3: Side panel - rear right side: Side panel - Scratch(es) -
No deduction



Wear and tear 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Wear and tear 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - No deduction



Repainting 1: Side panel - rear left side

Wartungshistorie

(gemäß Auftraggeber Informationen)



Fahrgestellnummer: U5YH581AGPL038981

Hersteller / Modell: HYUNDAI HYUNDAI Ceed SW 1.6 GDI DCT OPF Plug-in-Hybrid Spirit

Datum	KM-Stand	Beschreibung
09.01.2025	43.643	Bremsflüssigkeit; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
27.05.2024	29.818	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
09.04.2024	25.028	Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges